GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No. F6/MS/DFS/GH/2013/NO2/64/

Dated: 2 3/07/13

FIRE SAFETY CERTIFICATE

Certified that the New Bangali Lodge Guest House located at 1443, Ranjit Gali, Sangtrashan, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + 02 guest rooms), 1st floor (03 guest rooms) and 2nd floor (02 guest rooms) total 07 guest rooms, owned / occupied by M/s New Bangali Lodge Guest House have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 11-07-2013 in the presence of Sh. Chiranjit Basu (owner) and that the building / premises, is fit for occupancy class Group A Sub Division A-I Lodging or Rooming Houses with effect from $\frac{2}{\sqrt{2}}$ -2013 for a period of 03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service 1 Real 26/13

Copy to :-

- The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi – 110049 wrt. No.29183-86/Addl.C.P./Lic.(H) New Delhi dated 13-6-2013
- 2. M/s New Bangali Lodge Guest House, 1443, Ranjit Gali, Sangtrashan, Pahar Gani, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

New Bangali Lodge Guest House, 1443, Ranjit Gali, Sangtrashan, Pahar Ganj, New Delhi-110055

INSPECTION REPORT

1. Name & address of the building : New Bangali Lodge Guest House, 1443, Ranjit Gali,

Sangtrashan, Pahar Ganj, New Delhi-110055

2. Type of Occupancy

: Lodging House

3. Type of Case

New Case

4. Details of previous NOC

Letter No. N/A Dated

5. Fire Safety directives Letter No.

N/A

6. Date of inspection

11-07-2013

7. Name of the Inspecting Officer

Sh. D.S. Yadav (D.O.)

8. Name and designation of Officer

from the building side

Sh. Chiranjit Basu (owner)

9. Year of Construction

: 2008

10 Applicant's letter No.

: No.29183-86/Addl.C.P./Lic.(H) New Delhi dated 13-6-2013

No	Minimum standards on fire prevention	BBL	Provided at site	Remarks MR/NMR	
	and fire safety U/R 33	Requirements	(PSS Area)	(P.S.S Area)	
1.	Access of building				
	Road width	N/A	2 mtrs. Approx. (Notified Gali)	MR	
	Gate width		Directly Accessible from Road.	MR	
	Width of internal road	N/A	N/A	N/A	
2.	Number, width, Type & Arrangements of exits				
	a. Number of staircases				
	Upper floors	01	01	MR	
	 Basements 	N/A	N/A	N/A	
	b. Width of staircases			× ,	
	 Upper floors 	80 cms	125cms to 150cms.	MR	
	 Basements 	N/A	N/A	N/A	
	c. Protection of exits				
	Fire check door	N/A	N/A	N/A	
	 Pressurization 	N/A	N/A	N/A	
	d. No of continuous staircase to terrace	01	01	MR	
	e. Width Of Corridor	N/A	N/A	N/A	
	f. Door Size	N/A	N/A	N/A	
3.	Compartmentation				
	Fire check door	N/A	N/A	N/A	
	 Sealing of electrical shafts 	N/A	N/A	N/A	
	 Fire Rating of shaft door 	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	• Fire Dampers	N/A	N/A	N/A	
4.	Smoke managements System			8	
	Basements	30 a/c per hour	N/A	N/A	

New Bangali Lodge Guest House, 1443, Ranjit Gali, Sangtrashan, Pahar Ganj, New Delhi-110055

IN	ew Bangali Lodge Guest House, 1443,	Ranjit Gan, Ban	Natural ventilation	MR		
	 Upper floors 	12 a/c per hour	Natural ventuation	IVIIC		
1	Fire Extinguishers		0.0	MR		
	 Total numbers 	08	08	MR		
	 Types 		Water Co2 &	IVIK		
			A.B.C. type.	MR		
	IS marking	ISI marked	Provided	IVIK		
	First – Aid Hose Reels			27/4		
	Total numbers on each floor	N/A	N/A	N/A		
	 Length of hose reel hose 	N/A	N/A	N/A		
	Nozzle diameter	N/A	N/A	N/A		
7.	Automatic fire detection and alarming sy	vstem		*		
	Type of detectors	N/A	N/A	N/A		
	 Location of Main Panel 	N/A	N/A	N/A		
	I CD amagtan Danal	N/A	N/A	N/A		
	C	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	MOEFA	Required	Provided	MR		
	Public Address System	Required	Tiorided			
0.	Automatic Sprinkler System	N/A	N/A	N/A		
	Basements	N/A N/A	N/A	N/A		
	Upper Floor	N/A N/A	N/A	N/A		
	 Sprinkler above false ceiling 	IN/A	1 1 / / 1	11/17		
11.	Internal Hydrants	77/1	DI/A	N/A		
	 Size of riser/down- comer 	N/A	N/A	N/A		
	 Number of hydrants per floor 	N/A	N/A	N/A N/A		
	Hose Box	N/A	N/A	IN/A		
12.	Yard Hydrants			27/4		
	 Total number of hydrants 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements	-				
15.	Ground Level					
	Discharge of main pump	N/A	N/A	N/A		
	> Head of main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	> Jockey pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	auto Staring/Manual stopping	N/A	N/A	N/A		
	➤ Pump House Access	N/A	N/A	N/A		
	Terrace level	11/12				
	Discharge of pump	N/A	N/A	N/A		
	Head of the pump	N/A	N/A	N/A		
	> Power supply	N/A	N/A	N/A		
	> Auto starting of pump	N/A	N/A	N/A		
11	10/11					
14.	Captive water Storage for fire fighting	N/A	N/A	N/A		
	• Under ground tank capacity		N/A	N/A		
	> Draw of connection	N/A	N/A N/A	N/A		
	> Fire service inlet	N/A		N/A N/A		
	> Access to tank	N/A	N/A			
	Overhead Tank capacity	N/A	N/A	N/A		
15	Exit Signage	Required	Provided	MR		
16.	Provision of Lifts			71/4		
	Pressurization of Lift Shaft	N/A	N/A	N/A		
1	Pressurization of lift lobby	N/A	N/A	N/A		

New Bangali Lodge Guest House, 1443, Ranjit Gali, Sangtrashan, Pahar Ganj, New Delhi-110055 > Communication in lift Car N/A N/A N/A N/A N/A > Fireman's Grounding Switch N/A ➤ Lift Signage N/A N/A N/A Required D.G. Set MR 17. Standby power supply 18. Refuge Area Total area N/A N/A N/A Location N/A N/A N/A Fire control room 19. N/A N/A N/A Detector system panel Flow Switch Panel N/A N/A N/A PA System Panel N/A N/A N/A Batter backup N/A N/A N/A **Building Floor Plans** N/A N/A N/A Special Fire Protection Systems for N/A N/A 20. N/A Protection of special Risks, if any;

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation Signature of the Inspecting Officer

Name Dhosm viesinsh yadar-Designation Divisional afficel (central)