## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No: F6./DFS/MS/GH/2013/ SZ/ 705

Dated: 13 | 08 | 13

## FIRE SAFETY CERTIFICATE

Certified that the Chandrika Inn Guest House located at 4/9, 1<sup>st</sup> floor, Asaf Ali Road (Near Bank of India), New Delhi-110002 comprised of basement (storage others property), ground floor (restaurant 46 seats), 1<sup>st</sup> floor (05 guest rooms + reception), 2<sup>nd</sup> floor (office of other party), total 05 guest rooms, owned / occupied by M/s Chandrika Inn Guest House have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 31-07-2013 in the presence of Smt. Sunita Jain (owner) and that the building / premises, is fit for occupancy class Group A Sub Division A-I Lodging or Rooming Houses with effect from --1.3 ----2013 for a period of 03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 1.3. . at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

## Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049 w.r.t. letter No.3436-38/Addl.C.P./Lic.(H) New Delhi dated 09-07-2013
- 2. Chandrika Inn Guest House located at 4/9, 1<sup>st</sup> floor, Asaf Ali Road (Near Bank of India), New Delhi-110002

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Chandrika Inn Guest House, 4/9, 1st floor, Asaf Ali Road (Near Bank of India), New Delhi-110002

**INSPECTION REPORT** 

: Chandrika Inn Guest house, 4/9, 1<sup>st</sup> floor, Asaf Ali Road, New Delhi 1. Name & address of the building

2. Type of Occupancy Lodging House

3. Type of Case New Case

4. Details of previous NOC Letter No. N/A Dated .....

5. Fire Safety directives Letter No. N/A

6. Date of inspection 31-07-2013

7. Name of the Inspecting Officer Sh. D.S. Yadav (D.O.)

8. Name and designation of Officer

from the building side Smt. Sunita Jain (owner)

9. Year of Construction Prior to 2005

10	Applicant's letter No. : N	Io.3436-38/Add	I.C.P./Lic.(H) Nev	w Delhi dat	ted 09-07-2013
S No	Minimum standards on fire prevention	BBL	Provided at site	Rema	rks MR/NMR
	and fire safety U/R 33	Requirements			
1.	Access of building				
	<ul> <li>Road width</li> </ul>	Accessible	More then 06 m		MR
	Gate width		Directly Accessing Road.	ble from	MR
	Width of internal road	N/A	N/A		N/A
2.	Number, width, Type & Arrangements	of exits			
	a. Number of staircases				
	Upper floors	01	02		MR
	Basements (other property)	N/A	N/A		N/A
	b. Width of staircases	14/11	14/16	2	IVIT
	Upper floors	105cms & 90ci	ms. Prov	ided	MR
	<ul> <li>Basements(separate entry/exit)</li> </ul>	N/A	N/		N/A
	c. Protection of exits				2 * 5
	<ul> <li>Fire check door</li> </ul>	N/A	N/A	1	N/A
	<ul> <li>Pressurization</li> </ul>	N/A	N/A		N/A
	d. No of continuous staircase to terrace	01	01		MR
	e. Width Of Corridor	N/A	N/A		N/A
	f. Door Size	N/A	N/A		N/A
3.	Compartmentation				
	Fire check door	N/A	N/A		N/A
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A		N/A
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A		N/A
	Water Curtain	N/A	N/A		N/A
	Fire Dampers	N/A	N/A		N/A
4.	Smoke managements System				
	Basements	30 a/c per hour	N/A		N/A
	Upper floors	12 a/c per hour	Natural ventilation	1	MR
5.	Fire Extinguishers				
	Total numbers	06	06		MR

Chandrika Inn Guest House, 4/9, 1<sup>st</sup> floor, Asaf Ali Road (Near Bank of India), New Delhi-110002

	Chandrika Inn Guest House, 4/9, 1 <sup>st</sup> flo						
	<ul> <li>Types</li> </ul>		Water Co2 & A.B.C. type.	MR			
	IS marking	ISI marked	Provided	MR			
6.	First – Aid Hose Reels						
	<ul> <li>Total numbers on each floor</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Length of hose reel hose</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Nozzle diameter</li> </ul>	N/A	N/A	N/A			
7.	Automatic fire detection and alarming s	ystem					
	Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
8.	MOEFA	N/A	N/A	N/A			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System	IN/A	IN/A	IN/A			
10.		N/A	N/A	N/A			
	57340 (30000000000000000000000000000000000						
	Upper Floor     Sprinkland have false willing	N/A	N/A	N/A			
1.1	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down- comer	N/A	N/A	N/A			
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants	T					
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements						
	Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	> Head of main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	> Jockey pump out put	N/A	N/A	N/A			
	<ul><li>Jockey pump head</li></ul>	N/A	N/A N/A	N/A			
	Standby Pump out put	N/A	N/A N/A	N/A			
	Standby Pump Head	N/A	N/A N/A				
	> auto Staring/Manual stopping	N/A		N/A			
	> Pump House Access		N/A	N/A			
	Terrace level	N/A	N/A	N/A			
	Discharge of pump	DI/A	N//A				
	> Head of the pump	N/A	N/A	N/A			
	> Power supply	N/A	N/A	N/A			
	> Auto starting of pump	N/A	N/A	N/A			
1.4	0 1 1	N/A	N/A	N/A			
14.	Captive water Storage for fire fighting						
	<ul> <li>Under ground tank capacity</li> </ul>	N/A	N/A	N/A			
	Draw of connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	N/A	N/A	N/A			
15	Exit Signage	Required	Provided	MR			
16.	Provision of Lifts						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			
	Communication in lift Car	N/A	N/A	N/A N/A			
	Fireman's Grounding Switch	N/A	N/A				
	Lift Signage	N/A	N/A N/A	N/A			
17.				N/A			
1/.	Standby power supply	Emergency light	t Provided	MR			

	Chandrika Inn Guest House, 4/9, 1 <sup>st</sup> floo  ☐ ➤ Total area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19.	Fire control room			
/	Detector system panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	> PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation Signature of the Inspecting Officer

- 111

21/2

Name Platen via singh yelov.
Designation Divisional befores (c.3)