GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO.F6/DFS/MS/school/2013/52/798

Dated: 26/08/13

FIRE SAFETY CERTIFICATE

Certified that Govt. Sarvodaya Co-Ed Senior Secondary School, Sec.-6, R.K.Puram, New Delhi-110022 comprised of Ground floor + 1 Upper floor only (03 Blocks), having total 44 class rooms, owned/occupied by MCD was inspected by the officer concerned of this department on 08.08.2013 in presence of Mr. R.R.Meena (Principal) and found that the School have complied with the fire prevention and fire safety requirements in accordance with the Circular No-F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011issued by the Directorate of Education dated 01-03-2011 and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the below mentioned conditions.

Issued on -2-6/13- at New Delhi by.

(Dr. G.C. Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to: -

The Principal, Govt. Sarvodaya Co-Ed Senior Secondary School Sec.-6, R.K.Puram, New Delhi-110022

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Govt. Sarvodaya Co-Ed. Senior Secondary School, Sec.-6,

R.K.Puram, New Delhi-110022

2. Type of Occupancy

: Educational

3. Type of Case

: New Case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No : F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01-03-2011.

6. Date of inspection

: 08.08.2013

7. Name of the Inspecting Officers: ADO D.B.Mukherjee

8. Name and designation of officers

from the building side

: Sh.R.R.Meena, Principal

9. Year of Construction

: 1967 & 2012

10. Applicant's letter No.

: Nil dated 15/07/2013, Ground + 01 upper floors in 03 blocks.

S. N o.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR	
1	Access to building	1			
	 Road width 	Required	Provided	MR	
	• Gate width	Required	02 nos 3.5 mtrs each	MR	
	 Width of internal road 	N/A	N/A	N/A	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases		8 -2	, ,	
	 Upper Floors 	Required	02	MR	
	 Basements 	N/A	N/A	N/A	
	b. Width of staircases				
	 Upper Floors 	Required	Total 06 Nos	MR	
		ş	1.50,1.47,1.80,1.35,1.5 0 & 1.50 mtrs		
	• Basements	N/A	N/A	N/A	
	c. Protection of exits			9	
	 Fire check door 	N/A	N/A	N/A	
	 Pressurization 	N/A	N/A	N/A	
	e. No. of continuous staircases to	01	02	MR	
	terrace	N/A	N/A	N/A	
	g. Width of Corridorh. Door Size	N/A	N/A	N/A	

3	Compartmentation.	Not required	2		
	Fire check door	N/A	N/A	N/A	
	 Sealing of electrical shafts 	N/A	N/A	N/A	
	• Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	• Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System. Low-rise bldg, Not required				
	 Basements 	30 a/c per hour	N/A	N/A	
	 Upper floors 	12 a/c per hour	N/A	N/A	
5	Fire Extinguishers				
	• Total numbers		Provided 38 Nos.	MR	
	• Types	ISI marked	Provided ABC & Co2	MR	
	IS marking		Provided	MR	
5	First-Aid Hose Reels. Not required				
	 Total numbers on each floor 		N/A	N/A	
	 Length of hose reel hose 	30 m	N/A	N/A	
	Nozzle diameter	5 mm	N/A	N/A	
7	Automatic fire detection and alarming system. Not required				
	• Type of detectors	N/A	N/A	N/A	
	• Location of Main Panel	N/A	N/A	N/A	
	• Location of Repeater Panel	N/A	N/A	N/A	
	 Alternate source of power 	N/A	N/A	N/A	
	 Hooters' Location 	N/A	N/A	N/A	
8	MOEFA	N/A	N/A	N/A	
9	Public Address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System				
	• Basement	N/A	N/A	N/A	
	• Upper Floor	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	

K

13	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12	Yard Hydrants.			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements			
	 Ground Level 			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/ Manual	N/A	N/A	N/A
	stopping	N/A	N/A	N/A
	Pump House Access			
	Terrace levelDischarge of pump	N/A	N/A	N/A
	Head of the pump	N/A	N/A	N/A
	Power Supply	N/A	N/A	N/A
	Auto Starting of pump			
14	Captive Water Storage for fire fighting	9		
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15	Exit Signage.	Required	Provided	MR

16	Provision of Lifts.	Not Applicable		The state of the s	
100	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	• Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
	 Building Floor Plans 	N/A	N/A	N/A	
20	Special Fire Protection Systems for	N/A	N/A	N/A	
	Protection of special Risks, if any:				

The fire protection systems provided in the building were test checked and found functional at the time of nspection.

The shortcomings issued vide letter no.F6/DFS/MS/School/2011/2472 Dated 10/10/2011 has been rectified. Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules as per the directives of Education Department vide Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01-03-2011 it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010. Accordingly DFA is proved for supported to the property of the propert

Note: The school building is comprised of ground floor plus one upper floor and running in three blocks.

Do youth)

Signature of the Inspecting Officer

Name: D.B.Mukherjee

Designation: - Assistant Divisional Officer (BCP)