GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No. F6/MS/DFS/GH/2013/ MO2/836

Dated: 03/09/13

FIRE SAFETY CERTIFICATE

Certified that the R. Continental Guest House located at 9966-71, Gali No.-4, Des Raj Bhatia Marg, Mulatani Dhanda, Pahar Ganj, New Delhi-110055 comprised of lower ground floor (reception), upper ground floor (04 guest rooms), 1st floor (04 guest rooms), 2nd floor (04 guest rooms) and 3rd floor (04 guest rooms), total 16 guest rooms, owned / occupied by M/s R. Continental Guest House have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 22-08-2013 in the presence of Smt. Garima Dawer (owner) and that the building / premises, is fit for occupancy class Group A Sub Division A-I Lodging or Rooming Houses with effect from - 52/09/13 2013 for a period of 03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .0.3./.9.1/.3 at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

Copy to :-

- o:The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi - 110049 wrt. No.36642-45/Addl.C.P./Lic.(H) New Delhi dated 17-7-2013
- M/s R. Continental Guest House, 9966-71, Gali No.-4, Des Raj Bhatia Marg, 2. Mulatani Dhanda, Pahar Gani, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

R. Continental Guest House, 9966-71, Gali No.-4, Des Raj Bhatia Marg, Mulatani Dhanda, Pahar Ganj, New Delhi-55

INSPECTION REPORT

1. Name & address of the building

: R. Continental Guest House, 9966-71, Gali No.-4, Desraj

Bhatia Marg, Mulatani Dhanda, Pahar Ganj, New Delhi-55

2. Type of Occupancy

: Lodging House

3. Type of Case

New Case

4. Details of previous NOC

Letter No. N/A Dated

5. Fire Safety directives Letter No. :

N/A

6. Date of inspection

: 22-08-2013

7. Name of the Inspecting Officer

Sh. D.S. Yadav

(D.O.)

8. Name and designation of Officer

from the building side

Smt. Garima Dawer (owner)

9. Year of Construction

2005

10. Applicant's letter No.

: No.36642-45/Addl.C.P./Lic.(H) New Delhi dated 17-7-2013

| S No | Minimum standards on fire prevention | BBL | Provided at site | Remarks MR/NMR | |
|------|--|-----------------|--------------------------------|----------------|--|
| | and fire safety U/R 33 | Requirements | (PSS Area) | (P.S.S Area) | |
| 1. | Access of building | | | | |
| | Road width | N/A | 6 mtrs. Approx. | MR | |
| | Gate width | | Directly Accessible from Road. | MR | |
| | Width of internal road | N/A | N/A | N/A | |
| 2. | Number, width, Type & Arrangements | of exits | | | |
| | a. Number of staircases | | | | |
| | Upper floors | 01 | 01 | MR | |
| | Basements | N/A | N/A | N/A | |
| | | | | | |
| | Upper floors | 80 cms | 140 cms to 150 cms | MR | |
| | • Basements | N/A | N/A | N/A | |
| | c. Protection of exits | | I | | |
| | Fire check door | N/A | N/A | N/A | |
| | Pressurization | N/A | N/A | N/A | |
| | d. No of continuous staircase to terrace | 01 | 01 | MR | |
| | e. Width Of Corridor | N/A | N/A | N/A | |
| | f. Door Size | | 206 cms X 80 cms | N/A | |
| 3. | Compartmentation | | | | |
| | Fire check door | N/A | N/A | N/A | |
| | Sealing of electrical shafts | N/A | N/A | N/A | |
| | Fire Rating of shaft door | N/A | N/A | N/A | |
| | Water Curtain | N/A | N/A | N/A | |
| | Fire Dampers | N/A | N/A | N/A | |
| 4. | Smoke managements System | | | an consequence | |
| | Basements | 30 a/c per hour | Exhaust Fans | MR | |
| | Upper floors | 12 a/c per hour | Natural ventilation | MR | |

R. Continental Guest House, 9966-71, Gali No.-4, Des Raj Bhatia Marg, Mulatani Dhanda, Pahar Ganj, New Delh

| | ntal Guest House, 9966-71, Gali No4, Fire Extinguishers | | 10 | MR | | |
|-----|--|--|-------------------|--|--|--|
| | Total numbers | 10 | Water Co2 & | MR | | |
| | • Types | | A.B.C. type. | | | |
| | | | Provided Provided | MR | | |
| | IS marking | Si illaiked | Tiovides | | | |
| | First – Aid Hose Reels | 0.1 | 01 | MR | | |
| | Total numbers on each floor | 01 | Provided | MR | | |
| | Length of hose reel hose | 30 M | Provided | MR | | |
| | Nozzle diameter | 5 mm | 11071404 | | | |
| | Automatic fire detection and alarming sys | stem | N/A | N/A | | |
| • | Type of detectors | 14/11 | N/A | N/A | | |
| | Location of Main Panel | N/A | N/A | N/A | | |
| | Location of Repeater Panel | N/A | N/A | N/A | | |
| | Alternate source of power | N/A | N/A | N/A | | |
| | Hooters' Location | N/A | Provided | MR | | |
| 3. | MOEFA | Required | Provided | M/R | | |
|). | Public Address System | Required | Frovided | The second secon | | |
| 10. | Automatic Sprinkler System | ~ 7/1 | N/A | N/A | | |
| 10. | Basements | N/A | N/A N/A | N/A | | |
| | Unner Floor | N/A | N/A N/A | N/A | | |
| | Sprinkler above false ceiling | N/A | IN/FX | | | |
| 11. | Internal Hydrants | | NI/A | N/A | | |
| 11. | Size of riser/down- comer | N/A | N/A | N/A | | |
| | Number of hydrants per floor | N/A | N/A | N/A | | |
| | Hose Box | N/A | N/A | | | |
| 12. | Yard Hydrants | | 27/4 | N/A | | |
| 14. | Total number of hydrants | N/A | N/A | N/A | | |
| | Hose Box | N/A | N/A | THIX | | |
| 12 | Pumping Arrangements | | | | | |
| 13. | Ground Level | | 27/4 | N/A | | |
| | Discharge of main pump | N/A | N/A | N/A | | |
| | 1 0 | N/A | N/A | N/A N/A | | |
| | Head of main pumpNumber of main pumps | N/A | N/A | N/A N/A | | |
| | > Jockey pump out put | N/A | N/A | N/A N/A | | |
| | > Jockey pump head | N/A | N/A | N/A N/A | | |
| | Standby Pump out put | N/A | N/A | N/A | | |
| | Standby Pump Head | N/A | N/A | N/A | | |
| | auto Staring/Manual stopping | N/A | N/A | N/A | | |
| | Pump House Access | N/A | N/A | IN/A | | |
| | Terrace level | | 7 1 1 | MR | | |
| | Discharge of pump | 450 LPN | _ 111 | MR | | |
| | Head of the pump | 35 Mtrs | | M/R | | |
| | Power supply | Required | | M/R | | |
| | Auto starting of pump | Required | Provided | IVI/ IX | | |
| 1 | 4. Captive water Storage for fire fighting | C. C. vice water Storage for fire fighting | | | | |
| 1 | Under ground tank capacity | N/A | N/A | N/A N/A | | |
| | > Draw of connection | N/A | N/A | | | |
| | Fire service inlet | N/A | N/A | N/A | | |
| | > Access to tank | N/A | N/A | N/A | | |
| | Overhead Tank capacity | 5000 Ltrs | | MR | | |
| - | | Require | d Provided | MR | | |
| _ | 27.12 | | | NI/A | | |
| | 16. Provision of Lifts ➤ Pressurization of Lift Shaft | N/A | N/A | N/A | | |
| | > Pressurization of lift lobby | N/A | N/A | N/A | | |

Continental Guest House, 9966-71, Gali No.-4, Des Raj Bhatia Marg, Mulatani Dhanda, Pahar Ganj, New Delh

| - | , , , , , , , , , , , , , , , , , , , | 1, Des Raj Dilat | ia maig, mulatalli D | nanda, Panar Ganj, New Dell |
|-----|--|------------------|----------------------|-----------------------------|
| | Communication in lift Car | Required | Provided | M/R |
| | Fireman's Grounding Switch | Required | Provided | M/R |
| | Lift Signage | Required | Provided | M/R |
| 17. | Standby power supply | Required | D.G. Set | MR |
| 18. | Refuge Area | • | | IVIIC |
| | > Total area | N/A | N/A | N/A |
| 10 | > Location | N/A | N/A | N/A |
| 19. | Fire control room | | | 17/21 |
| | Detector system panel | N/A | N/A | N/A |
| * | Flow Switch Panel | N/A | N/A | N/A |
| | PA System Panel | N/A | N/A | N/A |
| | Batter backupBuilding Floor Plans | N/A | N/A | N/A |
| 20. | | N/A | N/A | N/A |
| 20. | Special Fire Protection Systems for | N/A | 01 Co2 & 01 ABC | MR |
| | Protection of special Risks, if any; | | fire extinguisher | |
| | | | provided near | |
| | | | electric panel | |

The fire protection systems provided in the building were test checked and found functional at the time of

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation Signature of the Inspecting Officer

Name Dharm vit singh yadar Designation Divisional officer (e. 2)