GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No. F6/OFS/ m8/school/2013/885

Dated: 09/09/13

FIRE SAFETY CERTIFICATE

Certified that the Kerla Education Society Regd. Senior Secondary School located at Srimat Madhav Rao Scindia Marg, (Canning Road), New Delhi-110001 comprised of Ground + 2 upper floor owned/ occupied by Kerla Education Society Regd. have complied with the prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 & verify by the officer concerned of fire service on 02-09-2013 in the presence of Mr. A.K. Thomas (Manager) and that the premises fit for occupancy class B Education Building School up to Sr. Sec. Level with effect from $\frac{1}{2} \frac{1}{2} \frac{1}{2$

Issued .o.Ş./.?. at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. Manager, Kerla Education Society Regd. Senior Secondary School, Srimat Madhav Rao Scindia Marg, (Canning Road), New Delhi-110001
- 2. The Director Education, Old Secretariat, Delhi110054

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Kerla Education Society Regd. Senior Secondary School, Srimat Madhav Rao Scindia Marg, (Canning Road), New Del

INSPECTION REPORT

1. Name & address of the building : Kerla Education Society Regd. Senior Secondary School, Srimat

madhav Rao Scindia Marg, (Canning Road), New Delhi-110001

2. Type of Occupancy : class B Education Building School up to Sr. Sec. Level

3. Type of Case : New

4. Details of previous NOC : N/A

5. Safety directives Letter No. : N/A

6. Date of inspection : 02-09-2013

7. Name of the Inspecting Officer : Sh. D.S. Yadav (D.O.)

8. Name and designation of Officer

from the building side : Mr. A.K. Thomas (manager)

9. Year of Construction : 1981

10. Applicant's letter No. : KES/Fire/2013/646 dated 22-07-13.

S No	Minimum standards on fire prevention	BBL	Provided at site	Remarks MR/NMR		
	and fire safety U/R 33	Requirements				
1.	Access of building					
	Road width	Accessible	More then 6 mtrs. wide road	MR		
	• Gate width	Required	4 mtr.	N/A		
	 Width of internal road 	N/A	N/A	N/A		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases			3 ° 0 ° 1		
	 Upper floors 	Required	03	MR		
	 Basements 	N/A	N/A	N/A		
	b. Width of staircases	1071				
	Upper floors	150 cms	150 cms., 130 cms.	MR		
	*		& 100 cms.			
	Basements	N/A	N/A	N/A		
	A COLOR DE LA COLO	Protection of exits				
	Fire check door	N/A	N/A	N/A		
	 Pressurization 	N/A	N/A	N/A		
	d. No of continuous staircase to terrace	01	02	MR		
	e. Width Of Corridor	N/A	N/A	N/A		
	f. Door Size	N/A	N/A	N/A		
3.	Compartmentation			TV/A		
	 Fire check door 	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke managements System			11/11		
	Basements	30 a/c per hour	N/A	N/A		

dely

Kerla Education Society Regd. Senior Secondary School, Srimat Madhav Rao Scindia Marg, (Canning Road),

	Smoke managements System					
4.	Basements	30 a/c per hour	N/A	N/A		
	Upper floors	12 a/c per hour	Natural ventilation	MR		
	Fire Extinguishers	The state of the s				
5.	Total numbers	14	14	MR		
	• Types		Water Co2 &	MR		
	Types		A.B.C. type.			
	IS marking	ISI marked	Provided	MR		
5.	First – Aid Hose Reels		1101100			
).	m 1 1 1 0	03	03	MR		
	POLICE CONTROL	30 M	Provided	MR		
	• Length of hose reel hose	5 mm	Provided	MR		
7	Nozzle diameter		Tiovided	IVIIC		
7.	Automatic fire detection and alarming s		NI/A	N/A		
	Type of detectors	N/A	N/A	N/A N/A		
	 Location of Main Panel 	N/A	N/A			
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8.	MOEFA	Siren	Provided	MR		
9.	Public Address System/Intercom	N/A	Provided	MR		
10.	Automatic Sprinkler System					
	Basements	N/A	N/A	N/A		
	Upper Floor	N/A	N/A	N/A		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
11.	Internal Hydrants					
	Size of riser/down- comer	N/A	100 mm.	MR		
	 Number of hydrants per floor 	N/A	03nos	MR		
	Hose Box	N/A	03 nos	MR		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.		11/12	11/12			
15.	Pumping Arrangements • Ground Level					
	 Ground Level Discharge of main pump	N/A	N/A	N/A		
	Discharge of main pumpHead of main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A N/A		
	Jockey pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A N/A	N/A N/A		
	> Standby Pump out put	N/A	N/A N/A	N/A N/A		
	Standby Pump Head	N/A	N/A N/A	N/A N/A		
	auto Staring/Manual stopping	N/A	N/A N/A	N/A N/A		
	> Pump House Access	N/A N/A	N/A N/A	N/A N/A		
	Terrace level	IN/A	1N/F	IN/A		
	Discharge of pump	OOO I DNA	D	MD		
	> Head of the pump	900 LPM	Provided	MR		
	> Power supply	40 Mtrs.	Provided	MR		
	> Auto starting of pump	Required	Provided	MR		
1.4	0 1 1	Required	Provided	MR		
14.	Captive water Storage for fire fighting	NT/A	N T/A	NT/A		
	Under ground tank capacity	N/A	N/A	N/A		
	> Draw of connection	N/A	N/A	N/A		
	Fire service inlet	Required	Provided	MR		
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	10000 ltrs	Provided	MR		
15	Exit Signage	Required	Provided	MR		

Perla Education Society Regd. Senior Secondary School, Srimat Madhav Rao Scindia Marg, (Canning Road), New Del

16.	Provision of Lifts	viaig, (Caining Road),			
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of lift lobby	N/A	N/A	N/A	
	Communication in lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
17.	Standby power supply	N/A	N/A	N/A	
18.	Refuge Area				
	> Total area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19.	Fire control room				
,,	Detector system panelFlow Switch Panel	N/A	N/A	N/A	
		N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
	➤ Building Floor Plans	N/A	N/A	N/A	
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation Signature of the Inspecting Officer

Name Dhazm viz single yalow Designation Divisional officel (c.D)