GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2013/ \$2/936

Dated: 20109/13

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Majestic Palace** located at 4/35, WEA, Saraswati Marg, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus three upper floors, using basement as office & store, ground floor as reception & office, first & second floor each having 09 guest rooms respectively, third floor having 05 guest rooms, office & a pantry for staff (Total 23 guest rooms) was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2010/2879 dated 05.10.2010 owned/occupied by Smt. Sawinder Jeet Kaur. The guest house building was re- inspected by the officer concerned of this department on 14.09.2013 in the presence of Sh. Y.P. Vij (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

6h

Copy to:-

1. The Joint. Commissioner of Police (Lic.)

1st floor, P.S., Defence Colony, New Delhi.

(Re. No.42639/Joint. C.P./Lic.(H), Dated 26.08.2013)

2. Smt. Sawinder Jeet Kaur (Owner), Hotel Majestic Palace, 4/35, WEA, Saraswati Marg, Karol Bagh, New Delhi-110005. Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

Basement, Ground floor plus three lepper Floors.

	INSPECT	TION PEROPT					
	Name & address of the building of	CION REPORT	0.0	:			
	 Name & address of the building: / Type of Occupancy 	Parila Majestic	Palace 4/35,	Sarascrati Marg, V			
	3. Type of Case	New Case/Rener	est Mouse) Karol	Bagh, N.D.as.			
	4. Details of Previous NOC	The Case / New levy al					
	5. Fire Safety directives letter No	Letter No. F.6/DFS/MS/GH/2010/2879 Date 05:10:20					
	 Date of inspection						
	7. Name of Inspecting Officer						
	8. Name and designation of officers						
	From the building side	Sh. V	P. Vij (Ma				
	9. Year of Construction	2001	7 (11/0	hager)			
	10. Applicant's letter No.		P/Lic(H) date	d 91.00 2010			
5.	Jan Startaards off file	NBC/BBL	Provided at	Remarks			
No.	prevention and fire safety U/R 33	Requirement	site	MR/NMR			
l	Access to building		1 3.00	TARRY MAIN			
	 Road width 	Accessible	07mtr	MR			
	Gate width	_	160 cms	MR			
	Width of internal road			(*//			
2.	Number, Width, Type & Arrangement	of Exits					
	a. Number of staircases						
	• Upper Floors	One	0.				
	 Basements 	Two	One	MR, Being a ola			
	b. Width of staircases	160	760	MRO			
	Upper Floor		1900				
	Basements		12Semp	MR, Being a old			
	c. Protection of exits		190 cm 8, 120 cm 8	-do-			
	Fire check door			1			
	• pressurization		- 1				
	d. Not of continuous staircases to						
	terrace	-					
	e. Width of Corridor	P	One				
	f. Door Size	_	185cms, 120cms	-			
		_	87 CM & 200 CMs	;			
	Compartmentation						
	Fire check door	_	· · · · · · · · · · · · · · · · · · ·				
	Sealing of electrical shafts		0				
	Fire Rating of shaft door		Sealed				
	Water Curtain	-		-			
	Fire Dampers			-			
١.	Smoke Management System						
	Basements	20 /	Exhaust forms				
	Upper floors	30 a/c per	ore Provided	MR			
	apper moors	hour	1 OUVICECT	1.17			

	e e e e e e e e e e e e e e e e e e e	*	2 A 2 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	1
	E TO THE STATE OF	12 a/c per		
		hour	-	-
5.	Fire Extinguishers			
٦.		Two at each floor	P 1. 1	200
*	Total Hambers	Co, WG, ABC	Provided	MR
	TypesIS marking	ISI marked	-do-	MR
6.	First-Aid Hose Reels	131 Harked	151 Marked	MR
0.	Total numbers on each floor	One	Pa	NR
	Length of hose reel hose	30 m	Provided	
	Nozzle diameter	5 mm	- do -	MR
7.	Automatic fire detection and alarming		-do:-	N/R
7.		system	<u> </u>	
	Type of detectorsLocation of Main Panel			
			-	
	Location of Repeater Panel		1	1 + +
	Alternate source of power	-	D.C. Set of 82.5K	VA I-
	Hooters' Location	0 , 1	0	
8.	MOEFA	Required	Provided	MR
9.	Public Address System	- do -	-00-	MAR
10.	Automatic Sprinkler System	0	0 111	NA
	Basement	Kequired	Provided	1778
	Upper Floor		1	6+
11	Sprinkler above false ceiling			
11.	Internal Hydrants		· · · · · · · · · · · · · · · · · · ·	
	Size of riser/down-comer		La Caracteria de la Car	+
	Number of hydrants per floor	• • •		
1.0	Hose Box	. !		
12.	Yard Hydrants	<u> </u>	J.	
	Total number of hydrantsHose Box			
13.				
13.	Pumping Arrangements • Ground Level			0 km 0
	Ground LevelDischarge of main Pump			
	> Head of Main pump			
	> Number of main pumps	-		
	> Jockey Pump out put			
	> Jockey pump head		*	1
	> Standby Pump out put			-
	Standby Pump Head			-
	> Auto Starting/Manual			
	stopping			

4/35, WEA, Saroswati Marg, Karol Bagh, New Delli-110005.

	Pump House Access	_				
	Terrace level			, ,		
	Discharge of pump	Servi	450 LPM	MR, Being a Olo		
	Head of the pump			MR, Being a Old - do - MR		
	Power Supply	Required	30 M Provided	MR		
	Auto Starting of pump					
L4.	Captive Water Storage for fire fighting			ı		
_	Underground tank capacity					
	Draw-off connection					
	➤ Fire service inlet	_	Provided	9,000		
	> Access to tank		700000			
	Overhead Tank capacity		Sooo Ur	MR, Being a O		
	overneud raim expansy			1		
4.5	Folk Cinnana	Required	Provided	MR		
15. 16.	Exit Signage. Provision of Lifts.			å å		
10.	Pressurization of Lift Shaft	-				
	Pressurization of Lift lobby		:	_ 1		
	Communication In lift Car		0	han !		
		-	Provided	MR		
	• * Fireman's Grounding Switch	Regard	- do -	MR		
	Lift Signage	do-	-do-	MR		
47	Se alle a para supply	Required -do- Required	Provided	MR		
17.	Standby power supply	V		i i		
4.0	Politica Area					
18.	Refuge Area. > Total Area					
		6				
	> Location		-	-		
	t t			-		
19.	Fire Control Room					
13.	Detector System Panel					
	Flow Switch Panel					
		-				
	PA System Panel Partnershader					
	Batter backup	Reguired	Provided	MR		
	Building Floor Plans	V				
			-			
		8		* ×		
20.	Special Fire Protection System for Protection of special Risks, if any:					
	t miles to the first the second to the manager	1 .	1	1		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers....

Signature of Inspecting Officer

Name P.S. Dahiya

Designation AppH. Divisional Officer-

Signature of Inspecting Officer

Name

Designation