GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001 Fax: 23412593, Email: cfohq.dlfire@nic.in Tel: - 01-23414333

NO. F6/DFS/MS/GH/2013/ NO2/969

Dated: 25/09/1/3

FIRE SAFETY CERTIFICATE

Certified that Sana Guest House, 1991, Gali Indrar Khan, Qasim Jaan Steret, Ballimaran, Delhi-6, comprised of ground (Commercial), first floor (06 rooms & reception), Second floor ((09 rooms), third floor (owner's residence), and terrace (Water tank) Total 15 rooms, was granted NOC by this department vide letter No. F.6/MS/DFS/GH/1677 Dated: 08-06-2010. The premises was re-inspected by the offices concerned of this department on 19-09-2013 in the presence of Sh. Shakeeruddin, Proprietor of the guest house and found that the said guest house is located in special area have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy of 15 guest rooms with effect from 25/09/1/2 for a period of 25---- years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules,2010.

Issued on 25/9//3 at New Delhi by.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to: -

- 1. The Joint.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.
- 2. M/s Sana Guest House, 1991, Gali Indrar Khan, Qasim Jaan Strret, Ballimaran, Delhi-6

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time.
- b. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- c. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- d. The trained fire fighting staff shall be available round the clock.
- e. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Sana Guest House, 1991, Gali Indara Kuan, Qasim Jaan Strret, Ballimaran, Delhi-6

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: Letter No. F.6/MS/DFS/GH/1677 Dated: 08-06-2010

5. Fire Safety directives letter No: Nil

6. Date of inspection

: 19-09-2013

7. Name of the Inspecting Officers: Sanjay Kumar Tomar, ADO (SPM)

8. Name and designation of officers

from the building side

:Mr.Shakeeruddin (Prop.)

9. Year of Construction

: -

10. Applicant's letter No.

:42519-20/Joint C.P./Lic(H) dated 26/8/13

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site (Spl Area)	Remarks MR/NMR	
1	Access to building				
	Road widthGate width	Accessible (Spl Area)	5 mtr (Aprox)	MR	
	 Width of internal road 	N/A	N/A	N/A	
		N/A	N/A	N/A	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases	-	_	r ja	
	Upper Floors	One	One	MR	
	Basements	N/A	N/A	N/A	
	b. Width of staircases	_	-		
	Upper Floors	85 Cms	85 Cms	MR	
	Basements	N/A	N/A	N/A	
	c. Protection of exits	N/A	N/A	N/A	
	Fire check door	N/A	N/A	N/A	
	 Pressurization 	N/A	N/A	N/A	
	e. No. of continuous staircases to terrace	One	One	MR	
	g. Width of Corridor	N/A	N/A	N/A	
	h. Door Size	N/A	N/A	N/A	
		N/A	N/A	N/A	

	Compartmentation.			7.	
	Fire check door	N/A	N/A	N/A	
	 Sealing of electrical shafts 	N/A	N/A	N/A	
	 Fire Rating of shaft door 	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	• Fire Dampers	N/A	N/A	N/A	
ļ	Smoke Management System.				
-	Basements	30 a/c per hour	N/A	N/A	
	Upper floors	12 a/c per hour			
	• Opper Hoors		N/A	N/A	
5	Fire Extinguishers				
<u> </u>	Total numbers	Six	Provided and	MR	
	• Types	Water Co2, Co2	found working	The same of	
	IS marking	ISI marked	Provided	MR	
			Provided	MR	
6	First-Aid Hose Reels.				
	Total numbers	One	Provided and	MR	
	 Length of hose reel hose 	30 m	found functional		
	Nozzle diameter	5 mm	Provided	MR	
			Provided	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors	N/A	N/A	N/A	
	 Location of Main Panel 	N/A	N/A	N/A	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
8	MOEFA	N/A	N/A	N/A	
9	Public Address System.	N/A	N/A	N/A	
10	Public Address System.				
10	Basement	N/A	N/A	N/A	
	 Upper Floor 	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
	1 Internal Hydrants				



•	Pressurization of Lift Shaft	N/A	N/A	N/A		
6 Prov	vision of Lifts.					
5 Exit	Signage.	Required	Provided	MR		
•	Overhead Tank capacity	2500 Ltrs	Provided	MR		
7		N/A	N/A	N/A		
7	Fire service inlet	N/A	- N/A	N/A		
7	> Draw-off connection	N/A	N/A	N/A		
•	Underground tank capacity	N/A	N/A	N/A		
4 Cap	tive Water Storage for fire fighting.					
		N/A	Switch Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
	Power Supply	40 M	Provided Provided	MR		
	Discharge of pumpHead of the pump	ZZJ LFIVI	found working	MR		
•	1011400 10 101	225 LPM	Provided and	N		
	Pump House Access	N/A	N/A	N/A		
	stopping	N/A	N/A	N/A		
	Auto Starting/ Manual	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Discharge of main Pump	N/A	N/A	N/A		
•	• Ground Level	N/A	N/A	N/A		
3 Pun	Pumping Arrangements.					
	Hose Box	N/A	N/A	N/A		
	Total number of hydrants	N/A	N/A	N/A		
2 Yar	Yard Hydrants.					
	Hose Box	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
· ·	Size of riser/down-comer	N/A	N/A	N/A		

Sana Guest House, 1991, Gali Indra Kuan, QuasimJan Street, hal Kuan, Delhi o

			de la companya della companya della companya de la companya della
Pressurization of Lift lobby	N/A	N/A	N/A
Communication In lift Car	N/A	N/A	N/A
Fireman's Grounding Switch	N/A	N/A	N/A
Lift Signage	N/A	N/A	N/A
17 Standby power supply	Required	Provided Inverter	MR
18 Refuge Area.	-	a so vided inverter	IVIK
> Total Area	N/A	N/A	N/A
> Location	N/A	N/A	N/A
19 Fire Control Room		1 1/11	14/11
Detector System Panel	N/A	N/A	N/A
Flow Switch Panel	N/A	N/A	N/A
PA System Panel	N/A	N/A	N/A
Batter backup	N/A	N/A	N/A
Building Floor Plans	N/A	N/A	N/A
Special Fire Protection Systems for	Required	Provided one Co2	MR
Protection of special Risks, if any:		fire extinguisher near	
		Elect Panel	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the non compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010. Accordingly, DFA is put up for approval please.

Received on 23-9-13

Signature of the Inspecting Officer Name: SANJAY KUMAR TOMAR

1x 10 mer

Designation :- Divisional Officer

00(00)

Submitted please.