GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001 Fax: 23412593, Email: cfohq.dlfire@nic.in Tel: - 01-23414333

NO. F6/DFS/MS/GH/2013/ NO2/1018

Dated: 03 /10/13

FIRE SAFETY CERTIFICATE

Certified that Shyama Inn, 5050/12, Netaji Subhash Marg, Darya Ganj, Delhi-6, comprised of ground floor (Commercial), Mezzanine floor (Commercial), first floor (06 rooms, reception + 01 store), Second floor ((05 rooms + 01 store) and terrace (Generator room, Water tank & mumty) Total 11 rooms, was granted NOC by this department vide letter No. F.6/MS/DFS/GH/2010/2896 Dated: 06-10-2010. The premises was re-inspected by the officer concerned of this department on 21-09-2013 in the presence of Sh. Suresh, Manager of the guest house and found that the said guest house is located in special area have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy of 11 guest rooms with effect from 03 16 13 for a period of -03 years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules,2010.

Issued on <u>03 110/13</u> at New Delhi by.

(DR G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to: -

- 1. The Joint.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.
- 2. M/s Shyama Inn, 5050/12, Netaji Subhash Marg, Darya Ganj, Delhi-6

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time.
- b. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- c. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- d. The trained fire fighting staff shall be available round the clock.
- e. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

| | 1. Name & address of the building: 3h | Jama Inn Isi | -12nd low 50501 | 12 Hanger |
|-----|--|----------------|-----------------------------|------------|
| | 2. Type of Occupancy : Lodgin | 0 | MargNDelli | |
| | 3. Type of Case Renev | val / New case | | 3" |
| | 4. Details of previous NOC : Letter | No. F. 6/melne | 5/64/2010/2896Date | di acliate |
| | 5. Fire Safety directives letter No : | The | 24411/2010/21360 are | 06/10/2018 |
| | 6 Date of ingreation | 1-09-2013 | | |
| | 7. Name of the Inspecting Officers: Sanja | v Kumar Tomar | DO(SKY) | |
| | 8. Name and designation of officers | January, J | DO(3R V) | |
| | | r. Suresh Cr | Janas () | |
| | Voor of Court ! | Started in 20 | | |
| | 10. Applicant's letter No. : 43 | 464/7000000 | 15. (1) Dal 1 00 | las la |
| S. | Minimum Standards on fire | NBC | Provided at site | |
| ło. | | Requirement | r roymed at site | Remarks |
| 1 | Access to building | x o quit o mem | | MR/NMR |
| | | | | |
| | • Road width | 6 Mm | 12 mtr. Provided | MR |
| | • Gate width | MIA | HIA | MIA |
| | Width of internal road | HIA | H 1A | HIA |
| 2 | Number, Width, Type & Arrangement | of Exits | | |
| | a. Number of staircases | | | |
| | Upper Floors | One | TWO 85 | MR |
| | • Basements | 414 | T/A | MIA |
| | b. Width of staircases | | | . 14 |
| | Upper Floors | 1.10 m/2 | 1.10 to 1.20 mm | |
| | Basements | | Provided Organization P/A | MR |
| | c. Protection of exits | | MIA | MIA |
| | • Fire check door | N/A | N/A | N/A |
| | Pressurization | N/A | N/A | N/A |
| | e. No. of continuous staircases to terrace | N/A | N/A | N/A |
| | | One | One Provided | MR |
| | g. Width of Corridor | N/A | N/A | N/A |
| | h. Door Size | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | Compartmentation. | | | |

| | Fire check door | N/A | N/A | N/A |
|-------|---|---|------------|-----|
| | Sealing of electrical shafts | N/A | N/A | N/A |
| | Fire Rating of shaft door | N/A | N/A | N/A |
| | Water Curtain | N/A | N/A | N/A |
| | Fire Dampers | N/A | N/A | N/A |
| 4 | Smoke Management System. | | | |
| | BasementsUpper floors | 30 a/c per hour 12 a/c per hour | r/A | H/A |
| | | | N/A | N/A |
| 5 | Fire Extinguishers | | | |
| | • Total numbers | 07 | ♦ Provided | MR |
| | • Types | ABC/CA & W COL | Provided | MR |
| , | • *ĬS marking | ISI marked | Provided | MR |
| 6~ | First-Aid Hose Reels. | | | 1 1 |
| | Total numbers on each floor | One | Provided | MR |
| | Length of hose reel hose | 30 m | Provided | MR |
| | Nozzle diameter | 5 mm | Provided | MR |
| 7 | Automatic fire detection and alarming | g system. | | 8 |
| | Type of detectors | N/A | N/A | N/A |
| | Location of Main Panel | N/A | N/A | N/A |
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooters' Location | N/A | N/A | N/A |
| 8 | MOEFA | Not Pequind | Provided | MR |
| 9 | Public Address System. | HIA | HIA | MIA |
| 10 | Automatic Sprinkler System. | | | |
| | Basement | TY /A | MIA | MIA |
| 8 | • Upper Floor | N/A | N/A | N/A |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| 11 | Internal Hydrants | H 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 | <u> </u> | |
| s (8) | Size of riser/down-comer | N/A | N/A | N/A |
| | Number of hydrants per floor | | | |

| - | | | | |
|-----|---|--------------|----------|--|
| | Hose Box | N/A | N/A | N/A |
| 12 | Yard Hydrants. | | | |
| | Total number of hydrants | N/A | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 3 4 | Pumping Arrangements. | | | |
| | Ground Level | N/A | N/A | N/A |
| | Discharge of main Pump | N/A | N/A | N'A |
| | > Head of Main pump | N/A | N/A | N/A |
| | Number of main pumps | N/A | N/A | N/A |
| | > Jockey Pump out put | N/A | N/A | N/A |
| | Jockey pump head | N/A | N/A | N/A |
| | Standby Pump out put | N/A | N/A | N/A |
| | > Standby Pump Head | N/A | N/A · | N/A |
| | > Auto Starting/ Manual | N/A | | |
| | stopping | N/A | N/A | N/A |
| | Pump House Access | | N/A | N/A |
| | Terrace level | N/A | N/A | N/A |
| | Discharge of pump | 225 LPM | Provided | MR |
| | Head of the pump | 40 mm | Provided | MR |
| | Power Supply | Required | Provided | MR |
| | Auto Starting of pump | Not Required | Provided | Acceptable |
| 1 | Captive Water Storage for fire fighting. | | | |
| | Underground tank capacity | N/A | N/A | N/A |
| | Draw-off connection | N/A | N/A | N/A |
| | Fire service inlet | N/A | N/A | N/A |
| | Access to tank | N/A | N/A | N/A |
| | Overhead Tank capacity | 2500 lts | Provided | MR |
| 5 | Exit Signage, | Required | Provided | MR |
| | Provision of Lifts. | | | The second secon |
|) | | | NI/A | N/A |
| 5 | Pressurization of Lift Shaft | N/A | N/A | 14/74 |
| 6 | Pressurization of Lift ShaftPressurization of Lift lobby | N/A N/A | N/A | N/A |

Shyama Inn, 5050/12 Ist Arnoll. Metaji Subhath Many Darya Ganj

| | Fireman's Grounding Switch | N/A | N/A | N/A |
|-----|--|----------|--|-----|
| | Lift Signage | N/A | N/A | N/A |
| 17 | Standby power supply | Required | Emergency hight Provided on Inverter | MR |
| 18 | Refuge Area. | | | |
| | > Total Area | N/A | N/A | N/A |
| | > Location | N/A | N/A | N/A |
| 19. | Fire Control Room | | | |
| | Detector System Panel | N/A | N/A | N/A |
| | Flow Switch Panel | N/A | N/A | N/A |
| | PA System Panel | N/A | N/A | N/A |
| | • Batter backup | N/A | N/A | N/A |
| | Building Floor Plans | N/A | N/A | N/A |
| 20 | Special Fire Protection Systems for Protection of special Risks, if any: | Required | Fire Extinguisher Providud near Elect Panel. | MR |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to /grant / renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

25913

submitted please.

Signature of the Inspecting Officer Name: SANJAY KUMAR TOMAR

Designation :- Div. Officer