GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2014/ 5 2 / 89

Dated: 22/1/14

FIRE SAFETY CERTIFICATE

Certified that the Guest House Hilltop Palace located at C-91, Shanker Road, New Rajinder Nagar, New Delhi-110060 is comprised of Basement, ground floor plus four upper floors (Half portion of third floor i.e. 02 rooms, one store, forth floor & one temporary room on terrace has been sealed with pucca brick wall by the owner), using basement as storage, ground floor as reception, hall, office & 02 guest room, first & second floor each having 05 guest rooms and one store respectively, half portion of third floor having 03 guest rooms (Total 15 guest rooms) was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2011/252 dated 10.02.2011 owned/occupied by Sh. Surinder Singh Bakshi. The guest house building was re- inspected by the officers concerned of this department on 09.01.2014 in the presence of Sh. Gurdeep Singh (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed over leaf.

Issued on _______at New Delhi.

(DR. G.C. MISRÁ) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

ole

Copy to:-

The Joint Commissioner of Police (Lic.)
 1st floor, P.S., Defence Colony, New Delhi.
 (Re. No. 82536/Jt. C.P./Lic.(H), Dated 13.12.2013)

2. Sh. Surinder Singh Bakshi (Owner), Guest House Hilltop Palace, C-91, Shanker Rd., New Rajinder Nagar, N.D-60. Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

The second Science was the self-second	INSPEC	TION REPORT					
	 Name & address of the building: 	G.H Hinter	Palace C-ai	1 . 1 . 01			
	2. Type of Occupancy	: Residential (G)	rest barres las	hankar Ka; N			
		: Residential (Guesthouse) Rajinder Mgr. N.D.					
	4. Details of Previous NOC : Letter No. Ecla calcular visco D						
	5. Fire Safety directives letter No	: Letter No. F.G/DFS/MS/GH/2011/252 Date 10.02.2011 :					
	Date of inspection						
	7. Name of Inspecting Officer	ispecting Officer . N. C. K. Tanan 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0					
	8. Name and designation of officer:	5	198 6 14.11.0	r.S. Dahiya			
	From the building side		dool Cual 1.	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
	9. Year of Construction	Sh. Gurdeep Singh (Manager) Before 2010					
Name of Street, Street	10. Applicant's letter No.	825361 Tt. C	Pllic (H) dot	ad 10 10 0.10			
S.	Minimum Standards on fire	NBC/BBL	Provided at Remarks				
No.	prevention and fire safety U/R 33	Requirement		Remarks			
1.	Access to building	ricqui cilielli	site	MR/NMR			
	Road width	Accessible	OGMTY	MR			
	Gate width		121 cms				
	Width of internal road		121 Cms	MR			
2.	Number, Width, Type & Arrangemen						
	a. Number of staircases	t or Exits		-			
	• Upper Floors			Y Mg			
	Basements	¥-	One	MR, Being a 01			
	b. Width of staircases	-	- do -	-do-			
	Upper Floor	_	90 cms	MR, Being a Old			
	• Basements	-	90 cms	-do- !			
	c. Protection of exits			1			
	Fire check door	-	-	Special and the second			
	• pressurization						
	d. Not of continuous staircases to						
	terrace	-	One	:.			
	e. Width of Corridor						
	f. Door Size		128cms, 91cms				
2			88 cm x 204 cms	_			
3.	Compartmentation			- /-			
	Fire check door						
	Sealing of electrical shafts	*	A	- Comment			
	Fire Rating of shaft door		Sealed	Burry			
	Water Curtain		Manage				
	• Fire Dampers		and the second				
4.							
т.	Smoke Management System						
	 Basements 	30 a/c per	Exhaust fans	N 10			
	 Upper floors 	hour	are Provided	MR			
			Nortural Ventila	Kon MR			

C-91 Shankar Road, New Rajinder Ngr, N.D-60.

	4			3
	Pump House Access		_	
	Terrace level			y
	Discharge of pump	-	456 LPM	MR
	Head of the pump	-	30 M	MR
	Power Supply	-	2017	
	Auto Starting of pump		.	· · · · · · · · · · · · · · · · · · ·
14.	Captive Water Storage for fire fighting			1
	 Underground tank capacity 	•,		<u> </u>
	Draw-off connection			-
	Fire service inlet		Provided	
	Access to tank	•		
	 Overhead Tank capacity 	.	10000 Ur	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			:
	Pressurization of Lift Shaft	•	****	-
	 Pressurization of Lift lobby 	-		
	Communication In lift Car	-	Provided	- 1
	* Fireman's Grounding Switch		1001/464	0111121
	Lift Signage	Required	Provided	Old Cift MR
17.	Standby power supply	Required Required	Provided	MR
			 - - - -	9
18.	Refuge Area.			, i
	> Total Area			-
	> Location			
19.	Fire Control Room	й п		
	Detector System Panel	***	-	- 1
	Flow Switch Panel	-		
	PA System Panel			
	Batter backup	-		
	Building Floor Plans	-7		
20.	Special Fire Protection System for Protection of special Risks, if any:			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. $\underline{f \cdot 6/NFS/MS/GH/2011/2S2}$ dated $\underline{10 \cdot 02 \cdot 2011}$ renewal under rule 35 of the

Delhi Fire Service rules 2010 is recommended. Note: - 02 quest rooms with store at third floor and forth floor have been sealed by pucca bricks wall as per affidavit submitted by the owner vide No. 38 AA 025207 docted 13.12.2010.

Signature of Inspecting Officer

Name S.K. Tomar

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation ASBH. Divisional Officer