FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1)-of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

12/01/2012/02/326

Dated: 13/3/19

FIRE SAFETY CERTIFICATE

Certified that the McDonalds Family Restaurant by Connaught Plaza Restaurants Pvt. Ltd. located at Shop in Park, Plot No. 2, Ground Floor, B Block, Community Centre, Shalimar Bagh, Delhi – 110034 was issued FSC vide Letter No. F6/DFS/MS/EH/2011/288 dated 14-02-2011. The Shop in Park Mall, Shalimar Bagh has already issued FSC vide letter no. F6/DFS/MS/2011/3125 dated 23-11-2011. The premises was re inspected by the officers concerned of this department on 10-01-2014 in the presence of Mr. D N Thakur (Senior Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group for a period of three years in accordance with rule 36 unless D with effect from renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Copy to:

1. Sh. Harish Sharma (Authorised Signatory). Connaught Plaza Restaurants Pvt. Ltd., 13A, Jor Bagh Market, New Delhi - 110003.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

Name & address of the building: McDonalds Family Restaurant by Connaught Plaza
 Restaurants Pvt. Ltd., Shop in Park, Plot No. 2, Ground Floor, B Block, Community Centre,
 Shalimar Bagh, Delhi – 110034

2. Type of Occupancy

: Assembly

3. Type of Case

: Renewal (Situated in Mall already issued NOC vide letter no.

F6/DFS/MS/2011/3125 dated 23-11-2011)

4. Details of previous NOC

: Letter No. F6/DFS/MS/EH/2011/288 dated 14-02-2011

5. Fire Safety directives Letter No.: FSC Issued to the mall

6. Date of inspection

: 10-01-2014

7. Name of the Inspecting Officer: Mukesh Verma, ADO (MN)

8. Name and designation of Officer

from the building side

: Sh. D N Thakur (Senior Manager)

9. Year of Construction

: 2007

10. Applicant's letter No.

: CPRPL/FM/NOC/2013-14/A26 dated 06-11-2013

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/NMR
1.	 Access of building Road width Gate width Width of internal road 	6 m NA NA	24m Provided NA NA	MR NA NA
2.	Number, width, Type & Arrangemer	nts of exits		
	 a. Number of staircases Upper floors Basements b. Width of staircases Upper floors 	NA NA	NA NA	NA NA
		NA NA	NA NA	NA NA
	 Basements Protection of exits Fire check door Pressurization No of continuous staircase 	NA NA	NA NA NA	NA NA NA
	to terrace e. Width Of Corridor f. Door Size	NA Old Case	NA Old Case	NA Old Case
3.	Compartmentation • Fire check door	NA	NA	NA

	Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
	• Fire Dampers	NA	NA	NA			
1	Smoke managements System	The same of the sa					
1.		30 a/c per hour	NA	NA			
	Basements	12 a/c per hour	Provided	MR			
	 Upper floors 	12 a/c per nour	Tiovided	TYTE			
· .	Fire Extinguishers						
	 Total numbers 	02 nos. each type	Provided	MR			
	Types	DCP, CO2 &	Provided	MR			
	 IS marking 	WCO2					
		ISI marked	Provided	MR			
Ó.	First – Aid Hose Reels						
	 Total numbers on each floor 	1	Provided	MR			
	 Length of hose reel hose 	30 m	Provided	MR			
	 Nozzle diameter 	5 mm	Provided	MR			
7.	Automatic fire detection and alarming	g system					
	Type of detectors	Smoke	Provided	MR			
	 Location of Main Panel 	Required	Provided at GF	MR			
	Location of Repeater Panel	NA	NA	NA			
		Required	Provided	MR			
	Alternate source of power	Required	Provided at	MR			
	 Hooters' Location 	required	entrance				
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	NA	Provided	MR			
10.	Automatic Sprinkler System			* -			
10.	Basements	Not Required	NR	NR			
	Upper Floor	Required	Provided	MR			
	 Sprinkler above false ceiling 		Provided	MR ,			
1.1	Internal Hydrants: common with the			La Caracteria			
11.		150 mm	Provided	MR			
	Size of riser/down- comer	130 11111	Provided	MR			
	Number of hydrants per	1	Trovided	IVIIC			
	floor	Required	Provided	MR			
	Hose Box	Required	Trovided	TVII C			
12.	Yard Hydrants		NIA	NA			
	 Total number of hydrants 	NA	NA	Company of the compan			
	 Hose Box 	NA	NA	NA			
13.	Pumping Arrangements: Common with the mall						
	Ground Level						
	 Discharge of main pump 	NA	2280 lpm	MR			
	 Head of main pump 	NA	60m	MR			
	 Number of main pumps 	NA	2	MR			
	Jockey pump out put	NA	180 lpm	MR			
	Jockey pump head	NA	60m	MR .			
	, boeney parting			MAD			
	Standby Pump out put	NA	2280 lpm	MR			
		NA NA	2280 lpm 60m	MR			

	stopping Pump House Access	NA	Provided	MR
	ers and transport	8		
Discharge of pump	900 lpm	The Main pump provided is provided in place of terrace	MR	
			pump	MAD
	Head of the pump	40 m	-	MR
	Power supply	Required	-	MR MR
	 Auto starting of pump 	Required		MK
Government of the fighting Common with the mall				
+	 Under ground tank capacity 	NA	2.00.000 110.00	MR
	 Draw off connection 	NA	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	NA	Provided	MR
	 Overhead Tank capacity 	10, 000 litres	50, 000 Litres	MIK
			Provided	MR
	Exit Signage	Required	Provided	IVIIX
	Provision of Lifts		and the same of th	NA
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of lift lobby	NA	NA	NA
	 Communication in lift Car 	NA	NA	and the second of the second o
	Fireman's Grounding	NA	NA	NA
	Switch	NA	NA	NA
	Lift SignageStandby power supply	Required	Provided	MR
	Refuge Area		NA NA	NA
	Total area	NA	NA	NA .
	Location	NA	I INVI	
) .	Fire control room	1214	NA	NA
	 Detector system panel 	NA	NA	NA
	Flow Switch Panel PA System Panel	NA	NA	NA S
		NA	NA	NA 3-2
	Battery backup	NA	NA NA	NA NA
	 Building Floor Plans 	NA	NA	NA 197
0.	Protection of special Risks, if any			necked and found functional at

The fire protection systems provided in the building were test checked and found functional at

In view of the deemed compliance of minimum standards on fire prevention and fire safety as bequired under the rules the NOC issued vide letter no. /DFS/MS/EH/2011/288 dated 14-02-2011 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Meeting Officer

Signature of the Inspecting Officer

Mukesh reeme