GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/2014/ School / w2/536

Dated: 30/ 64/2014

FIRE SAFETY CERTIFICATE

Certified that Queen Mary's School, A-Block, Sector-25, Rohini, Delhi-110085 comprised of Ground + Three upper floors owned / occupied by Queen Mary's School has already been issued fire safety certificate vide this office letter No F.6/DFS/MS/09/295 dated 03/02/2009. The premise was re-inspected by the officer concerned and all the fire prevention & fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with Circular No F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 issued by Director of Education / NBC- Part IV and verified by the officer concerned of Fire Service on 17/04/2014 in the presence of Sh. Narender Kumar and that the building / premises is fit for occupancy of Group Class B (Educational) with effect from 30/09/2014 for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction
- 6. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Issued on 30/04/19 at New Delhi by

(SANTOKH SINGH) Chief Fire Officer Delhi Fire Service Ph: 011-23414250 cfowz.dlfire@nic.in

Copy to:

1. The Principal, Queen Mary's School, A-Block, Sector-25, Rohini, Delhi-110085

2. The Director of Education, Old Secretariat, Delhi-110054

INSPECTION REPORT

1. Name & address of the building: Queen Mary's School, A-Block, Sector-25, Rohini, Delhi-85

Type of Occupancy

: Educational

(G+3)

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/09/295 dated 03/02/2009

5. Fire Safety directives letter No : F.6/DFS/MS/BP/2002/1985 dated 18/10/2002

6. Date of inspection

: 17/04/2014

7. Name of the Inspecting Officers : DO (NW) & ADO (Rohini)

8. Name and designation of officers

from the building side

: Sh. Narender Kumar

9. Year of Construction

: 2002

10. Applicant's letter No.

: nil dated 05/03/2014

Plot area-2400 Sq.yds. Covered area-2400Sq.yds No's of student-1647 No's of class room-36

	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	Accessible	Accessible	M/R		
	Gate width	Accessible	Accessible	M/R		
	Width of internal road	(
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	01	02	M/R		
	Basements					
	b. Width of staircases					
	• Upper Floors	Old case	Old case	Old case		
	Basements		e 			
	c. Protection of exits					
	Fire check door					
	Pressurization					
	e. No. of continuous staircases to terrace					
	g. Width of Corridor					
	h. Door Size (Each class rooms having two exit doors)	1 mtr	1)1.4mtr 2)1.4 mtr	M/R		

3	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	30 a/c per hour	N/A	N/A		
	• Upper floors	12 a/c per hour	N/A	N/A		
5	Fire Extinguishers					
	Total numbers	15	30	M/R		
	• Types		ABC	M/R		
	IS marking	ISI marked	Yes	M/R	_	
6	First-Aid Hose Reels.					
	Total numbers on each floor	One at each floor	04	M/R		
	Length of hose reel hose	30 m	Yes	M/R	/	
	Nozzle diameter	5 mm	Yes	M/R		
7	Automatic fire detection and alarming system.					
	Type of detectors					
	Location of Main Panel	GF N/R	P	N/R		
	Location of Repeater Panel					
	Alternate source of power	N/R	P	N/R		
	Hooters' Location	N/R	P	N/R		
8	MOEFA	N/A	N/A	N/A		
9	Public Address System.	N/R	P	M/R		
10	Automatic Sprinkler System.					
	Basement	N/A	N/A	N/A		
	• Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer					
	Number of hydrants per floor	N/R	P	N/R		
	Hose Box	N/R	P	N/R		

12	Yard Hydrants.			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.			
	Ground Level		5	
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	225 LPM	P	M/R
	> Jockey pump head	40 m	P	M/R
	> Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/ Manual stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pumpHead of the pump	450 LPM	P	M/R ^
		40 m	P	M/R
	> Power Supply		,	
14	Auto Starting of pump			
	Captive Water Storage for fire fighting.	50,000 1		
	Underground tank capacity	50,000 ltr	P	M/R
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10,000 ltr	10,000 ltr	M/R -
15	Exit Signage.	R	P	M/R
6	Provision of Lifts.	٠,		
	Pressurization of Lift Shaft	N/A/M	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A

18	Refuge Area.			
	Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/09/295 dated 03/02/2009 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name

N-f. Sharms

Designation

ADO R

17-14-14

Signature of the Inspecting Officer

Name

Designation