

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/MS/DFS/EH/2015/52/163

Dated: 05/02/15

FIRE SAFETY CERTIFICATE

Certified that the Yeti The Himalayan Kitchen Bunmanchi (a unit of Yeti group), running at ground, mezzanine, first & second floor of a building comprised of basement, ground, mezzanine + 02 upper floors, located at M-20, Greater Kailash, Part-II, M-Block Market, New Delhi-110048 owned/occupied by a unit of Yeti group. The premises was inspected by the officer concerned of this department on 28/01/2015 in the presence of Mr. Prem Prakash (Accounts Manager) and found that the said restaurant have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group – D (Assembly Building) with effect from 05/02/15 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued ---05/02/15---at New Delhi by,


(Dr. G.C. Misra)
Chief Fire Officer
Tel: 011-23414333



Copy to: -

(1) The Dy. Health Officer,
SDMC, South Zone,
Aurobindo Marg, Green Park
New Delhi

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of NBC
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:- Yeti The Himalayan Kitchen Bunmanchi, M-20, GF, Mezzanine, FF, SF, Greater Kailash –II Market, New Delhi
2. Type of occupancy:- Group – D, Assembly Building, (Restaurant)
3. Type of case:- New
4. Details of previous NOC:- Nil
5. Fire safety directives No.- Nil
6. Date of inspection:- 28/01/2015
7. Name of the inspecting officer:- D.B.Mukherjee, A.D.O.(BCP)
8. Name & designation of officer From the building side:- Mr. Prem Prakash (Accounts Manager)
9. Year of construction:- 2000
10. Applicant's letter No:- DHO/SZ/2014/D/359, dated 16/05/2014 and party letter no. Nil dated Nil
Building is comprised of basement, ground + mezzanine + first & second upper floors. restaurant is running in ground, mezzanine, first floor & second floor.

Sl. No.	Minimum Standards on Fire Prevention and Fire Safety U/R 33	Requirement NBC	Provided at Site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	09 m	Provided	MR
	2) Gate width	Abuts on road	Approachable	MR
	3) Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrangement of Exits:			
	A. Number of staircases			
	1. Upper floors	02	Provided	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	1.5mtrs	1.5 mtrs & 1mtr	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	Required	Provided	MR
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01no	Provided	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	2 mtrs.	Provided in all floors	MR
3.	Compartmentation			
	1) Fire check door	Required	Provided	MR
	2) Sealing of electrical shafts	Required	Provided	MR
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 a/c per hour	N/A	N/A
	2) Upper floors	12 a/c per hour	Provided exhaust fans	MR
5.	Fire Extinguishers			
	1) Total numbers	ISI Marked	12 Nos.	MR
	2) Types		ABC, Co2, Foam	MR
	3) ISI marking		Yes	MR
6.	First-Aid Hose Reel			
	1) Total number of each floor	Required	Provided 01nos	MR
	2) Length of hose reel hose	30 mm	Provided	MR
	3) Nozzle diameter	5 mm	Provided	MR

7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	Required	Provided	MR
	2) Location of main panel	Required	Ground Floor	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Every Floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	Not Required	Provided in all floors	M/R
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 mm	Provided	MR
	2) Number of hydrants per floor	01no.	Provided	MR
	3) Hose box	Required	Provided	MR
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level			
	a) Discharge of main pump	2280 LPM	Provided	MR
	b) Head of main pump	70 mtrs	Provided	MR
	c) Number of main pump	01no	Provided	MR
	d) Jockey pump out put	180 LPM	Provided	MR
	e) Jockey pump head	70 mtrs	Provided	MR
	f) Stand by pump output	2280 LPM	Provided	MR
	g) Stand by pump head	70 mtrs.	Provided	MR
	h) Auto starting/Manual stopping	Required	Provided	MR
	2) Terrace level			
	a) Discharge of pump	900 LPM	Provided	MR
	b) Head of pump	70 mtrs.	Provided	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fire Fighting			
	1) Under ground tank capacity	50,000 ltrs.	Provided	MR
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	5,000 Ltrs.	10000 ltrs. Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided DG set	MR
18.	Refuge Area			
	Total area location	N/A	N/A	N/A

19.	Fire Control Room			
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection system provided in the restaurant were checked and found functional at the time of inspection. The shortcomings issued vide letter no.F6/DFS/MS/EH/2014/1785 dated:08/08/2014 have been rectified.

Keeping in view of substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010. Accordingly DFA is prepared and put up for perusal and sign please.

D.B. Mukherjee
29/11/15

Signature of the inspecting officer

Name :- D.B. Mukherjee.

Designation :- Assitt. Div. Officer(BCP).