GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2015/ 22 / 492

Dated: 07/09/15

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Avantika Inn** located at 11/23, East Patel Nagar, New Delhi-110008 is comprised of Ground Floor plus three upper floors, using ground floor as reception, office & shops, first & second floor each having 08 guest rooms respectively, third floor having 04 guest rooms (Total 20 guest rooms) was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2012/1867 dated 23.05.2012 owned/occupied by Sh. Shamsher Sethi. The guest house building was re-inspected by the officers concerned of this department on 23.03.2015 in the presence of Sh. Shamsher Sethi and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE
Ph:- 011-23414333

Copy to:-

- 1. The Joint Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No.3805/Joint C.P./Lic.(H), Dated 24.02.2015)
- 2. Sh. Shamsher Sethi (Owner) Hotel Avantika Inn, 11/23, East Patel Nagar, New Delhi-08.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	INSPE	CTION REPORT		and an income of the same and the same of			
	1. Name & address of the building	Hatel Aver 1"	Les transition of the second				
	 Name & address of the building: Hotel Avantika Inn, 11/23. East Pate Type of Occupancy : Residential (Guest House) 						
	3. Type of Case	: New Case/Rene	CILIPAL MOMAR	0			
	A D-1 11 5-	ewal					
	5. Fire Safety directives letter No : Letter No. 66/DFS/MS/GH/2012/1867 Date						
	6. Date of inspection	23.03.2015					
	7. Name of Inspecting Officer						
	8. Name and designation of officer.						
	From the building side						
	9 Variation of the Olohan						
	10 0	Before 19	Before 1993				
S.	10. Applicant's letter No.	3805/ Joint	C.P/LIC.CH)	dated 96. Ag. 9			
No.		NBC/BBL	Provided at	Remarks			
1.	prevention and fire safety U/R 33	Requirement	site	MR/NMR			
Ł.	Access to building			I MINIMALK			
	 Road width 	Accessible	18 mtr	MO			
	Gate width	4	210 cms	MR			
	· Width of internal road/Side Roa	J		MR			
2.	Number, Width, Type & Arrangement		0.5 mtr	MR			
	a. Number of staircases	OFEXITS	1	•			
	• Upper Floors						
	· 11	One	One	MR			
	 Basements Width of staircases 			No Basemen			
			The second secon	1 NO Busemen			
	Upper Floor	125cms	125cms	000			
	• Basements	111/3	TAS CMS	MR			
	c. Protection of exits			No Bosement			
	 Fire check door pressurization d. No. of continuous staircases to terrace 		The discount age on marketing affices and marketing on my three sections of general framework has the	1			
				And the second s			
			Annual Annual State of the Stat				
	e. Width of Corridor		One				
	f. Door Size		105 cms, 220 cms				
				and the same of th			
	Compartmentation		85 cms x 195 cms	- The second section is a second seco			
	Fire check door						
			Specimentum	Charles a Control of the Control of			
	 Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 		Contra	The state of the s			
			Sealed				
- Control of the Cont				•			
		Ballion and the second					
•	Smoke Management System			Andrew Control of the			
			2 1				
	* Basements	30 a/c per	the billion of the best of the	No Basement			
1	 Upper floors 			I h h /I			

	N118			-
		12 a/c per hour		
5.	Fire Extinguishers			
	 Total numbers 	Two at each Flow	* 0	
	Types	Co, Wlo, Foam	120Vided	MR
	IS marking	ISI marked	- do 7	MR
6.	First-Aid Hose Reels		131 Marked	MR
	 Total numbers on each floor 	One	Panilal	b 0
	 Length of hose reel hose 	30 m	- do -	MR
	 Nozzle diameter 	5 mm	- do =	MR
7.	Automatic fire detection and alarming	system	1 - 00:	I MR
	 Type of detectors 	•		
1	 Location of Main Panel 	_		
	 Location of Repeater Panel 			
	 Alternate source of power 			
B.C	 Hooters' Location 			
8.	MOEFA	Required	Provided	MR
9.	Public Address System	- do -	- do -	MR
10.	Automätic Sprinkler System	1		
	• Basement		- ;	No Basement
	 Upper Floor 			- Justinenc
4.4	 Sprinkler above false ceiling 			
11.	Internal Hydrants			
	 Size of riser/down-comer 			
	 Number of hydrants per floor 			7
17	Hose Box			
12.	Yard Hydrants		J.	3
	Total number of hydrantsHose Box			
13.	Pumping Arrangements			
	Ground Level			
			*	
		_	-	
	- said Be of main famp			
	Head of Main pump			
	Head of Main pumpNumber of main pumps			
1	Head of Main pumpNumber of main pumps			
5	 Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put 	-		
20	 Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head 			
	 Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put 			
	 Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head 			

to

M/19. 11/23, East Patel Magar, New Delli-110008.

	> Pump House Access			
	Terrace level			
	Discharge of pump	450 LPM	450LPM	MR
	Head of the pump	30M Required	30 M Paovided	MR MR
	> Power Supply	Required	Provided	MR
	> Auto Starting of pump			
L4.	Captive Water Storage for fire fighting			1
	 Underground tank capacity 		_	
	Draw-off connection			•
	Fire service inlet		- Camanana	
	Access to tank	~		-
	Overhead Tank capacity		3000 Ltr	MR, Old Co
15.	Exit Signage.	Required	Provided	MR
13.				
16.	Provision of Lifts.			
	 Pressurization of Lift Shaft 			**************************************
	 Pressurization of Lift lobby 	-		
	Communication In lift Car	-	Provided	MR
	 * Fireman's Grounding Switch 			Old Lift
	Lift Signage		Provided	MR
17.	Standby power supply	Required	D.G. Set of 30 KVA	MR
18.	Refuge Area.			
	Total Area	-		
	> Location		-	
19.	Fire Control Room			*
201	Detector System Panel			
	Flow Switch Panel	-		-
	PA System PanelBatter backup	ii.	-	Characteristics
	 Building Floor Plans 	×		8
20.	Special Fire Protection System for Protection of special Risks, if any:		4	_

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS GH 2012 1867 dated 23.05.2012 renewal under rule 35 of the

Signature of Inspecting Officer

Name S. K. Tomas

Designation Divisional Officer

Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Name P.S. Dahiya

Designation Asstt. Divisional Officer