## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/EH/2015/ 5 2 / 630

Dated: 28/04/15

## **FIRE SAFETY CERTIFICATE**

Pvt. Ltd.) located at First Floor, Shop No. 163-164 & 165, Rajendra Bhawan, Rajendra Place, New Delhi-110008. The Rajendra Bhawan building is comprised of Basement, ground floor plus four upper floors. The restaurant building is comprised of basement, ground floor plus one upper floor but the restaurant is running at First floor only owned/occupied by Sh. Devenderjit Singh Sahni (Director). The Restaurant building was inspected by the officers concerned of this department on 22.04.2015 in the presence of Sh. Devenderjit Singh Sahni (Director) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Restaurant area at First Floor Only) is fit for occupancy class Group D Assembly Building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on... 2-2./.0.4.//. at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

- The Dy. Health Officer, North Delhi Municipal Corporation, Karol Bagh Zone, New Delhi-110005. (Ref. No. DHO/KBZ/2015/2824 dated 27.03.2015)
- 2. Sh. Devenderjit Singh Sahni (Director), M/s Lanterns Restaurant (A unit of Marks Tours & Travels Pvt. Ltd.), 163-164 & 165, Rajendra Bhawan, Rajendra Place, New Delhi-08.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.

5. The certificate may not be treated in any case for regularization of

unauthorized construction, if any.

6. The basement shall be used strictly as per the provisions of the building bye laws.

7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this

Certificate, six months prior to its expiry.

	INSPEC	TION REPORT						
	1. Name & address of the building: M/C/Outcome Oc.							
	1. Name & address of the building: M/S Lanterns Restaurant, Shop No. 163, 164 \$ 165 K  2. Type of Occupancy  Assembly (Restaurant)							
	or Table of Case	Assembly (Restaurant) Bhawan Rajindra Pl New Case/Renewal N.D-08						
	4. Details of Previous NOC	· latter Ne						
	5. Fire Safety directives letter No.	Date						
	<ol> <li>b. Date of inspection .</li> </ol>	Λ.Δ.						
	7. Name of Inspecting Officer	Officer 1.0 C V To 2015						
	8. Name and designation of officers	me and designation of officers						
	krom th - 1 11 11							
	9. Year of Construction .	on 1999 1994						
	10. Applicant's letter No.							
S.	Minimum Standards on fire	NBC/BBL	03.2013 & DHO/K					
No.	prevention and fire safety U/R 33	1	Provided at	Remarks				
1.	Access to building	Requirement	site	MR/NMR				
	Road width	Accessible	10.	:				
	Gate width	riccosine	18 mds	MR				
	Width of internal road Side Road	A .	213 cms, 05 mt	r MR				
2.	Number, Width, Type & Arrangement		06 mtr	MR				
The second second	a. Number of staircases	of Exits						
	• Upper Floors							
	Basements	Two	Two	MR				
	b. Width of staircases	- do -	- do -	MR				
	1 11			<u> </u>				
	Upper Floor     Page 1	02 mts	12 mts, 2.40 mtr	ha O				
	Basements	- do -		MR				
	c. Protection of exits		06 mts 02 mts	MR				
	<ul> <li>Fire check door</li> </ul>	•						
	• pressurization							
	d. No. of continuous staircases to			-				
	terrace		4					
	e. Width of Corridor		One					
	f. Door Size		03mts	_				
3.	Cdhantu		213 cms, 122 cms					
	Compartmentation							
	Fire check door							
	<ul> <li>Sealing of electrical shafts</li> </ul>		•					
	• Fire Rating of shaft door	-	Sealed					
	Water Curtain							
	• Fire Dampers	_						
1.								
-	Smoke Management System							
	Basements	30 a/c per	Exhaust Fons					
:	<ul> <li>Upper floors</li> </ul>	hour	are Provided	MR				
			latural Ventilation					

( No

	N/4.	200		
		12 a/c per hour		
5.	Fire Extinguishers			_0
	<ul> <li>Total numbers</li> </ul>	OG Nos	0	
	<ul><li>Types</li></ul>	ABC,	Provided	MR
	<ul> <li>IS marking</li> </ul>	ISI marked	- do -	MR
6.	First-Aid Hose Reels		1SI Marked	MR
	<ul> <li>Total numbers on each floor</li> </ul>	One	Pill	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided - do -	MR
	Nozzle diameter	5 mm	- de 2	MR
7.	Automatic fire detection and alarming	system	- ae +	I. MR
	<ul> <li>Type of detectors</li> </ul>			T
	<ul> <li>Location of Main Panel</li> </ul>			+
	<ul> <li>Location of Repeater Panel</li> </ul>			
	<ul> <li>Alternate source of power</li> </ul>			+
	<ul> <li>Hooters' Location</li> </ul>			
8.	MOEFA	Required	P	+
9,	Public Address System	Regleired	Provided	MR
10.	Automätic Sprinkler System	requirea	Provided	MR
	• Basement	Required	Provided	MR
	· Upper Floor/Restaurant Area	- do-	-do-	
	<ul> <li>Sprinkler above false ceiling</li> </ul>		1	MR
11.	Internal Hydrants	11		
	<ul> <li>Size of riser/down-comer</li> </ul>	100m.m	100 M.M.	100
	<ul> <li>Number of hydrants per floor</li> </ul>	One	One	MR
4.2	• Hose Box	- do -	= do -	MR
12.	Yard Hydrants		1	MR
	<ul> <li>Total number of hydrants</li> </ul>	One	One	MR
13.	* Hose Box	~	-	
٠,٠	Pumping Arrangements			
	• Ground Level  Discharge of main Duran			
	o is charge of main Pump	~		
	rieda or iviani pullip		-	
2	<ul><li>Number of main pumps</li><li>Jockey Pump out put</li></ul>	-		. ~
district in the second	> Jockey pump head		-,	
	<ul><li>Standby Pump out put</li></ul>			
Total Control	> Standby Pump Head			
and the second	Auto Starting/Manual	-	p.i.	
# HO	stopping	-	-	
		-		-
	The state of the s			~

NIS Rajindra Place, New Delli - 110008.

_	The state of the s			}			
-	Pump House Access		-				
	Terrace level			3 7			
	Discharge of pump	450 LPM	450 LPM	(Acc)			
	Head of the pump	1		MR			
	Power Supply	30 M Required	30M Provided	MR			
	Auto Starting of pump		- I source	MR			
14.	Captive Water Storage for fire fightin	g	8				
	<ul> <li>Underground tank capacity</li> </ul>						
	Draw-off connection						
	Fire service inlet		ρ				
	Access to tank		Provided	MR			
	Overhead Tank capacity						
		10000 Ur	10000 Ctr	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.		* ****				
	Pressurization of Lift Shaft			61. 1.01			
	<ul> <li>Pressurization of Lift lobby</li> </ul>			No loft			
	Communication In lift Car			-do-			
	• * Fireman's Grounding Switch			-do -			
	Lift Signage			-do -			
	Life Signage	-	7	-do -			
17.	Standby power supply	Required	D.G.Set of 75 KVA	MR			
18.	Defuse Assa			· · · · · · · · · · · · · · · · · · ·			
10.	Refuge Area.		T				
	> Total Area	-	-				
	Location						
10	Fire Control Room						
19.	Detector System Panel	T					
	Flow Switch Panel		-				
	PA System Panel						
	Batter backup			:			
	Building Floor Plans		_				
	Sanding (100) (101)			8			
20.	Special Fire Protection System for Protection of special Risks, if any:						

The fire protection systems provided in the building were test checked and found functional the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers. The Rejector Bhawan beilding is Comprised of G.F plus of capper floors. The Restaurant premises (Shop No. 163-164 \$ 165) is comprised of Basement, G.F plus of Lepper floor, but the restaurant is running at first floor with two staircases of width 12 mts & 2.40 mtr respectively. The basement having seprate entry & exitstee Restaurant having O'H tank of Cap. 10000 Ctr, Firefump of 450 LPM discharge with some Head, Down Comer, Sprinkler, Hose Reel, MOEFA, P.A System, Exit sign etc. seprately. The Kitchen having two exits. The exhaust ducts are provided for proper ventilation.

Signature of Inspecting Officer

Name S. K. Tomar

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation Aggtt. Divisional Officer