GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

No. 66/DFS/MS/school/2015/32/1126 Dated: 01/07/15

FIRE SAFETY CERTIFICATE

Certified that Global Scholars Academy located at L^{1st}, Main Bandh Road, Sangam Vihar, New Delhi- 110062 comprised of ground floor only was inspected by the officer concerned of this department on 16.06.2015 in presence of Mr. Mehtab Siwas, manager of the Academy and observed that the school building have complied with the fire prevention and fire safety requirements in accordance with the Directorate of Education circular No. F.6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the under mentioned conditions.

Issued on -01/07/11—at New Delhi by.

(Dr. G.C. MISRA) CHIEF FIRE OFFICER

Copy to: -

- 1. The Manager, Global Scholars Academy, L^{Ist}, Main Bandh Road, Sangam Vihar, New Delhi- 110062
- 2. The Directorate of Education, Old Secretariat, New Delhi-110006.

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Global Scholars Academy, L^{lst}, Main Bandh Road, Sangam

Vihar, New Delhi- 110062

1. Type of Occupancy

: Educational

2. Type of Case

: New Case

3. Details of previous NOC

: N/A

4. Fire Safety directives letter No : Directorate of Education circular No. F.16/Estate/CC/Fire

4

Safety/2011/3298 to 3398 dated 01-03-2011.

5. Date of inspection

: 16.06.2015

6. Name of the Inspecting Officers : M.K.Chattopadhyay, ADO(M.Rd)

7. Name and designation of officers

from the building side

: Mr. Mehtab Siwas, manager

9. Year of Construction

: 2014

10. Applicant's letter No.

: TGSA/FIRE/2015 dated 03.06.2015.

Global Scholars Academy is comprised of ground floor only.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	06 mts	Provided	MR		
	Gate width	4.5 mts	Provided	MR		
	 Width of internal road 	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	• Upper Floors	Ground floor only				
	 Basements 	N/A	N/A	N/A		
	b. Width of staircases					
	• Upper Floors	Ground floor only				
	• Basements	N/A	N/A	N/A		
	c. Protection of exits					
	• Fire check door	N/A	N/A	N/A		
	 Pressurization 	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	N/A	N/A	N/A		
	g. Width of Corridor	1.5 mts	Provided	MR		
	h. Door Size	1.0 mts	Provided	MR		

	Compartmentation.			,		
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire Rating of shaft door 	N/A	N/A	N/A		
,	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
	Smoke Management System.					
		30 a/c per hour	N/A	N/A		
	Basements Light Garage	12 a/c per hour	N/A	N/A		
	Upper floors	•				
5	Fire Extinguishers	03 nos.	Provided	MR		
	Total numbers Tagget	ABC type	Provided	MR		
	• Types	ISI marked	Provided	MR		
	IS marking First-Aid Hose Reels.					
6	The larger and floor		N/A	N/A		
		30 m	N/A	N/A N/A		
	Length of hose reel hoseNozzle diameter	5 mm	N/A	IN/A		
7	Nozzle diameter Automatic fire detection and alarming system Not required					
1		N/A .	N/A	N/A		
	Type of detectorsLocation of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	N/A	N/A	N/A		
9		N/A	Provoded			
10	Public Address System.					
10	Basement	N/A	N/A	N/A		
	• Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
-	Size of riser/down-comer	N/A	N/A	N/A		

*	• Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
12	Yard Hydrants.				
	 Total number of hydrants 	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A	
3		N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A		
	Auto Starting/ Manual	N/A		N/A	
ø	stopping Pump House Access	7	N/A	N/A	
		N/A	N/A	N/A	
	Terrace level				
	 Discharge of pump Head of the pump Power Supply Auto Starting of pump 	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
14		N/A	N/A	N/A	
1 1	Captive Water Storage for fire fighting				
	Underground tank capacity	N/A	N/A	N/A	
	Draw-off connectionFire service inlet	N/A	N/A	N/A	
	Fire service inletAccess to tank	N/A	N/A	N/A	
	Overhead Tank capacity	N/A	N/A	N/A	
	Overhead Fank Capacity	N/A	N/A	N/A	
15	Exit Signage.	N/A	N/A	N/A	
16	Provision of Lifts. Not Applicable				
	 Pressurization of Lift Shaft 	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	

	Communication In lift Car	N/A	N/A	N/A
	 Communication in int Car Fireman's Grounding Switch 	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.		2	*
10	Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
17	Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	D. M. Flagge Dlong	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	01 CO ₂ type fire extinguisher is provided near elect. Panel.	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011.

DFA is put up for approval & signature please

DCFO(SK) MAS

Signature of the Inspecting Officer
Name (M.K. CHATTOPADHYAY)
Designation: - Assistant Divisional Officer