GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2015/ 12 /1086

Dated: 26/06/15

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Rijak Continental** located at 12A/14, WEA, Saraswati Marg, Karol Bagh, New Delhi-110005 is comprised of Basement, Ground Floor plus four upper floors, using basement as Gym Khanna, ground floor as reception & shops, first, second & third floor each having 09 guest rooms respectively (Total 27 guest rooms) and one staff room with pantry for staff on fourth floor was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2012/2338 dated 29.06.2012 owned/ occupied by Sh. Manjeet Singh. The guest house building was re- inspected by the officers concerned of this department on 13.06.2015 in the presence of Sh. Veera Kumar (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 2.6. $\frac{1}{2}$. $\frac{1}{2}$. at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph. 011-23414333

Copy to:-

- 1. The Joint Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No.346/Joint C.P./Lic.(H), Dated 19.05.2015)
- 2. Sh. Manjeet Singh (Owner) Hotel Rijak Continental, 12A/14, WEA, Saraswati Marg, Karol Bagh, N.D-110005.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The basement shall be used strictly as per the provisions of the building bye laws.
- 7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Natural Ventilation

MR

1	N/14.		e	· ·			
		12 a/c per					
and an area of the second		hour	-				
5:	Fire Extinguishers						
J	• Total numbers	Two at each floor					
	Total numbersTypes	Co, WCo2	1 Dovided	MR			
	IS marking	ISI marked	-dg-	MR			
6,	First-Aid Hose Reels	131 marked	1SI Marked	MR			
· · · · · · · · · · · · · · · · · · ·	Total numbers on each floor						
		One	Provided	MR			
	Length of hose reel hoseNozzle diameter	30 m	-do-	MR			
7.		5 mm	- do'-	L: MR			
<i>f</i> .	Automatic fire detection and alarming system						
1	 Type of detectors 		Same American	1			
7)	 Location of Main Panel 	-					
	 Location of Repeater Panel 	-					
	 Alternate source of power 	_					
	 Hooters' Location 						
8.	MOEFA	Required	Provided	MR			
9,	Public Address System	- do -	-do-	MR			
10.	Automätic Sprinkler System						
	 Basement 	Required	Provided	MRI			
	 Upper Floor 	/ - '					
	 Sprinkler above false ceiling 						
11.	Internal Hydrants						
	 Size of riser/down-comer 	-					
	 Number of hydrants per floor 			5			
	 Hose Box 						
12.	Yard Hydrants		J.				
	 Total number of hydrants 						
	* Hose Box		•				
13.	Pumping Arrangements		8				
	 Ground Level 		*	:			
	Discharge of main Pump	_	_				
	Head of Main pump			·			
	> Number of main pumps						
	> Jockey Pump out put						
	Jockey pump headStandby Pump out put		Name of the latest and the latest an				
	see and the compact par						
P or or Superior		•	i.	-			
	Auto Starting/Manual stopping						
	srobbing						
To a manage approximation	distance of the second						



MIS Karol Bagh, New Delli-110005.

					ĺ			
	Pump House Access		_	~	420			
	Terrace level				-			
	Discharge of pump		450 LPM	MR, Old	0			
	> Head of the pump		1	- do -				
	Power Supply	Required	30 M Provided	MR	(87)			
***************************************	Auto Starting of pump			orporation to the same of the				
14.	Captive Water Storage for fire fighting							
	 Underground tank capacity 							
	Draw-off connection	Philippe		-				
	Fire service inlet		Provided	MR				
	Access to tank							
	Overhead Tank capacity	Manage Control of the	Scoo Ltr	MR, Old	Co			
l5.	Exit Signage.	Required	Provided	MR	0 1			
16.	Provision of Lifts.				8			
	Pressurization of Lift Shaft				3			
	Pressurization of Lift lobby				7			
	Communication In lift Car	~			_			
	• * Fireman's Grounding Switch		Provided	MR	1			
	Lift Signage	Required	-do-	MR				
		-do-	-do -	MR				
17.	Standby power supply	Required	D. G. Set of 62.5 Kup	MR	!			
18.	Refuge Area.							
I.	Total Area				1			
	> Location							
0	Fire Control Room				-			
19.	Detector System Panel							
	Flow Switch Panel				1			
	PA System Panel				-			
	Batter backupBuilding Floor Plans							
			Provided	MR				
20.	Special Fire Protection System for Protection of special Risks, if any:	-	_					
		*	De la constant de la					

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6|DFS|MS|GH|2012| 2338 dated 29.06.2012 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Name S. K. Tomar

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation ASBH, Divisional Officer