GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2015/ NO2/1820

Dated : 08/10/15

FIRE SAFETY CERTIFICATE

Certified that the "SudershanPalace" Guest House located at 8189/6, Multani Dhanda, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (reception), 1st floor to 3rd floor (04 guest rooms at each floor) and 4th floor (01 guest room + kitchen for staff), total 13 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2012/2429 dated 06/07/12. The premises was re-inspected by the officer concerned of this department on 27/09/15 in the presence of Sh. Balraj (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010, and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 13 guest rooms only with effect from -- 29-1-0-1-5---- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -09-/10-/15----at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Ph-011-23414333

Copy to:-

- opy to:
 The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi
- 2. Sh. Balraj (Manager),

"SudershanPalace" Guest House 8189/6, Multani Dhanda, Pahar Ganj, New Delhi Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

Name	Name & address of the building "SudershanPalace" Guest House located at 8189/6, Multani Dhanda, Pahar Ganj, New Delhi						
2							
۷.	Residential, Sub Division-A-1 Gr. + 04 Upper floors (total 13 Guest rooms)						
3.	Type of case:-	Renewal					
	Details of previous FSC:-	No. F6/DFS/MS/GH/2012/2429 dated					
		06/07/12.					
5.							
6.	Date of inspection:- 27/09/15						
7.	 Name of the inspecting officer:- Name & designation of officer From the building side:- Sh. Manoj Kumar Sharma (ADO/CC) Sh. Balraj (Manager) 						
8.							
	Year of construction:-	1999		20/15			
10	. Applicant's letter No:-	lo. 1311 Joint Ch	P/Lic.(H) dated 20/0				
			T	Old Case			
S.No.	Minimum Standards on fire	Requirement	Provided at site	Remarks			
	Prevention and fire safety	Existing	PSS	MR/NMR			
	U/R 33						
1.	Access to Building	127/1	106) MD			
	1) Road width	N/A	06 mtr.	MR			
	2) Gate width	N/A	N/A	N/A			
	3) Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Ari	rangement of Ex	kits				
	A. Number of staircases						
	1. Upper floors	01 Nos.	01 Nos.	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	0.80 mtr.	1.00 mtr.	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous	01	01	MR			
	staircase to terrace						
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	1 mtr.	1 mtr.	MR			
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	1) Basements	30 ACPH	N/A	N/A			
	2) Upper floors	12 a/c per hour	Natural Ventilation	MR			
5.	Fire Extinguishers	****					

	1) Total numbers	08 Nos.	08 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
	First-Aid Hose Reel			
6.	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
•	Automatic Fire Detection &		em	
•	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
	MOEFA	NA	NA	NA
•		NA	Provided	MR
	Public Address System		1101100	
0.	Automatic Sprinkler System 1) Basement	N/A	N/A	N/A
		N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	IN/A	11/12	
	ceiling			
11.	Internal Hydrants	N/A	N/A	N/A
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	IN/A	14/14	
	floor	N/A	N/A	N/A
	3) Hose box	IN/A	14/11	
12.	Yard Hydrants	N/A	N/A	N/A
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	IN/A	IN/A	1 1/2 2
13.	Pumping Arrangement	NI/A	N/A	N/A
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	IN/A	IVIX
	pump	27/4	N/A	N/A
	b) Head of main pump	N/A		N/A
	c) Number of main pum		N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A N/A
	f) Stand by pump outpu		N/A	N/A N/A
	g) Stand by pump head	N/A	N/A	N/A N/A
	h) Auto starting/Manual	N/A	N/A	IN/A
	stopping			
	2) Terrace level	2007 73.6	225 I DM	MR
	a) Discharge of pump	225LPM	225 LPM	MR
	b) Head of pump	18 mtr.	18 mtr.	
	c) Power supply	Required	Provided	MR
	d) Auto starting of pum	p Required	Provided	MR
14.	Captive Water Storage for	Fire Fighting		NT/A
2	1) Under ground tank	N/A	N/A	N/A
	capacity			

	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
I.SL.	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
,	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter No. F6/DFS/MS/GH/2015/1719 dated 31/07/2015 have been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2012/2429 dated 06/07/2012 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

PATE SEPTION