GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. FG/DFS/MS/EH/2015/NED2/1946

Dated 29/10/15

FIRE SAFETY CERTIFICATE

Certified that the Haldiram Restaurant at upper ground floor of building comprised of Lower basement, upper basement, lower ground & upper ground floor at Akshardham Metro Station, Delhi, owned/occupied by M/s Haldiram Ethnic Food Pvt Ltd, have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on dated 20.10.15 in the presence of Sh. Pardeep Kumar Sharma (Manager) and found that upper ground floor of building is fit for occupancy class "(Assembly Building)" with effect from ... 29/1.2/... for a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service Ph -01 | -23414333

ZO ZOXI'

To

The Dy.Health Officer
East Delhi Municipal Corporation
Health Department, Karkardooma,
South Zone, Shahdara, Delhi.

Copy to:-

M/s Haldiram Ethnic Food Pvt.Ltd H-154,Sector-63,Noida,UP-201307

Conditions

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 6 This FSC may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building: Haldiram Restaurant at Commercial building, Metro Station Akshardham, Delhi. 2. Building is comprised of : Upper ground floor. 3. Type of Occupancy : Restaurant (Assembly) 4. Type of Case : New Case : F.6/DFS/MS/2015/NDZ/1686 dated 15/09.15 for 5. Details of Previous FSC commercial/PDP area 6. Fire Safety direction letter No: F.6/DFS/MS/BP/2008/1226 dated 29.04.2008 for commercial/PDP area 7. Date of Inspection :20.10.2015 8. Name of the Inspecting officers: DO Virendra Singh & ADO Suresh Singh 9. Name and designation of Officer from the building side :Sh.Pardeep KumarSharma (Manager) 10. Year of Construction :2008 :Nil dated 09.10.15 11. Applicant's letter No Provided at Site Minimum Standards on fire prevention NBC/BBL Remarks S.NO. and fire safety U/R33 Requirement MR/NMR 16 Mtrs. MR Road width 12 Mtrs. 1 Gate width 4.5 Mtrs. 6 Mtrs. MR Width of internal road 6 Mtrs. 6 Mtrs. MR 2 Number, Width, Type and Arrangement of Exits a. Number of Staircases 7 nos. 7 nos. MR **Upper Floor** 7 nos. 7 nos.+2 ramp MR Basement B. Width of Staircases MR **Upper Floor** 1.20 & 1.5 M 1.20,1.5,2.5 M 1.20 & 1.5 M 1.20,1.5,2.5 M MR Basement c. Protection of exits Provided MR Fire check door Required Pressurization N/A N/A N/A N/A e. No. of continuous staircases to terrace N/A N/A g. Width of Corridor N/A N/A N/A h. Door Size 2.0 M 2.0 M MR Compartmentation. 3 MR Required Provided Fire check door MR Required Sealed Sealing of electrical shafts N/A N/A N/A Fire rating of shaft door Water curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System. N/A N/A N/A Basement Provided MR Required Upper floor 5. Fire Extinguisher 05 Nos. 07 nos. MR Total numbers ABC & Co2 MR ABC & Co2 Types ISI marked ISI marked MR IS marking First-aid-Hose Reels. 6 02 nos. MR 02 nos.

30 m

5 mm

30 m

5 mm

MR

MR

Total numbers of each floor

Length of hose reel hose

Nozzle diameter

11/2

7	Automatic fire detection and alarming system.				
	Type of detectors	N/A	Smoke	MR	
	 Location of main panel 	N/A	Provided	MR	
	 Location of repeater panel 	N/A	Provided	MR	
	 Alternate source of power 	N/A	Provided	MR	
-1	Hooter's location	N/A	Provided	MR	
8	MOEFA	Required	Provided	MR	
9	Public address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System.			1.77.	
	Basement	N/A	N/A	N/A	
	upper floor	Required	Provided	MR	
	sprinkler above false ceiling	Required	Provided		
11	Internal Hydrants	Required	Provided	MR	
11	size of riser/down-comer	100 mm	150	145	
			150 mm	MR	
	Training of try draftes per floor	2 nos.	2 nos.	MR	
12	Hose Box Vord Hydropts	2 nos.	2 nos.	MR	
12	Yard Hydrants.	10.40			
	Total number of hydrants	N/A	N/A	N/A	
12	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.			- Company	
	Ground Level	Required	Provided	MR	
	Discharge of main Pump	2850 LPM	2850 LPM	MR	
	> Head of Main Pump	80 Mtrs.	80 Mtrs.	MR	
	Number of main pumps	1No.	1No.	MR	
	Jockey pump out put	180 LPM	180 LPM	MR	
	> Jockey pump head	80 Mtrs.	80 Mtrs.	MR	
	> Standby pump out put	2850 LPM	2850 LPM	MR	
	> Standby pump Head	80 Mtrs	80 Mtrs	MR	
	Auto Starting / Manual stopping	Required	Provided	MR	
	Pump House Access	Required	Provided	MR	
	Terrace Level	N/A	N/A	N/A	
	Discharge of pump	N/A	N/A	N/A	
	> Head of the Pump	N/A	N/A	N/A	
	> Power supply	N/A	N/A	N/A	
	> Auto Starting of pump	N/A	N/A	N/A	
14	Captive Water Storage for Fire Fighting.				
	Underground tank capacity	1,00,000 Ltrs.	1,00,000 Ltrs.	MR	
	> Draw-off connection	Required	Provided	MR	
	> Fire service inlet	Required	Provided	MR	
	> Access to tank	Required	Provided	MR	
	Overhead Tank capacity	N.A	N.A	N.A	
.5	Exit Signage.	Required	Provided	MR	
.6	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
		. 4/ / 1	14/1	IN/A	
		N/A	NI/A	NI/A	
	Communication in lift car Firemen's grounding switch	N/A N/A	N/A N/A	N/A N/A	

17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room			1
	Detector system panel	Required	Provided	MR
	Flow switch panel	N/A	N/A	N/A
	PA system panel	Required	Provided	MR
	Battery backup	Required	Provided	MR
	Building Floor Plans	Required	Provided	MR
20	Special Fire Protection systems for	Required	Provided at	MR
	protection of special Risks, if any:		LT & HT	
			Penels	

The fire protection systems provided in the building were tested checked and found functional at the time of inspection. The fire safety arrangements for Haldiram Restaurant (Eating House) are connected to commercial /PDP area. This department had already issued fire safety certificate for commercial building vide letter no. F.6/DFS/MS/2015/NDZ/1686 dated 15/09.15.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Submitted please.

Signature of the Inspecting Officer

Name: Suresh Singh

Designation :ADO(Shah.)

Signature of the Inspecting Officer

Name : Virendra Singh

Designation:DO(ED)