GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F6/DFS/ans/school/2016/W2/1760 Dated: 6 1/2 /2016

FIRE SAFETY CERTIFICATE

Manglam Palace) Rohini-110085 comprised of 2nd floor of Ground + Two upper floors building owned / occupied by New Bal Bharti Secondary School has already been issued fire safety certificate vide letter no F-6/DFS/MS/S/2013/WZ/1084 dated 15/10/2013. The premises was re-inspected by the officers from this department on dated 16/11/2016 in the presence of Sh Sandeep Dahiya, (Manager) and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with the requirements of Circular No F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 issued by Director of Education / NBC- Part IV and verified by the officer concerned of Fire Service and the building / premise is fit for occupancy of Group Class B (Educational) with effect from 6 / 10 / 2016 for a period of three years, subject to compliance of the conditions mentioned below:

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction
- 6. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on **WWW.dfs.Delhigovt.nic.in**

Issued on _______at New Delhi by

Chief Fire Officer Ph: 011-23414250

Copy to: 1. The Principal, New Bal Bharti Sec. School. Sector-7, M2K Road, Rohini, Delhi

2. The Director of Education, Old Secretariat, Delhi

INSPECTION REPORT

1. Name & address of the building: New Bal Bharti Secondary School. Sector-7, M2K Road,

Rohini-110085 on 2nd floor

2. Type of Occupancy

: Education

3. Type of Case

: Renewal

4. Details of previous NOC : F-6/DFS/MS/S/2013/WZ/1084 dated 15/10/2013

5. Fire Safety directives letter No : Director of education

6. Date of inspection

: 16/11/2016

7. Name of the Inspecting Officers: DO(NW) & ADO (Rohini)

8. Name and designation of officers

from the building side

: Sh. Sandeep Dahiya

9. Year of Construction

: 1998

10. Applicant's letter No.

: NBBPS/16/1413199

dated 22/09/2016

PA-650 Sq.m. CA-full NOS-410

NOT-17

CR-16

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR	
1	Access to building				
	Road width	6 mtr	6 mtr	M/R	
	Gate width	 c			
	Width of internal road				
2	Number, Width, Type & Arrangement o	f Exits			
	a. Number of staircases			2	
	Upper Floors	02	02	M/R	
	Basements				
	b. Width of staircases				
	Upper Floors	1.5	1.5 Provided	M/R	
	Basements		-	-	
	c. Protection of exits				
	Fire check door	N/A	N/A	N/A	
	• Pressurization	N/A	N/A	N/A	
	e. No. of continuous staircases to terrace	N/A	N/A	N/A	
	g. Width of Corridor	N/A	N/A	N/A	
	h. Door Size	1 mtr	1 mtr	M/R	

2				13	
3	Compartmentation.				
	Fire check door	N/A	N/A	N/A	
	Sealing of electrical shafts	N/A	N/A	N/A	
	Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System.				
	Basements	30 a/c per hour	N/A	N/A	
	Upper floors	12 a/c per hour	N/A	N/A	
5	Fire Extinguishers				
	Total numbers	05	05	M/R	
	• Types		ABC	M/R	
	IS marking	ISI marked	Yes	M/R	
6	First-Aid Hose Reels.				
	Total numbers on each floor	01	Provided	M/R	
	• Length of hose reel hose	30 m	Provided	M/R	
	Nozzle diameter	5 mm	Provided	M/R	
7	Automatic fire detection and alarming system.				
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
8	MOEFA	Required	Provided	M/R	
9	Public Address System.			35 6 5 - 1 · 10	
10	Automatic Sprinkler System.				
	Basement	N/A	N/A	N/A	
	Upper Floor	N/A	N/A	N/A	
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
11	Internal Hydrants				
V	Size of riser/down-comer	N/A	N/A	N/A	
	 Number of hydrants per floor 	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	

12	Yard Hydrants.				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual	N/A	N/A	N/A	
	stopping ➤ Pump House Access	N/A	N/A	N/A	
	Terrace level		/		
v T	Discharge of pump	2X450 lpm	Provided	M/R	
	➤ Head of the pump	40m	Provided	M/R	
	> Power Supply	Required	Provided	M/R	
1.4	Auto Starting of pump	Required	Provided	M/R	
4	Captive Water Storage for fire fighting	•			
	Underground tank capacity				
	> Draw-off connection	N/A	N/A	N/A	
	> Fire service inlet	N/A	N/A	N/A	
	> Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	5,000 ltr	Provided -	M/R	
15	Exit Signage.	Required	Provided	Required	
6	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
	Standby power supply	N/A	N/A	N/A	

10/11

18	Refuge Area.			1
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
Ux:	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F-6/DFS/MS/S/2013/WZ/1084 dated 15/10/2013 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name Swresh Singh,

Name Rajesh Kumal

Designation Designation

Designation ADOL RN

30.11.11

)yccothoz)

cfo. wex Althors