GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2018/ MO2/23

Dated :05/01/16

FIRE SAFETY CERTIFICATE

Certified that the Krishna Lodge Guest House located at 3441, Dariba Pan, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (reception + 04 guest rooms), 1st floor to 2nd floor (03 guest rooms at each floor) and 3rd floor (04 guest rooms), total 14 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2012/4194 dated 08/11/12. The premises was re-inspected by the officer concerned of this department on 24/12/15 in the presence of Sh. Tony Khanna (Owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 14 guest rooms only with effect from -0-1-1-1/6------ for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -63-1-146---at New Delhi by.

(Dr. G. C. Misra) Chief Fire Officer Ph-011-23414333

Copy to:-

1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.

2. Sh. Tony Khanna (Owner),

Krishna Lodge Guest House located at 3441, Dariba Pan, Pahar Ganj, New Delhi. Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building:-Krishna Lodge Guest House located at 3441,

Dariba Pan, Pahar Ganj, New Delhi 2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 14 Guest rooms) 3. Type of case:-

Renewal 4. Details of previous FSC:-No. F6/DFS/MS/GH/2012/4194 dated

08/11/12.

5. Fire safety directives No.-N/A 6. Date of inspection:-24/12/15

7. Name of the inspecting officer:-Sh. Manoj Kumar Sharma (ADO/CC) 8. Name & designation of officer

From the building side:-Sh. Tony Khanna (Owner) 9. Year of construction:-

1999 10. Applicant's letter No:-No. Nil dated 17/12/2015

			red 17/12/2015.	011.6		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing	Provided at sir	Old Case te Remarks MR/NMR		
1.	Access to Building					
	1) Road width	N/A	10 Fact			
	2) Gate width	N/A	10 Feet N/A	MR		
1	3) Width of internal road			N/A		
2.	Number, Width Type & A	N/A	N/A	N/A		
	Number, Width Type & Arrangement of Exits A. Number of staircases					
	1. Upper floors	01 Nos.	0.1.2.4			
	2. Basements	N/A	01 Nos.	MR		
	B. Width of staircase	IN/A	N/A	N/A		
	1. Upper floors	0.80 mtr.	0.00 . 0.07			
	2. Basements	N/A	0.80 to 0.95 mtr.			
	C. Protection of exits	IN/A	N/A	N/A		
	1. Fire check door	N/A	27/4			
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	01	N/A	N/A		
	staircase to terrace	01	01	MR		
	E. Width of corridor	N/A	N/A			
	F. Door size	1 mtr.	1 mtr.	N/A		
3.	Compartmentation	1 11111.	1 IIItr.	MR		
	1) Fire check door	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A N/A	N/A		
	4) Water curtain	N/A	N/A N/A	N/A		
	5) Fire Dampers	N/A		N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	NI/A		
	2) Upper floors	12 a/c per	Natural	N/A		
		hour	rvaturar	MR		
	Fire Extinguishers	-				
	1) Total numbers	09 Nos.	09 Nos.	MR		
3	2) Types	ABC & CO2	1500	MR		
	3) ISI marking	Required	D 111	MR		
	First-Aid Hose Reel		51,404	1411/		
1) Total number of eachfloor	01	01	MR		
2	2) Length of hose reel hose	30 mtr.	20	MR		
3) Nozzle diameter	05 mm	0.5	MR		

N/22

7.					
	Automatic Fire Detection 1) Type of detectors	n & Alarmin	g System		
	2) Location of main panel	N/A	N/A	N/A	
4	3) Location of repeater pa	N/A	N/A	N/A	
	4) Alternate source of pov	nel N/A	N/A	N/A	
	5) Hooter's Location		N/A	N/A	
8.	MOEFA	N/A	N/A	N/A	
9.		N/A	N/A	N/A	
10.	Public Address System	Require	d Provided	MR	
10.	1) Possers of the System			IVIIC	
		N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false ceiling	N/A	N/A	N/A	
11.				IVA	
11.	Internal Hydrants				
	1) Size of riser/down-come		N/A	N/A	
	2) Number of hydrants per floor	N/A	N/A	N/A	
	3) Hose box			IVA	
12.	Yard Hydrants	N/A	N/A	N/A	
	1) Total number of			14/11	
	 Total number of hydrants Hose box 		N/A	N/A	
13.		N/A	N/A	N/A	
10.	Pumping Arrangement			14/71	
	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main	N/A	N/A	N/A	
	pump			IN/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pum	ip N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A N/A	
	f) Stand by pump outpu	t N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual	N/A	N/A	N/A	
	stopping		The second of the	IV/A	
	2) Terrace level				
	a) Discharge of pump	225 LPM	225 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	
•	Captive water Storage for Fire Fighting				
	1) Under ground tank	N/A	N/A	N/A	
	capacity		2 2005	IVA	
-	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
-	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank	2500 ltr.	2500 ltr.	MR	
	capacity			IVIIX	
	Exit Signage.	Required	Provided	MR	
	Provision of Lifts.			1411/	
	a) Pressurization of lift shaft	N/A	N/A	N/A	
0	b) Pressurization of lift lobby	N/A	N/A	N/A	
	-) 0	N/A	N/A	N/A	

m

	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	NA		

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter No. F6/DFS/MS/GH/2015/2586 dated 11/12/2015 have been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2012/4194 dated 08/11/2012 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

Doless (

Usulmal 31/17/15