

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F.6/DFS/MS/EH/2016/ w2/182

Dated: 28/01/2016

FIRE SAFETY CERTIFICATE

Certified that McDonalds Family Restaurant located on ground floor of M2k Manglam palace, Sector 3, Rohini, Delhi 110085 was granted NOC by this department vide letter no F-6/DFS/MS/EH/2013/502 Dated 05/02/2013. The premises was re-inspected by the officer concerned of this department on 06/01/2016 in the presence of Sh. Kukreja and observed that all the fire prevention and fire safety arrangement as provided in the premises found in good working condition. The Manglam Palace in which restaurant is located has a valid Fire Safety Certificate issued vide letter no F6/DFS/MS/2014/WZ/509 dated 24/04/2014. The premises have therefore, deem complied with the requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and premises is fit for Assembly Building occupancy with effect from 28/01/2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

1. Means of escape shall not be kept locked or bolted from outside and shall be easily open able by guests in an event of emergency.
2. All employees shall be acquainted with the use and maintenance of all the fire fighting installation/equipments.
3. The fire suppression / protection arrangements provided in the guest house are to minimize losses, if maintained in good working condition. These systems cannot give any guarantee that there will be no fire or losses in the event of one.
4. Any loss of life and property due to non-functional of fire safety arrangements and other installations shall be the responsibility of the licensee.
5. This report may not in any way be treated as regularization of unauthorized construction, if any.
6. The basement shall be used strictly as per the provision of building bye laws
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Issued on 28/01/16 at New Delhi by



(SANTOKH SINGH)
Chief Fire Officer
Ph: 011-23414250

Copy to:

1. The Dy. Health Officer, Rohini Zone, Health Department MCD, Sector - 5, Rohini, Delhi
2. McDonalds Family Restaurant at 16 M2k Manglam palace, Sector 3, Rohini, Delhi 110085



N19

INSPECTION REPORT

1. Name & address of the building : McDonalds Family Restaurant at 16, M2K Manglam Palace, DDA Central Market, Sec-3, Rohini, Delhi.
2. Type of Occupancy : Assembly **Restaurant running on ground floor only**
3. Type of Case : Renewal
4. Details of previous NOC : F-6/DFS/MS/EH/2013/502 Dated 05/02/2013
5. Fire Safety directives letter No : nil
6. Date of inspection : 06 / 01 / 2015
7. Name of the Inspecting Officers : DO (NW)
8. Name and designation of officers from the building side : Sh. Kukreja
9. Year of Construction : 2007
10. Applicant's letter No. : L.No- nil Dated 03/04/2015.

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	06 mtr	P	M/R
	• Gate width	Old case	P	M/R
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits (On Ground Floor only)			
	a. Number of staircases			
	• Upper Floors	N/A	N/A	N/A
	• Basements	--	--	--
	b. Width of staircases			
	• Upper Floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	--	--	--
	• Pressurization	--	--	--
	d. No. of continuous staircases to terrace			
	e. Width of Corridor	--	--	--
	f. Door Size	Old case	135 & 90 cm	M/R
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A

	<ul style="list-style-type: none"> Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4	Smoke Management System.			
	<ul style="list-style-type: none"> Basements Upper floors 	30 a/c per hour	N/A	N/A
		12 a/c per hour	Exhaust fan provided	M.R
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers Types IS marking 	One ABC & One Co2 type	04	M/R
			ABC type	M/R
		ISI marked	Yes	M/R
6	First-Aid Hose Reels.			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	One at each floor	Provided with Mall	M/R
		30 m	Provided with Mall	M/R
		5 mm	Provided with Mall	M/R
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Smoke/Heat	Provided in restaurant	M.R
		On GF	Provided	M.R
		N/R	—	—
		R	Common with mall	M.R
		On GF	Provided	M.R
8	MOEFA	R	P	M.R
9	Public Address System.	N/R	—	—
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	N/R	—	—
		R	Provided	M.R
		N/R	—	—
11	Internal Hydrants provided with shopping mall			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	150 mm	Common with mall	M/R
		01	Common with mall	M/R
		01	Common with mall	M/R
12	Yard Hydrants. Provided with shopping mall			
	<ul style="list-style-type: none"> Total number of hydrants 	N/R	Provided	M.R

	• Hose Box	N/R	Provided	M.R
13	Pumping Arrangements.	Provided with shopping mall		
	• Ground Level			
	➤ Discharge of main Pump	2850LPM	Common with mall	M.R
	➤ Head of Main pump	60 m	Common with mall	M.R
	➤ Number of main pumps	2	Common with mall	M.R
	➤ Jockey Pump out put	180 LPM	Common with mall	M.R
	➤ Jockey pump head	60 m	Common with mall	M.R
	➤ Standby Pump out put	2850 LPM	Common with mall	M.R
	➤ Standby Pump Head	60 m	Common with mall	M.R
	➤ Auto Starting/ Manual stopping	R	Common with mall	M.R
	➤ Pump House Access	R	Common with mall	M.R
	• Terrace level			
	➤ Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	
	➤ Power Supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14	Captive Water Storage for fire fighting.			
	• Underground tank capacity	N.A.	60,000 Ltr Common with mall	N.R
	➤ Draw-off connection		Common with mall	N.R
	➤ Fire service inlet	N/R	Common with mall	N.R
	➤ Access to tank	N/R	Common with mall	N.R
	• Overhead Tank capacity	10,000 ltr	20,000 ltr Common with mall	M/R
15	Exit Signage.	R	P	M/R
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/R	N/R	N/R
	• Pressurization of Lift lobby	N/R	N/R	N/R
	• Communication In lift Car	N/R	N/R	N/R
	• Fireman's Grounding Switch	N/R	N/R	N/R
	• Lift Signage	N/R	N/R	N/R
17	Standby power supply	R	Provided with mall	M/R

2/11

McDonalds Family Restaurant, 16, M2k Manglam Palace, DDA Central Market Sector – 3 Rohini, Delhi

18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	R	on G.F Provided with mall	M.R
	• Flow Switch Panel	N/R	N/R	N/R
	• PA System Panel	N/R	N/R	N/R
	• Batter backup	R	P	M.R
	• Building Floor Plans	N/R	N/R	N/R
20	Special Fire Protection Systems for Protection of special Risks, if any:	--	---	--

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F-6/DFS/MS/EH/2013/502 Dated 05/02/2013 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name

Designation

Debo (wp)

pl explain delay.

DO not

*ventat
15/11*

Signature of the Inspecting Officer

Name

Designation

Debo
14/1/16
DO (NW)