GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2016/ \$2 /366

Dated: 68/63/16

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Sarthak Palace** located at 14A/34, WEA, Karol Bagh, New Delhi-110005 is comprised of Basement, ground floor plus three upper floors, using basement as hall/storage, ground floor as reception and shops, first, second & third floor each having 09 guest rooms respectively (Total 27 guest rooms), a hall and staff pantry in a temporary shed on terrace was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2013/645 dated 14.02.2013 owned/occupied by Sh. Sanjeev Malhotra. The guest house building was re-inspected by the officers concerned of this department on 23.02.2016 in the presence of Sh. Gurpreet Singh (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on....at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

 Sh. Sanjeev Malhotra (Owner), Hotel Sarthak Palace, 14A/34, WEA, Karol Bagh, New Delhi-110005. Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The basement shall be used strictly as per the provisions of the building bye laws.
- 7. The owner/ occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSP	ECTION REPORT	The second secon					
 Name & address of the buildin 	g: Hotel Sorthat	Palace Halas.	1100 10 0				
2. Type of Occupancy	building: Hotel Sarthak Palace, 14A 34, WEA, Karol Residential (Guest House) N.D						
3. Type of Case	: New Case/Rene	: New Case/Renewal					
 Details of Previous NOC 	: Letter No. F.G.IA	: Letter No F.C. La Colonal Co. La					
Fire Safety directives letter No	on 23.02.2016 ting Officer . N.O. S. V. Terrar						
6. Date of inspection							
 Name of Inspecting Officer 							
Name and designation of office	ers	alles b H.D.C	P.S. Dahiya				
From the building side	: Sh. Gurh	arest Challes					
9. Year of Construction	Sh. Guxbreet Singh (Manager) Before 2001						
10. Applicant's letter No.	Mil datad ag ag gala						
S. Minimum Standards on fire	NBC/BBL	Provided at	The state of the s				
No. prevention and fire safety U/R 33	Requirement		Remarks				
1. Access to building	The second content	1 site	MR/NMR				
 Road width 	Accessible	07mtr	No.0				
Gate width	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		MR				
 Width of internal road 	,	115 cms	MR				
2. Number, Width, Type & Arrangemen		Automotive Control of the Control of					
a. Number of staircases	III OF EXITS						
• Upper Floors							
Basements	One	One	MR Old Case				
b. Width of staircases	- do -	-do-	-do-				
• Upper Floor		The second secon	The second for the second seco				
Basements		125cms	MR, Old Case				
c. Protection of exits	-	llocms	- do -				
• Fire check door							
	-	Parame	Annual to the control of the second that the control of the contro				
* pressurization		Commence of the Control of the Contr	A Committee on Later committee of the control of th				
To the continuous stair cases to		And the second s	AMERICAN AND ADDRESS OF THE PARTY AND A COURSE OF THE PARTY AND ADDRESS OF THE PARTY ADDRESS OF THE PARTY AND ADDRESS OF THE PARTY AND ADDRESS OF				
terrace e. Width of Corridor	Appears -	One	Commence of the contract of th				
f. Door Size		300 cms, 235 cms	Comments of the second section of the second section of the second section is a second section of the second section of the second section of the second section section is a second section of the second section section is a second section of the second section section is a second section of the second section section is a second section of the second section secti				
1. 0001 3126		the second secon					
3. Compartmentation		76cms x 203 cms					
- The state of the		and the second s	The second of Address of the State of Control of Control of State				
Fire check door	-		The state of the s				
 Sealing of electrical shafts 		0	AND THE PROPERTY OF THE PROPER				
 Fire Rating of shaft door 		Sealed					
 Water Curtain 	Annual Control of the						
 Fire Dampers 		(100					
Smoke Management System			And the second s				
- Waltagement System							
* Basements	30 a/c per	Exhaust Fans	· h a A				
Upper floors	hour	are Provided	MR				
	No.	itural Ventilation	MR				

	NIX	4		
		12 a/c per		
		hour		
5.	Fire F. Al.			-
	Fire Extinguishers	0		
	 Total numbers 	14 NOS	Provided	NhO
	* Types	Co2, WCo2.	-do-	
6.	IS marking	ISI marked	131 Marked	
0.	First-Aid Hose Reels		LISTIMINED	I MK
	 Total numbers on each floor 	One	Provided	200
	 Length of hose reel hose 	30 m	-do-	
	 Nozzle diameter 	5 mm	-do-	
7.	Automatic fire detection and alarming	system	1 -00-	L. MR
	 Type of detectors 			
	 Location of Main Panel 		· ·	
	 Location of Repeater Panel 			
	 Alternate source of power 			
	 Hooters' Location 		American and the second and the seco	
8.	MOEFA	0		
9,	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	- 00 -	L do -	MR
	Basement	0		
	 Upper Floor 	Required	Provided	MR
	 Sprinkler above false ceiling 		-	
11.	Internal Hydrants			+
	 Size of riser/down-comer 			
	 Number of hydrants per floor 			
	 Hose Box 			
12.	Yard Hydrants	i i	The state of the s	MR M
	 Total number of hydrants 		J.	
	* Hose Box			
13.	Pumping Arrangements		And the second s	
	 Ground Level 			
	Discharge of main Pump			
	Head of Main pump			
	Number of main pumps			
	Jockey Pump out put			
	Jockey pump head			
	Standby Pump out put			
	Standby Pump Head		1	-
	Auto Starting/Manual			· ·
	stopping			-

No.

MIX 14A/34, WEA, Kasol Beegh, New Delli - 110005.

T	Pump House Access			-	
	Terrace level				2
	Discharge of pump		450 LPM	MR.O	Id Ca
	> Head of the pump			-do-	-
	> Power Supply	Required	30 M Provided	MR	
	> Auto Starting of pump	Kapara	7 500 700		
					1
4.	Captive Water Storage for fire fighting				,
Addition to the second	 Underground tank capacity 				
	Draw-off connection	-	0 11	h=0	
	Fire service inlet	Qualitarian	Provided	MR	
	Access to tank	C	name.		
	 Overhead Tank capacity 	-	3000 Ur	MR, C	old Ca.
5.	Exit Signage.	Required	Provided	MR	ý
.6.	Provision of Lifts.				ili
	Pressurization of Lift Shaft	-		-	i
	Pressurization of Lift lobby	367	-	_	1
	Communication In lift Car		D /	MR	
	• * Fireman's Grounding Switch	^	Provided		
	 Lift Signage 	Required	-do-	MR	
	• Lift Signage	-do-	- do -	, MR	
17.	Standby power supply	-do-	D.G. Set of 625 KV	A MR	ı
de l' e	Startas / Posts				
18.	Refuge Area.				
	> Total Area	-	_		
	> Location				
			×		- 1
19.	Fire Control Room		×.		
1.0.	Detector System Panel	-	_		. 1
	• Flow Switch Panel			-	1
	PA System Panel			_	8
	Batter backup		_		v le
 Building Floor Plans 	-		_	2 ×	
20.	Special Fire Protection System for Protection of special Risks, if any:	-	-	-	



The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F-6/NFS/MS/G-H/2013/645 dated 14.03.2013 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

CK 19m/2/16

Signature of Inspecting Officer

Name S.K. Tomar

Designation Divisional Officer

Malya May 100 M

Signature of Inspecting Officer

Name P.S. Sahiya

Designation Appth. Divisional Officer.