## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. 66/06s/as/school/2016/w2/632 Dated: 25/4/2016

## FIRE SAFETY CERTIFICATE

Certified that <u>Vidya Jyoti Shiksha Sadan</u>, <u>kh. No. 84/22</u>, <u>Village Daryapur Kalan</u>, <u>Delhi-39</u> comprised of <u>Single Block</u>, <u>Ground floor only</u> owned/occupied by <u>Vidya Jyoti Shiksha Sadan</u> have complied with the fire prevention and fire safety requirements in accordance with the <u>Circular No F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011</u> issued by Director of Education and verified by the officer concerned of Fire Service on <u>21/03/2016</u> in the presence of <u>Sh. Sandeep Kumar (Manager)</u> and that the building / premises is fit for occupancy of <u>Group Class B (Educational)</u> building with effect from <u>75/ 12016</u> for a period of <u>three years</u>, subject to compliance of the conditions mentioned below:

## Conditions for the validity of Fire Safety Certificate:

- 1 All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
- 2 Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3 The trained fire fighting staff should be available round the clock.
- 4 Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5 This certificate cannot be treated in any case for regularizations of unauthorized construction.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.be/higovt.nic.in"><u>WWW.dfs.be/higovt.nic.in</u></a>

Issued on 25/4/6 at New Delhi by

(Dr. G.C.Mishra)
Director

Ph: 011-23414333

Copy to:

- 1. The Principal, Vidya Jyoti Shiksha Sadan, kh. No. 84/22, Village Daryapur Kalan, Delhi-39.
- 2. The Director of Education, Old Secretariat, Delhi

NO Vidya Jyoti Shiksha Sadan, Daryapur kalan, Delhi INSPECTION REPORT Ground Floor only 1. Name & address of the building: Vidya Jyoti Shiksha Sadan, Kh. No. 84/22, Village Daryapur Kalan, Delhi – 110039 (School has been shifted from previous address) : Educational 2. Type of Occupancy : New Case 3. Type of Case : nil 4. Details of previous NOC 5. Fire Safety directives letter No : Director of education 01/03/2011 : 21/03/2016 6. Date of inspection 7. Name of the Inspecting Officers : ADO (Bawana) 8. Name and designation of officers : Sh. Sandeep Kumar (Manager) from the building side : 2015 9. Year of Construction : nil dated 08/03/2016 10. Applicant's letter No. Plot area:585 sq mtr Covered area:325 sq mtr No.'s of students: 363 No's of classrooms:- 10 + 01 room for other purpose Remarks Provided at site Minimum Standards on fire Director of MR/NMR education prevention and fire safety U/R 33 1 Access to building M/R P 6 m Road width 4.5 m u M/R P Gate width Width of internal road Number, Width, Type & Arrangement of Exits 2 a. Number of staircases Upper Floors Basements b. Width of staircases Upper Floors Basements c. Protection of exits

01 mtr

01 mtr

M/R

Fire check door

e. No. of continuous staircases to terrace

Pressurization

g. Width of Corridor

h. Door Size

N-Z

3	a Jyoti Shiksha Sadan, Daryapur kalan, Delhi  Compartmentation.			1		
	Fire check door					
	Sealing of electrical shafts					
	• Fire Rating of shaft door			k		
	Water Curtain					
	• Fire Dampers					
4	Smoke Management System.					
	Basements	30 a/c per hour				
-%	Upper floors	12 a/c per hour				
5	Fire Extinguishers					
	Total numbers	03	04	M/R		
	• Types	TCT - 1-1	ABC	M/R		
	IS marking	ISI marked	Yes	M/R		
6	First-Aid Hose Reels.					
	Total numbers on each floor	,				
	<ul> <li>Length of hose reel hose</li> </ul>					
	Nozzle diameter	30 m 5 mm				
7	Automatic fire detection and alarming	10 100000000000000000000000000000000000				
	Type of detectors	1 <del></del>				
	Location of Main Panel					
	Location of Repeater Panel					
	Alternate source of power					
	Hooters' Location			,		
8	MOEFA					
9	Public Address System.		, <del>-</del> -			
10	Automatic Sprinkler System.					
	Basement					
	Upper Floor					
	Sprinkler above false ceiling					
11	Internal Hydrants					
	Size of riser/down-comer					
	Number of hydrants per floor		·	7		
	,					

*	12	Yard Hy	drants.					
		Total number of hydrants						
	1. 4.1	Hose Box		-		<u> </u>		
	13							
	13	Pumping Arrangements.						
		Ground L						
			arge of main Pump					
		> Head	of Main pump					
		> Number	er of main pumps					
		> Jockey	Pump out put	-				
		> Jockey	pump head					
			y Pump out put					
			y Pump Head					
		The state of the s	tarting/ Manual					
		stoppin	g House Access		_			
		Terrace lev				_		
2			arge of pump		_	_		
			of the pump			_		
		> Power	_	_				
			tarting of pump		-			
-	14							
L		Captive Water Storage for fire fighting.						
			nd tank capacity	_		-		
		Draw-off co	onnection	_				
		> Fire service	inlet	_				
		> Access to ta	nk					
		Overhead Ta	ank capacity	_				
1	5	Exit Signage.			-	_		
1					_	_		
1	0	Provision of Lifts.						
			on of Lift Shaft		_			
			on of Lift lobby	_	<del></del>	_		
		THE RESERVE OF THE PARTY OF THE	tion In lift Car		- 1			
			rounding Switch		A11/2 - 22/2	_		
A	2	• Lift Signage			rici _			
17	3	Standby power sup	ply	_	_			
	- 1		1.	÷				
				7.11				

Vidya Jyoti Shiksha Sadan, Daryapur Kalan, Delhi-110332

18	Refuge Area.		4		
	> Total Area				
	Location				
10		_			
19	Fire Control Room				
8	Detector System Panel			I.	
	Flow Switch Panel				
	PA System Panel		_		
	Batter backup				
	•	_			
20	Dunaing 1 1001 1 Ialis	.—		_	
20	Special Fire Protection Systems for Protection of special Risks, if any:			E .	
	roccotion of special Risks, if any:				
4. 5. 6. 7.	Electric circuit	a Jvoti Shiksha Sad	lan Damonus V	•••••••	39
fire saf	The fire protection systems provided in the of inspection.  Keeping in view the substantial compliance of required under the rules it is recommendable for the Service Rules 2010/ issue shortcoming.	the building were te	st checked and	prevention and	at
ignatu	re of the Inspecting Officer	Signature of	the Inspecting C	Officer	
		8	and mapeeting C	/IIICCI	
Nam	ne	Name	all to	ia	
Desi	gnation	Designation	on 22/2	2/16 (BID)	