GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/GH/2016/ ND2 90 >

Dated: 01/06/16

FIRE SAFETY CERTIFICATE

Certified that the Hotel Mandakini Palace, located at 8/29 W.E.A Abdul Aziz Road ,Karol Bagh, New Delhi-110005 is comprised of Basement, Ground floor + Three Upper floors, the basement used as storage, Ground floor as reception, office, one hall and two Guest rooms, first, second and third floor each having 08 guest rooms respectively. (Total 26 guest rooms), A Pantry for Staff in temporary tin set on terrace was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2010/ 2606 dated 07-09-2010 for 26 guest rooms. The premises was re-inspected by the officer concerned of this department on 28-05-2016 in the presence of Md. Irfan (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub-Division A-1 Guest House for 26 guest rooms with effect from --- 01/06/-2016 for a period of three years in accordance with rule 36 unless renewed funder rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on at New Delhi by.

(Rajesh Panwar) Dy. Chief Fire Officer Delhi Fire Service Ph -011*23412025

Copy to:-

4.30.747

1. Sh. Sumit Aanad (Owner), Hotel Mandakini Palace, 8/29 W.E.A Abdul Aziz Road, Karol Bagh, New Delhi-110005

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1. Name & address of the building Hotel Mandakini Palace, 8/29 W.E.A Abdul Aziz Road

Karol Bagh, New Delhi-5

. 2. Type of Occupancy Residential (G.H) B+ GF + 03 upper floors, total guest

rooms-26

3. Type of Case Renewal

4. Details of Previous NOC F.6/DFS/MS/GH/2010/2606 dated 07/09/2010

5. Fire Safety directives letter No N/A

6. Date of inspection 23/05/2016

7. Name of Inspecting Officer Dy. C.F.O Rajesh Panwar

8. Name and designation of officer

From the building side Md.Irfan (Manager) 9. Year of Construction

Before 2007

10. S. No.	Applicant's letter No.	ll dated 23.05.201	6				
	and fire safety U/R 33	n NBC/BBL Requirement	Provided at site	Remarks			
1.	Access to building	Tredancinent		MR/NMR			
2.	Road widthGate widthWidth of internal road	Accessible NA NA	07 mtr NA NA	MR NA NA			
·•	Number, Width, Type & Arrangement	of Exits		11,1			
	 Upper Floors Basements 	One One	One	MR , Old Case			
	b. Width of staircases	One	One	MR, Old Case			
	Upper FloorBasements	125 cms 125 cms	126 cms	MR, Old Case			
		125 CIIIS	115cms	MR, Old Case			
	c. Protection of exits • Fire check door	NA NA	NA	NA			
	• Pressurization	NA	NA	NA			
	d. No. of continuous staircases to			•			
	terrace e. Width of Corridor	One	One	MR			
	c. Width of Corridor	1.0 Mtr	155cms	MR			
3.	f. Door Size Compartmentation	1.0 Mtr.	102 cms X 206 cms	MR, Old Case			
	Fire check door	NIA					
	Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	Sealed	MR			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
	Smoke Managamana S	NA	NA	NA NA			
	Smoke Management System		27	INA			
	Basements Upper floors	30 ACPH	Exhaust Fans are Provided	MR			
	opper moors	12 ACPH	Natural Ventilation	MR			
	Fire Extinguishers						
	Total numbersTypes	02 at each floor ABC, Co2, WCO2	Provided	MR			
	• IS marking	ICI	Provided	MR			
	First-Aid Hose Reels	ISI marked	ISI marked	MR			
	Total numbers on each floor	One					
	• Length of hose reel hose	One 30 m	Provided	MR			
1001000	Nozzlo diamete	50 III	Provided	MR			

7.	Automatic fire detection and alarming						
	Type of detectors	NA					
	 Location of Main Panel 	NA NA	NA	NA			
	Location of Repeater Panel	NA NA	NA	NA			
	 Alternate source of power 		NA	NA			
		NA	NA	NA			
8.	 Hooters' Location 	NA	NA	NA			
9.	MOEFA	Required	D 1 1				
10.	Public Address System	Required	Provided Provided	MR			
10.	Automatic Sprinkler System		Frovided	MR			
	Basement	Required	Provided	MD			
	Ground Flan	NA	NA	MR NA			
	• Ground Floor	NA	NA				
11.	Sprinkler above false ceiling Internal Hydrants		1111	NA			
	Size of view / l						
	Size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floorHose Box	NA	NA	NA NA			
12.	Yard Hydrants	NA	NA	NA			
				14/1			
	Total number of hydrantsHose Box	NA	NA	NA			
13.		NA	NA	NA NA			
	Pumping Arrangements			IVA			
	Ground Level	() () () () () ()					
	procharge of main pump	NA	NA	NA			
	rieda of Maili pullip	NA	NA				
	Number of main pumpsJockey Pump out put	NA		NA			
	> Jockey pump head	NA	NA	NA			
	Standby Pump out put		NA	NA			
	Standby Pump Head	NA	NA	NA			
	Auto Starting/Manual	NA	NA	NA			
	Stopping	NA	NA	NA			
	Pump House Access	NA	NA	• NA			
	Terrace level			IVA			
	Discharge of pump	900 LPM	456, LPM Each	MD(02 D			
	Head of the pump	30 M	30 M Each	MR(02 Pumps)			
	Power Supply	Required		MR(02 Pumps)			
	Auto Starting of pump		Provided	MR			
	in the state of th	NA	NA	NA			
l	Captive Water Storage for fire fighting						
	 Underground tank capacity 	NA	NA	NA			
	Staw of confiection	NA	NA				
	Fire service inlet Access to tank	NA	NA	NA			
		NA		NA			
	Overhead Tank capacity	10000 Ltr	NA 10000 F	NA			
		Required	10000 Ltr	MR			
	Exit Signage.	required	Provided	MR			
	Provision of Lifts.						
	Pressurization of Lift Shaft	NA	NIA				
	 Pressurization of Lift lobby 	NA	NA	NA			
	Communication In lift Car	Required	NA	NA			
		required	Provided	MR			

	•	Firemen's County County					
		Fireman's Grounding Switch Lift Signage	Required	Provided	MR		
			Required	Provided	MR		
17.	Standt	y power supply	Required	Provided	MR		
18.	Refuge Area.						
	A	Total Area	NA	NA	NA		
	>	Location	NA	NA	NA		
19.	Fire Control Room						
	•	Detector System Panel	NA	NA	NA		
		Flow Switch Panel	NA	NA	NA		
	•	PA System Panel Batter backup	NA	NA	NA		
			NA	NA	NA		
	•	Building Floor Plans	NA	NA	NA		
20.	Special Protect	Fire Protection System for ion of special Risks, if any:	NA	NA	NA		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/GH/2016/2606 dated 07.09.2010 renewal under rule 35 of Delhi Fire Service Rules 2010, is recommended please.

Signature of Inspecting Officer

Signature of Inspecting Officer

Name: - Rajesh Panwar

Name

Designation: - Dy. C.F.O (NDZ)

Designation

ton Cons

F.7 letter ia put up for signaline

Dycho (FPW) W

1.6.16