FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. F6/DFS/MS/EH/2016/WZ/ 1075

Dated: 93 06 2016

FIRE SAFETY CERTIFICATE

Certified that the McDonalds Family Restaurant by Connaught Plaza Restaurants Pvt. Ltd. located at Shop No.02, 03 & 04 at Ground Floor, & Storage at Shop No- 102 at 1st Floor, DT City Centre Shalimar Bagh, Delhi – 110088 was issued FSC vide Letter No. F6/DFS/MS/EH/2013/WZ/522 dated 08-07-2013. The premises was re inspected by the officers concerned of this department on 27-05-2016 in the presence of Mr. Jayant Sharma (Senior Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect from 23/06/2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. The mall, Community Centre, A Block, Shalimar Bagh, Delhi – 110088 have already been issued FSC by this department vide letter no F-6/MS/DFS/2015/WZ/1035 dated 18/06/2015.

Issued on . 93 06 2016 at New Delhi by.

(Dharmpal Bhardawaj)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:

1. Sh. DN Thakur (Authorised Signatory), Connaught Plaza Restaurants Pvt. Ltd., 13A, Jor Bagh Market, New Delhi – 110003.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

 Name & address of the building: McDonalds Family Restaurant by Connaught Plaza Restaurants Pvt. Ltd., located at DT City Center, Shop no.2,3, & 4 on ground floor & storage at Shop no. 102, on First floor, Block-A, Community Center, Shalimar Bagh, New Delhi.

2. Type of Occupancy

: Class D(Assembly)

3. Type of Case

: Renewal

4. Details of previous NOC

: Letter No. F6/DFS/MS/EH/2013/WZ/522

dated 08-07-2013

5. Fire Safety directives Letter No.: Nil

6. Date of inspection

: 27-05-2016

7. Name of the Inspecting Officer: Udai vier, ADO (WZ)

8. Name and designation of Officer

from the building side

: Sh. Jayant Sharma

9. Year of Construction

: 2007

10. Applicant's letter No.

: Nil dated- 04/05/2016

S	Minir	num standards on fire	DDI AIDG			
Vo			BBL/NBC	Provided at		Remarks
	33	ntion and fire safety U/R	Requirements	site	;	MR/NMR
l	Access of building					
	•	Road width	12 mtrs	24	mtr	MR
	•	Gate width	4.5 mtr	5 mtr Provided		MR
	•	Width of internal road	6 mtr			MR
	Number, width, Type & Arrangements of exits					
	a.	Number of staircases	Required	10 Pro	ovided.	MR
DOM: NOT THE REAL PROPERTY.	•	Upper floors	2	10+1	MR (01 s	tair of 90cm width from Ground to 1st Floor
	•	Basements	NA	16	Provided	NA
	b.	Width of staircases				
	•	Upper floors	1.5 mtr & 2 mtr	Pro	vided	MR
	•	Basements	NA	Pro	vided	NA
	C.	Protection of exits				
	•	Fire check door	NA	Pro	vided	NA
	٠	Pressurization	NA	Pro	vided	NA
	d.	No of continuous				
	0	staircase to terrace	Required	Pro	vided	MR
	e. f.	Width Of Corridor Door Size	GF=2x 2 mtr FF=1x1mtr	Pro	vided	MR

3.	Compartmentation	NIA	D 1 1	DT A
	• Fire check door	NA	Provided	NA
	 Sealing of electrical shafts 	NA	Provided	NA
	• Fire Rating of shaft door	NA	Provided	NA
	Water Curtain	NA	Provided	NA
	• Fire Dampers	NA	Provided	NA
1.	Smoke managements System			
	Basements	NA	NA	NA
	Upper floors	Required	Provided	MR
5.	Fire Extinguishers	1		
-	Total numbers	04 nos.	06 Provided	MR
	• Types	ABC, CO2	Provided	MR
	• IS marking	ISI marked		
	To marking		Provided	MR
6.	First – Aid Hose Reels			*
	• Total numbers on each	01	01	MR
	floor			
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7.	Automatic fire detection and alar	ming system con	nmon with the n	nall
	Type of detectors	Smoke	Provided	MR
	 Location of Main Panel 	Ground floor	Provided	MR
	 Location of Repeater 	NA	NA	NA
	Panel	NA	Provided	NA
	 Alternate source of 	NA	Provided at	NA
	power		entrance	
	 Hooters' Location 			
8.	MOEFA	Required	Provided	MR
9.	Public Address System	NA	NA	NA
10.	Automatic Sprinkler System con	nmon with the m	all	
	Basements	NA	Provided	NA .
	• Upper Floor	Required	Provided	MR
	Sprinkler above false	Required	Provided	MR
	ceiling	1		
11.	Internal Hydrants: common with	the mall		
	Sing - F / 1	150 mm	Provided	MR
	• Size of riser/down-	150 mm	Provided	MR
	comer	-+	Fiovided	17117
	Number of hydrants per floor	4	Provided	MR
		7	TTOVIGEG	IVIIX
12.	Yard Hydrants common with the	a mall		
12.	Taig Tryurains common with the	e man		
		NA	6 Provided	NA
	Total number of	1 1 1 2-4	OTTOVICE	INA
	Total number of hydrants	NA	6 Provided	NA

13. Pumping Arrangements: Common with the mall						
	Ground Level		1500 T D) 1	D.T.A.		
	 Discharge of main pump 	NA	4500 LPM	NA		
	Head of main pump	NA	60 mtr	NA		
	Number of main pumps	NA	03 pumps	NA		
	Jockey pump out put	NA	Two 180	NA		
			LPM each			
	Jockey pump head	NA	60 mtr	NA		
	Standby Pump out put	NA	4500lpm	NA		
	Standby Pump Head	NA	60 mtrs	NA		
	Auto Staring/Manual stopping	NA	Provided	NA		
	> Pump House Access	NA	Provided	NA		
	m 1 1	NA	Tiovided	1111		
		450 LPM	Provided	MR		
	Discharge of pump		Provided	MR		
	> Head of the pump	40 mtr		MR		
	> Power supply	Provided	Provided	MR		
	> Auto starting of pump	Required	Provided	IVIIV		
14.	Captive water Storage for fire fig	ghting: Common	with the mall	NIA		
	 Under ground tank 	3 lacs ltrs	3 Lac Ltrs	NA		
	capacity	NA	Provided	NA		
	Draw off connection	NA	Provided	NA		
	Fire service inlet	NA	Provided	NA		
	Access to tank	10, 000 litres	30 KL	MR		
	 Overhead Tank capacity 		Provided			
15	Exit Signage	Required	Provided	MR		
16		Common w	ith the mall			
	Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of lift lobby	Required	Provided	MR		
	Communication in lift Car	Required	Provided	MR		
	Fireman's Grounding	Required	Provided	MR		
	Switch > Lift Signage	Required	Provided	MR		
17	. Standby power supply	Required	Provided	MR		
18						
	> Total area	NA	NA	NA		
	Location	NA	NA	NA		
19	Fire control room Common with the mall					
		NA R	Provided	NA MIR IN		
	Detector system panel	NA NA	Provided	NA		
	Flow Switch Panel		Provided	NA		
	> PA System Panel	NA 10	Provided	NAMIR V		
	Battery backup	NA R	Provided	NA NA		
	Building Floor Plans	NA	TTOVICE	1111		

C.

Special Fire Protection	Cristanas					
For Protection of spec fany;		NA .	NA	NA		
ound functional at the In view of the d re safety as requ 6/DFS/MS/EH/2013/	time of insperenced compared under WZ/522 date	ection. bliance of minin the rules th ed 08-07-2013	num standards e NOC issu	on fire prevention and led vide letter no.		
ignature of the Inspec	ing Officer		Signat	ture of the Inspecting		
Officer Name Uday VIT Digh			Name			
esignation AD	o/wp		Desig	nation		
Dy. 460	38/5		A 20 1			
	The fire protection of functional at the In view of the dre safety as requisioned for Service Rules 2010 ignature of the Inspection of the	The fire protection systems and functional at the time of inspection of the deemed compare safety as required under 6/DFS/MS/EH/2013/WZ/522 date are Service Rules 2010 is recommendative of the Inspecting Officer of the Inspect	The fire protection systems provided in the bound functional at the time of inspection. In view of the deemed compliance of miniming resafety as required under the rules the S/DFS/MS/EH/2013/WZ/522 dated 08-07-2013 for Service Rules 2010 is recommended. Service Rules 2010 is recommended. The fire protection of the inspection of the	The fire protection systems provided in the building wound functional at the time of inspection. In view of the deemed compliance of minimum standards re safety as required under the rules the NOC issum 6/DFS/MS/EH/2013/WZ/522 dated 08-07-2013 renewal under the Service Rules 2010 is recommended. Signature of the Inspecting Officer Signature of the Inspecting Officer Signature of the Inspecting Officer Designation Designation		