

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/SZ/2016 /1799

Dated: 20/12/16

FIRE SAFETY CERTIFICATE

Certified that M/s **Tripti Restaurant & Catering Services, A-67/1, Mahipalpur Extension, NH-8, New Delhi**, building comprised of Basement, Ground plus two upper floors (Restaurant running at ground floor only) was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2013/SZ/1077 Dated 15/10/2013. The premises was re-inspected by the officer concerned of this department on 22.11.2016 in the presence of Mr. Rajesh Khanna, (GM) of the restaurant and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "**Assembly Building**" (Restaurant) with effect from 20/12/16 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 20/12/16 at New Delhi by


Vipin Kental
Chief Fire Officer

Copy to: -

1. M/s Tripti Restaurant & Catering Services,
A-67/1, Mahipalpur Extension, NH-8, New Delhi-110037
2. The DHO, Public Health Department, Najafgarh Zone, M.C.D, New Delhi-110043

Conditions for the validity of Fire Safety Certificate

1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
4. The basement shall be used strictly as per the provisions of Building Bye Laws.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1	Name & Address of the Building	Tripti Restaurant & Catering Services, A-67/1, Mahipal Pur Extension, New Delhi-110037 (Existing in Hotel Shanti Place)		
2	Type of Occupancy	Assembly Building "Group-D" Restaurant		
3	Building Comprised of	Basement, Ground + 02 upper floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/EH/2013/SZ/1077 Dated 15/10/2013		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	22.11.2016		
8	Name of the Inspecting Officers	ADO R.N. Singh		
9	Name & Designation of Officers from the building side	Mr. Rajesh Khanna (GM)		
10	Year of construction	2000-01	Restaurant is running at ground floor only (There are two halls. One is used as bar-room and other as family zone. Also there are offices, kitchen cafeteria and business center at ground floor)	
11	Applicant letter No.	Nil dated 05/10/2016		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC 29/09/2005 Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building. <i>FSC issued Hotel Shanti Place Letter No: FG/DFS/MS/GH/2016/SZ/1077 dated 22.11.2016</i>			
	• Road width	9 mtr	20 mtr	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, width, type and arrangements of exits. [Provided by maintained by Hotel management]			
	a. Number of Staircase			
	• Upper floors	Restaurant within Hotel	As Above	NA
	• Basement floor	Restaurant within Hotel	As Above	N/A
	b. Width of Staircase			
	• Upper floors	Restaurant within Hotel	As Above	N/A
	• Basement floor	Restaurant within Hotel	As Above	N/A
	c. Protection of exits			
	• Fire check door	Restaurant within Hotel	As Above	N/A
	• Pressurization	Restaurant within Hotel	As Above	N/A
	d. No. of continuous staircase to terrace	Restaurant within Hotel	As Above	NA
	e. Width of corridor	Restaurant within Hotel	As Above	N/A
	f. Door size	Old Case	1.10 m x 2 (final exit)	MR
3	Compartmentation.	Provided by maintained by Hotel management		
	• Fire check door.	Restaurant within Hotel	As Above	N/A
	• Sealing of electrical shafts.	Restaurant within Hotel	As Above	N/A
	• Fire rating of shaft door.	Restaurant within Hotel	As Above	N/A
	• Water curtain	Restaurant within Hotel	As Above	N/A
	• Fire dampers.	Restaurant within Hotel	As Above	N/A
4.	Smoke Management system.	Provided by maintained by Hotel management		
	• Basement	Restaurant within Hotel	As Above	N/A
	• Upper floors	Restaurant within Hotel	As Above	MR
5.	Fire Extinguishers.			
	• Total numbers	12 No's	12 Nos.	MR
	• Types	ISI Marked	ABC-08 & Co2-04	MR
	• ISI Marking		Provided	MR
6.	First Aid Hose Reels.	Provided by maintained by Hotel management		
	• Total numbers on each floor.	One (Near to Restaurant)	As Above	MR
	• Length of hose-reel hose.	30 mtr	As Above	MR
	• Nozzle Diameter	05 mm	As Above	MR

7	Automatic Fire Detection and Alarming system. [Provided by maintained by Hotel management]			
	• Type of detectors	N/A	As Above	N/A
	• Location of Main Panel	N/A	As Above	N/A
	• Location of Repeater Panel	N/A	As Above	N/A
	• Alternate source of power	N/A	As Above	N/A
	• Hooter's location	N/A	As Above	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	As Above	N/A
10.	Automatic Sprinkler System	Provided by maintained by Hotel management		
	• Basement	N/A	As Above	N/A
	• Upper floors	N/A	As Above	N/A
	• Sprinkler above false ceiling	N/A	As Above	N/A
11.	Internal Hydrants.	Provided by maintained by Hotel management		
	• Size of Riser/Down-comer	100 mm (Near to Restaurant)	As Above	MR
	• Number of Hydrant per floor	One (Near to Restaurant)	As Above	MR
	• Hose box.	One (Near to Restaurant)	As Above	MR
12.	Yard Hydrants.	Provided by maintained by Hotel management		
	• Total number of hydrants.	N/A	N/A	N/A
	• 2. Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.	Provided by maintained by Hotel management		
	• Ground Level			
	➤ Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	➤ Number of main pumps.	N/A	N/A	N/A
	➤ Jockey Pump output.	N/A	N/A	N/A
	➤ Jockey Pump head.	N/A	N/A	N/A
	➤ Standby Pump output.	N/A	N/A	N/A
	➤ Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting / Manual Stopping.	N/A	N/A	N/A
	• Terrace Level	Provided by maintained by Hotel management		
	➤ Discharge of pump.	900 LPM	As Above	MR
	➤ Head of pump.	40 mtr	As Above	MR
	➤ Power supply.	Required	As Above	MR
	➤ Auto starting of pump.	Required	As Above	MR
14.	Captive water storage for Fire Fighting.	Provided by maintained by Hotel management		
	• Underground tank capacity.	N/A	As Above	N/A
	➤ Draw-off connection.	N/A	As Above	N/A
	➤ Fire Service Inlet.	N/A	As Above	N/A
	➤ Access to tank.	N/A	As Above	N/A
	• Overhead tank capacity.	5,000 Ltr	As Above	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A


N/14

19.	Fire Control Room.	Provided by maintained by Hotel management		
	• Detector System Panel.	N/A	N/A	N/A
	• Flow Switch Panel.	N/A	N/A	N/A
	• PA system Panel.	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	N/A	N/A

The Fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2013/SZ/1077 Dated 15/10/2013, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended subject to compliance of the conditions as mentioned in the FSC

Accordingly, DFA is put up for approval and signature please.




Signature of the Inspecting Officer
 Name : R.N. Singh
 Designation: ADO

Renewal

Tripti Restaurant & Catering Services, A-67/1, Mahipalpur Extn.

Div. Officer (SD)



By [Signature]

[Signature]
9/12

Chf S/P

M. S. Cell

R. T. M.

[Signature]
13/12



443/Chf S2
 14/12/16/20/12