GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2016 / 17

Dated: 06 / 0 / /2017

FIRE SAFETY CERTIFICATE

Certified that the Queen Mary's School Northend locaded at Model Towm-Ill, Delhi-110009 comprised of Ground and 03 upper floors with separate basement owned/ occupied by Queen Mary's School Northend was granted Fire Safety Certificate vide this department letter no. F-6/DFS/MS/school/2012/4743 dated 21.12.2012, have deemed complied with the fire prevention and fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 20.12.2016 in the presence of Mrs. Anupma Singh/Principal and that the building/ premises is fit for occupancy class "Group B Educational" with effect from ... Object. Local for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.Delhigovt.nic.in

Issued on ... 06.01.2017 at New Delhi

Chief Fire Officer Ph:-011-23414250

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Director, Queen Mary;s School Northend, Model Town-Ill, Delhi-110009.

INSPECTION REPORT

1. Name & address of the building

: Queen Mary's School Northend, Model Town-Ill, Delhi-110009.

Type of Occupancy

:Educational

3. Type of Case

:Renewal, (Ground plus 03 Upper floor with separate basement)

4. Details of previous NOC

: F-6/ DFS/MS/School/2012/4743

5. Fire Safety directives letter No

: F.6/DFS/MS/06/2888 dated 11.02.2004.

6. Date of inspection

: 20/12/2016

7. Name of the Inspecting Officers

: ADO (RN) Rajesh Kumar

8. Name and designation of officers

from the building side

: Mrs. Anupma Singh (Principal)

9. Year of Construction

: 2003

10. Applicant's letter No.

: QMS/Fire/Deptt/2016/101 dated 25.10.2016

dated 21/12/2012

	Minimum Standards on fire prevention and fire safety U/R 33	DOE circular letter dated 01.03.2011	Provided at site	Remarks MR/NMR		
1	Access to building	01.03.2011				
	Road widthGate width	6m	12m	MR		
	Width of internal road	4.5m	06m	MR		
!		06m	06m	MR		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircasesUpper Floors	* 1	, v			
	Basements	04	06	MR		
	b. Width of staircases	02	02	MR(Old case)		
	Upper Floors					
	 Basements c. Protection of exits Fire check door 	1.50m	1.50m x 3 &1.53m	MR		
		1.50m	1.18m &97cm	MR(old case)		
	Pressurization	Required	Provided	MR		
	d. No. of continuous staircases to terrace	NA	NA	NA		
	e. Width of Corridor	02	02	MR		
	f. Door Size	Required	2.5m	MR		
		1 m	1.14 m(two door each class)	MR		

3	Compartmentation.			
	Fire check door	NA	NA	NA
	Sealing of electrical shafts	NA	NA	NA
	Fire Rating of shaft door	NA	NA	NA
	Water Curtain	NA	NA	NA
	Fire Dampers		- Laboratoria	
4	Smoke Management System.	NA	NA	NA
	Basements	30 a/c per hour	NA I	NA
	Upper floors	12 a/c per hour	Natural Ventilated	MR
		12 a/c per nour	Natural Ventilated	IVIK
5	Fire Extinguishers			
	Total numbers	35 nos	49 nos	MR
	• Types	ABC/Co2	ABC49	MR
	ISI marking	ISI Marked	Yes	MR
6	First-Aid Hose Reels.			-
	Total numbers on each floor	02	02no	MR
	 Length of hose reel hose 	30m	30m	MR
	Nozzle diameter	5mm	5mm	MR
7	Automatic fire detection and alarming syst		Jillii	IVIK
	Type of detectors	NA	NA	NA
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
8	MOFFA			
9	MOEFA Dublic Address Senders	NA	NA NA	NA
	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
	Basement	Required NA	Provided NA	MR NA
	Upper Floor	NA	NA NA	NA NA
	Sprinkler above false ceiling	NA NA	INA	NA
11	Internal Hydrants			
	Size of riser/down-comer	100mm	100mm	MR
	Number of hydrants per floor Head Poys	2	Provided	MR
	Hose Box	2	Provided	MR
12	Yard Hydrants.		the state of the s	

N	1	0
N	1	ı

	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put		N/A	N/A	
	> Standby Pump Head	N/A			
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A	
	Terrace level	N/A	N/A	N/A	
	Discharge of pump				
	> Head of the pump	900 lpm	900 lpm	MR	
	> Power Supply	40m	40m	MR	
	Auto Starting of pump	Required	Provided	MR	
		Required	Provided	MR	
14	Captive Water Storage for fire fighting.				
	Underground tank capacity	50000 ltr	100000 ltr.	MR	
	 Underground tank capacity Draw-off connection 	NA	NA	NA	
	> Fire service inlet	NA	NA	NA	
	> Access to tank	NA	NA ·	NA	
	Overhead Tank capacity	10,000 ltrs	25,000ltrs	MR	
15	Exit Signage	Required	Provided	MR	
16	Provision of Lifts.		0	3.7/4	
10	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	

11/17

17	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A	

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part 4, the FSC issued vide letter of even no 4743 dated 21.12.2012 renewal under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.

Signature of the Inspecting Officer

Name :- Rajesh Kumar

Designation:- ADO/RN

DOIN/NO Shyh 26.12.16

Dy CPO(W2)

6