## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ / 5 2

Dated: 12/01/17

## **FIRE SAFETY CERTIFICATE**

Certified that the Adarsh Shri Ram Vidya Mandir, Chetan Vihar, Gopal Nagar, Near Rail Factory, Gopal Nagar Extn., Najafgarh, New Delhi-110043, comprised of ground floor plus one upper floor owned/occupied by the Shiv Charan Memorial & Education Society was issued FSC by this department vide letter no. F6/DFS/MS/School/2013/SZ/1254 dated 28.11.2013. The school was re-inspected by the officer concerned of this department on 22.12.2016 in the presence of Sh. Satish Yadav (Chairman) and found that Adarsh Shri Ram Vidya Mandir have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- The Manager, Adarsh Shri Ram Vidya Mandir, Chetan Vihar, Gopal Nagar, Near Rail Factory, Gopal Nagar Extn., Najafgarh, New Delhi-110043.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT Adarsh Shri Ram Vidya Mandir, Chetan Vihar, Gopal Nagar, Near Rail 1. Name & address of the building: Factory, Gopal Nagar Extn., Najafgarh, New Delhi-110043. Educational 2. Type of Occupancy 3. Type of Case Renewal 4. Details of Previous NOC F6/DFS/MS/School/2013/SZ/1254 dated 28.11.2013 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 22.12.2016 7. Name of Inspecting Officer : A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. Satish Yadav (Chairman) 9. Year of Construction 2002 : Nil dated 24.11.2016 10. Applicant's letter No. Dir. Of Edu. Provided at Remarks S. No. Minimum Standards on fire prevention and MR/NMR Circular dt. site fire safety U/R 33 01.03.2011 Access to building 1. M/R, being old case Old Case 5.5 mtrs Road width N/A 03 mtrs N/A Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors 02 No.'s 02 No.'s MR Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms/additional 120 & 115 cms M/R, being old case Basements staircase of 75 cms if less than 150 cms c. Protection of exits N/A N/A N/A Fire check door Pressurization N/A N/A N/A N/A N/A N/A d. No. of continuous staircases to terrace N/A Width of Corridor N/A One Door Size 150 cms 180 cms MR Old Case M/R, (students are 90 cms less than 45 in each class room) Compartmentation 3. N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. **Smoke Management System** N/A N/A N/A Basement Natural MR Required Upper floors ventilation 5. Fire Extinguishers Provided 04 no's MR Total numbers Provided MR Types ABC type IS marking ISI marked Provided MR First-Aid Hose Reels 6. N/A N/A N/A Total numbers on each floor N/A N/A N/A Length of hose reel hose Nozzle diameter N/A N/A N/A

	P			0
7.	Automatic fire detection and alarming system	NI/A	N/A	N/A
	Type of detectors	N/A		N/A
	Location of Main Panel	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A Provided	N/A N/A
9.	Public Address System	N/A	Provided	IN/A
10.	Automatic Sprinkler System     Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A .	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	7711	27/4	DI/A
	Total number of hydrants	N/A	N/A N/A	N/A N/A
	Hose Box	N/A	N/A	IN/A
13.	Pumping Arrangements			
	<ul><li>Ground Level</li><li>Discharge of main Pump</li></ul>	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
1 2 1	Number of main pumps			N/A
	> Jockey Pump out put	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A
. 1145	Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
	, rate stateing reasons are pro-	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			The Part of the Pa
	Discharge of pump	N/A	N/A	N/A
	<ul><li>Head of the pump</li><li>Power Supply</li></ul>	N/A	N/A	N/A N/A
	> Auto Starting of pump	N/A	N/A N/A	N/A N/A
		N/A	IN/A	IVA
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
15.	Exit Signage.			
16.	Provision of Lifts.			(No Lift)
		NI/A	N/A	N/A
	Pressurization of Lift Shaft  Pressurization of Lift lobby	N/A	3000	
	<ul><li>Pressurization of Lift lobby</li><li>Communication In lift Car</li></ul>	N/A	N/A N/A	N/A N/A
	Fireman's Grounding Switch	N/A		N/A
	Lift Signage	N/A	N/A	
	2 2.6	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area			
	> Total Area	N/A	N/A	N/A
	> Location	NI/A	N/A	N/A

19.	Fire Control Room     Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2013/SZ/1254 dated 28.11.2013 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per the letter submitted by the Chairman there are less than 45 students in each classroom (placed at C-69).

Saudant

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

D.O. (South West)

23/12/16

28/17/6 3/ 1746 3/

Cfo CT

3/12 FTM:

m-scell 4/1

F.T. letter is put up for signature

sandest 7