GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/GH/2017/SZ/ 63

Dated: ../6/1//7

FIRE SAFETY CERTIFICATE

Issued on 16/1/17 at New Delhi by

Vipin Kental Chief Fire Officer

Copy to: -

- 1. M/s Hotel Kabli Guest House, 73, Masjid Road, Jangpura, Bhogal, New Delhi-110014
- 2. The Joint Commissioner of Police (Lic.), 1st Floor, PS Defence Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

1		INSPECT	ON REPORT			
1	N	ame & Address of the Building	Hotel Kabli G	uest House, 73, Masjic	l Road,	
			Jangpura, Bho	gal, New Delhi-11001	4	
2		ype of Occupancy	Residential & Lodging, Group-A (Guest House)			
3		uilding Comprised of	Ground + 1 upper floor			
4		ype of Case	Renewal			
5		etails of Previous NOC	F.6/DFS/MS/GH/2013/SZ/1206 dated 14/11/2013			
6		ire Safety Directives Letter No	Nil			
7		ate of Inspection	09.12.2016			
8		ame of the Inspecting Officers	ADO R.N. Singh			
9		ame & Designation of Officers	Mr. Indervir Sin	ngh Manager		
	from the building side			_		
10	Year of construction		1948 Ground floor- Reception + 10 guest rooms,			
11	1	1	First flo	First floor- 08 guest rooms (Total- 18 G/rooms)		
11 C. N.	A	pplicant letter No.	Nil Dated 21.11.2016			
S. No		inimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks	
	an	d Fire Safety U/R 33	Dt. 16/01/2009	2	MR/NMR	
1	A .	ages to Duild's	Requirement			
	A	1. Road width.	D : 1			
		2. Gate width	Required	More than 06 mtr	MR	
		3. Width of internal road	N/A	N/A	N/A	
2	N.		N/A	N/A	N/A	
	a.	umber, width, type and arrangements o Number of Staircase	I exits.			
	a.	Upper floors	D 1	1031.1		
		Basement floor	Required N/A	2 No's	MR	
	b.	Width of Staircase	N/A	N/A	N/A	
	D.		D : 1			
		opper moors.	Required	1.0 mtr each	MR	
	-	Buscinent 11001.	N/A	N/A	N/A	
	c.	Protection of exits	77/1			
		Fire check door	N/A	N/A	N/A	
	_	Pressurization	N/A	N/A	N/A	
	1	No. of continuous staircase to terrace	Required	1 No	MR	
	e.	Width of corridor	N/A	N/A	N/A	
2	f.	Door size	N/A	1.15 m (Final exit)	N/A	
3	Co	mpartmentation.				
		 Fire check door. Sealing of electrical shafts. 	N/A	N/A	N/A	
		8	N/A	N/A	N/A	
		3. Fire rating of shaft door.4. Water curtain.	N/A	N/A	N/A	
		5. Fire dampers.	N/A	N/A	N/A	
4	C		N/A	N/A	N/A	
4.	3m	oke Management system. 1. Basement	37/4			
			N/A	N/A	N/A	
5.	D:-	11	N/A	Natural Ventilation	N/A	
J.	rif	e Extinguishers. 1. Total numbers	D:	00.31.3	1	
		2. Types	Fire	08 No's	MR	
		3. ISI Marking	Extinguisher	ABC- 05 & Co2-03	MR	
6.	Fir	st Aid Hose Reels.		Provided	MR	
U.	A 11	Total numbers on each floor.	Hose reel	0	1100	
			nose reel	One	MR	
1	- 1	2. Length of hose-reel hose.		30 m	MR	
		3. Nozzle Diameter		05 mm	IVIIX	

Hotel Kabli at 73, Masjid Moth, Jangpura, Bhogal, ND

7	Automatic Fire Detection and Alarmin	ng system.						
	Type of detectors	N/A	N/A	N/A				
	2. Location of Main Panel	N/A	N/A	N/A				
	3. Location of Repeater Panel	N/A	N/A	N/A				
	4. Alternate source of power	N/A	N/A	N/A				
	5. Hooter's location	N/A	N/A	N/A				
8.	MOEFA	Required	Provided	MR				
9.	Public Address System	Required	Provided	MR				
10.	Automatic Sprinkler System	requires	11071404	17112				
	1. Basement	N/A	N/A	N/A				
	2. Upper floors	N/A	N/A	N/A				
	3. Sprinkler above false ceiling	N/A	N/A	N/A				
11.	Internal Hydrants.	1 1 1 1 1 1	1771	11///				
	1. Size of Riser / Down-comer	N/A	N/A	N/A				
	2. Number of Hydrant per floor	N/A	N/A	N/A				
	3. Hose box.	N/A	N/A	N/A				
12.	Yard Hydrants.	11/14	IV/A	11/74				
14.	1. Total number of hydrants.	N/A	N/A	N/A				
	2. Hose box.	N/A	N/A	N/A				
13.	Pumping arrangements.	11/71	11/71	IN/A				
13.	a) Ground Level							
		N/A	N/A	N/A				
	Discharge of main pump.	N/A	N/A	N/A				
	> Head of main pump.	N/A	N/A	N/A				
	Number of main pumps.	N/A N/A						
	> Jockey Pump output.		N/A	N/A				
	Jockey Pump head.	N/A	N/A	N/A				
	Standby Pump output.	N/A	N/A	N/A				
	Standby Pump head.Auto Starting/Manual Stopping.	N/A	N/A	N/A				
	Auto Starting/Manual Stopping.Pump House Access	N/A	N/A	N/A				
		N/A	N/A	N/A				
	b) Terrace Level							
	Discharge of pump.	Required	225 LPM	MR				
	Head of pump.	Required	40 mtr	MR				
	Power supply.	Required	Provided	MR				
	> Auto starting of pump.	Required	Provided	MR				
14.	Captive water storage for Fire Fighting		1 2 7 / 1					
	 Underground tank capacity. 	N/A	N/A	N/A				
	 Draw-off connection. 	N/A	N/A	N/A				
	Fire Service Inlet.	N/A	N/A	N/A				
	 Access to tank. 	N/A	N/A	N/A				
	 Overhead tank capacity. 	Required	2,500 Ltr.	MR				
15.	Exit Signage.	Required	Provided	MR				
16.	Provision of Lifts.							
	 Pressurization of lift shaft. 	N/A	N/A	N/A				
	 Pressurization of lift lobby. 	N/A	N/A	N/A				
	 Communication in lift car. 	N/A	N/A	N/A				
	• Fireman's switch.	N/A	N/A	N/A				
	Lift signage.	N/A	N/A	N/A				
17	Standby Power Supply	Required	Provided	MR				
18.	Refuge Area	Troquited	TIOTIGO	IVIIC				
10.	Total area	N/A	N/A	N/A				
	• Location	N/A	N/A N/A	N/A N/A				
	• Location		73, Masjid Moth, Jang					

19.	Fire Control Room.						
	Detector System Panel.	N/A N/A	N/A				
	Flow Switch Panel.	N/A N/A	N/A				
	 PA system Panel. 	N/A N/A	N/A				
	Battery backup	N/A N/A	N/A				
	Building floor plan	N/A N/A	N/A				
20.	Special Fire Protection System for the Protection of special Risk, if any.						

The Fire Protection system provided in the building were randomly checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2013/SZ/1206 dated 14/11/2013 renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name

: R.N. Singh

Designation: ADO

Renewal

Hotel Kabli at 73, Masjid Moth, Jangpura, Bhogal, ND

Div. Officer (SD)

108C)

dy cocses

Cho (52)

28/12