GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F6 10F5 | ms/ EH/2017/320

Dated: 06 03 2017

FIRE SAFETY CERTIFICATE

(Vipin Kental)
Chief Fire Officer

T.No.011-23412225

Copy to:- 1. Joint C.P. Licensing, 1st Floor, Police Station, Defence Colony, New Delhi.

2. M/s "McDonald's Family Restaurant" located at BG-02, Ground Floor, Ansal Plaza Shopping Arcades at Hudco Place at Pinira Pole, Andrewsganj, New Delhi.

Conditions for the validity of fire safety certificate are as under:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. The employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All fire fighting equipments shall be maintained in perfect working condition all time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate, six month prior to its expiry.

NIII

1	Name & address of the building					
. 1	rvanie & address of the building	M/s McDonald's Family Restaurant located at BG-02, Ground Floor, Plaza Shopping Arcades at Hudco Place at Pinjra Pole, Andrewsga Delhi.				
Type of Occupancy						
3	Building comprised of	Two tier basements, Ground Mezzanine plus three upper floors. But restaurant is at ground floor only.				
4	Type of case	Renewal				
5	Details of previous NOC	No. F6/MS/DFS/EH/2014/SZ/526, Dated 28.04.2014.				
6	Fire safety directives letter No	Nil.				
7	Date of inspection					
8	Name of the inspecting Officers :	17.02.2017.				
9	Name and designation of officers	ADO Vedpal Sh. Parshant, Dy. Manager.				
	from the building side	John Farsharit, Dy. Manager.				
10	Year of construction	1997-1999				
11	Applicant's letter No.	Nil, dated 27.01.2017.				
NO.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements /Existing Fire Protection System as per Old NOC	Provided at site	Remarks MR / NMR		
1	Access to building					
	1) Road width	Required	12m	MR		
	Sate width Width of internal road	Required	5m	MR		
	3) Width of Internal load	Required	Provided as per approved plans	MR(old case)		
2	Number, width Type & arrangeme	nt of exits	V			
	a. Number of staircases					
	1. Upper floors	N/A	N/A	N/A		
	2. basements	N/A	N/A	N/A		
	b. Width of staircase					
	1. Upper floors	N/A	N/A	N/A		
	2. basements	N/A	N/A	N/A		
	c. Protection of exits			111/7		
	1. Fire check door	Required	Provided	MD		
	2. Pressurization	N/A	N/A	MR N/A		
	d. No. of continuous staircase to terrace		04Nos(One in A Block, One in B Block & Two in C Block)			
	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	Required 02 Exits	1m & 1.90m (two exits)	MR(old case)		
3	Compartmentation.		y 4			
	1. Fire check door	Required	Provided	MR		
	2. Sealing of electrical shafts	Required	Provided	MR		
	3. Fire Rating of shaft door	Required	Provided	MR		
	4. water curtain	N/A	N/A	N/A		
1	5. Fire dampers	N/A	N/A	N/A		
+	Smoke Management system. Basement	30 a/c per hour		T		
		12 a/c per hour	N/A	N/A		
	Upper floors	1	Exhaust Fans Provided	MR		
5	Fire Extinguishers total numbers	OGNICO	00 N D			
		06Nos ABC, CO2, WCO2	06 Nos.Provided ABC, CO2, Water CO2,	MR		
		ICI		MR		
6	101 Harking	(Fire fighting system is comm	Provided on for entire mall building)	MR		
			02nos (Near restaurant)	MR		
			30 Mtr Provided	MR		
		5mm	5 MM Provided	MR		

f

11/12

	Type of detectors	Smoke & Heat	Smoke & Heat	Tues.
	location of Main Panel	Ground Floor	Ground Floor	MR
	location of Repeater panel			MR
		N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
8	hooter's location MOEFA	Required	All Areas	MR
		Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.	(Fire fighting system is co	mmon for entire mall building)	
		N/A	N/A	N/A
	upper floors sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants	N/A	N/A	N/A
	Size of riser/down-corner	(Fire fighting system is co	mmon for entire mall building)	
	Number of Hydrants per floor	150 mm	150mm Provided	MR
		02nos. (Near restaurant)	02nos (Near restaurant).	MR
	hose Box	02nos. (Near restaurant)	02nos. (Near restaurant)	MR
12	Yard Hydrants.	(Fire fighting system is cor	mmon for entire mall building)	
	total number of hydrants	08 Nos	08 Nos. Provided	IMR
2	house box	08 Nos.	08 Nos Provided	MR
3	Pumping arrangements (Fire fig	ihting system is common fo	r entire mall building)	
	1. Ground level			
	a. Discharge of main Pump	Required	4050 LPM Provided	MR
	b. Head of main pump	Required	90m	MR
	c.Number of main pumps	Required	02nos.	MR
	d.jockey pump out put	Required	450LPM	MR
	e jockey pump head f. Standby Pump output	Required	90m	MR
	g Stanby Pump head	Required	8100 LPM Provided	MR
		Required	90m	MR
	h.Auto Starting/Manual stopping pump house access	Required	Provided	MR
	2.Terrace level	Required	Provided	MR
	a. Discharge of pump	N1/0		
	b. head of the pump	N/A N/A	N.A.	N.A.
	c. Power supply	N/A	N.A.	N.A.
	d. Auto starting of pump	N/A	N.A.	N.A.
4	Captive water storage for fire		mon for entire mall building)	N.A.
	fighting	the agraining dysterm is com-	imon for entire mail building)	
	Underground tank capacity	450000 ltr	4.50.000 Lts Dazvidad	Taris .
	a. Draw-off connection	Required	4,50,000 Ltr·Provided Provided	MR
	b. fire service inlet	Required	Provided	MR
	c. Access to tank	Required	Provided	MR MR
	d. Over head tank Capacity	20,000 ltr	20,000 ltrs on AB Block &	MR
	* 13		30000 Itrs on C Block	IVII .
5	Exit Signage.	Required	Provided	MR
;	Draviale 6 1/6			
)	Provision of lifts.			
	a. Pressurization of lift shaft b. Pressurization of lift lobby	N/A	N/A	N/A
	c. Communication in lift car	N/A	N/A	N/A
	d. Fireman's grounding switch	Required	Provided	MR
	e. Lift signage	Required	Provided	MR
	Standby power supply	Required	Provided	MR
	Refuge Area.	Required	DG Set Provided	MR
	total area	NI/A	lation .	
	location	N/A N/A	N/A	N/A
		Vetom is occurred to	N/A	N/A
-	Fire control room. (Fire fighting s a. Detector system Panel	Poguired		
	b. Flow switch Panel	Required	Provided	MR
	c. PA system Panel	N/A Required	N/A	N/A
	d. Batter backup	Required	Provided Provided	MR
	Id. Daller Dackiiii			MR

NIB

20 Special Fire Protection systems for protection of special risks, if any:

CO2 & ABC Type Fire Extingushers Provided near Electric Panel=MR

The fire protection systems provided in the building were checked and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC issued vide letter No.F.6/MS/DFS/EH/2014/SZ/147, dated 30.01.2014 renewal under rule 37 of the Delhi Fire Service Rule 2010 is recommended.

Accordingly DFA is put up for kind consideration please

Signature of the inspecting officer

Name: Vedpal

Designation: ADO(SJ) If the Ansed Plaza Shopping Breade has been issued free by this class. If yes the copy of same Need Jul Love Rosubmilted phane