## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. FG/DF3/ms/2017/schal/433

Dated: 22/03/17

## FIRE SAFETY CERTIFICATE

Issued on at New Delhi by

(Vipin Kental) Chief Fire Officer

Ly

To:-

Mr. Ram Dhani (Manager) M/s Saraswati Vidya Public School C-1, Gali No. 1, Milan Garden, Sabhapur, Delhi 110094

Copy:-

The Dy. Director of Education, B–Block, Yamuna Vihar, Delhi-110053

## **CONDITIONS**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form `J` [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building

: Saraswati Vidya Public School, C-1, Gali no.-1, Milan Garden, Sabhapur, Delhi-110094

2. Building is comprised of

: Ground floor only

3. Type of Occupancy

: Educational

Type of Case

Renewal

4. Details of Previous NOC letter

: F.6/DFS/MS/School/2014/NDZ/228 dated-20/11/14

Fire Safety directive letter No.

: F16/Estate/CC/Fire Safety/2011/3298 to 3398

Dated 01/03/11

6. Date of Inspection

: 10/02/2017

7. Name of the Inspecting officers

: ADO V. B. Yadav

8. Name and designation of Officer

from the building side

: Mr. Ram Dhani (Manager)

9. Year of Construction

: 2009

10. Applicant's letter No

: Letter No.-Nil, Dated- 30/01/2017

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Circular Requirement	Provided at Site	Remarks MR/NMF				
)1	Access to Building.							
	Road width	06 mtr.	06 mtr.	MR				
	Gate width	N/A	N/A	N/A				
	Width of internal road	N/A	N/A	N/A				
)2	Number, Width, Type and Arrangement of Exits.							
et Laborat despire, terresis finale int	a. Number of Staircases							
	<ul> <li>Upper floor</li> </ul>	N/A	N/A.	N/A				
	Basement	N/A	N/A.	N/A				
	B. Width of Staircases		innere seneral i se Mohalita Strattari i relicase ha plene e negli i relicati se e teli sepo co telipinto i forcio	A I I A				
	<ul> <li>Upper floor</li> </ul>	N/A	N/A.	N/A				
	<ul> <li>Basement</li> </ul>	N/A	N/A	N/A				
	c. Protection of Exits		graves on the first of the firs	31/4				
	<ul> <li>Fire check door</li> </ul>	N/A	N/A	N/A				
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A				
	d. No. of Continuous Staircases	N/A	N/A	N/A				
	to Terrace e. Width of Corridor	1.50 mtr.	1.50 mtr.	MR				
	f. Door Size	01 mtr.	01 mtr.	MR				
)3	Compartmentation.							
	Fire check door	I N/A	N/A	N/A				
		N/A	N/A	N/A				
	<ul> <li>Sealing of electrical sharts</li> <li>Fire rating of shaft door</li> </ul>	N/A	N/A	N/A				
	Water curtain	N/A	NA	N/A				
	Fire dampers	N/A	N/A	N/A				
)4	Smoke Management System.							
	Basement	N/A	NA	N/A				
	Upper floor	N/A	N/A	N/A				
)5.	Fire Extinguishers.							
alia ya ina an ina ina ina ina ina ina ina ina	Total numbers	03 nos.	05 nos.	MR				
	Types	ABC /CO <sub>2</sub>	ABC /CO <sub>2</sub>	MR				
	IS marking	ISI marked	ISI marked	MR				

06	6 First-Aid-Hose Reels.						
	Total numbers on each floor	N/A	N/A.	N/A			
	<ul> <li>Length of hose reel hose</li> </ul>	N/A	N/A.	N/A			
	Nozzle diameter	N/A	N/A.	N/A			
07	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	<ul> <li>Location of repeater panel</li> </ul>	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
08	MOEFA	N/A	N/A	N/A			
09	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
er verken kannen		N/A	N1/A	N1/A			
	Basement	en di mandi metrigament mengang ang sempang ang permitang akan mengang dengan di kepang dalah pangkalan sejang	N/A	N/A			
	upper floor	N/A	N/A	N/A			
11	sprinkler above false ceiling     Internal Hydrants	N/A	N/A	N/A			
and desired in commen	size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
12	Yard Hydrants.	1477	\$ %F & %	1417			
Spokolač slovansk	Total number of hydrants	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	> Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	Head of main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	<ul> <li>Jockey pump out put</li> </ul>	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting /manual stopping	N/A	N/A	N/A			
	Pump house access	N/A	N/A	N/A			
	> Terrace Level	erressor arrest place successor accessor and majorist content companies to present and accessor and accessor accessor.					
	Discharge of pump	N/A	N/A.	N/A			
	Head of the pump	N/A	N/A.	N/A			
	Power supply	N/A	N/A.	N/A			
	Auto starting of pump	N/A	N/A.	N/A			
114	Captive Water Storage for Fire Fighting.						
Yayab (Alter equals)	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	<ul> <li>Access to tank</li> </ul>	N/A	N/A	N/A			
	Overhead tank capacity	N/A	N/A.	N/A			
5	Exit Signage.	N/A	N/A.	N/A			
6	Provision of Lifts.			interior de describer de la professiona de la composition della co			
and the second section	Pressurization of lift shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			
	Communication in lift car	N/A	N/A	N/A			
	Firemen's grounding switch	N/A	N/A	N/A			
	Lift signage	N/A	N/A	N/A			
	- Lin signage	1417	14/7	I W/M			

7 Standby Poyer Supply	N/A			
8 Refuge Ar	the same of the sa	N/A	N/A	
• Mal area			and the second second second second second second	
ocation	N/A	N/A	a contract of the same of the	
The second secon	N/A	N/A	N/A	
9 Fire Filtroi Room	and provided the second	A Secretaria de Companyo de Co	N/A	
Detector system panel		5.1		
7 FIOW switch panel	N/A	N/A	N/A	
* PA system panel	N/A	N/A	N/A	
Battery backup	N/A	N/A	The state of the s	
Building floor plans	N/A	N/A	N/A	
Special Fire Protection	N/A	The second of the factor of the second of th	N/A	
Special Fire Protection Systems for Protection of Special Risks, if Any:	for N/A	N/A	N/A	
Protection of Charles	i was i	N/A	N/A	

The fire protection systems provided in the school building were tested/checked at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the circular no. F16/Estate/CC/Fire Safety/2011/3298to3398 dated 01/03/11 issued by Director of Education, it is recommended to grant Fire Safety Certificate.

> Signature of Relinspecting Officer Name - V. B. Yadav

Designation- A.D.O (Tahirpur)