GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI <u>HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001</u> Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/2017/SZ/ 467

Dated: .28(.03/1.)

FIRE SAFETY CERTIFICATE

Certified that the Smoke House Deli Restaurant located at Shop No-125, Ground floor, DLF Place, Plot No-3, Nelson Mandela Marg, Vasant Kunj, New Delhi, building comprised of Two tier basement, Lower Ground floor, Upper Ground floor, 1st floor and Projection room was granted FSC by this department vide letter No. F.6/DFS/MS/2013/EH/384 dated 28-05-2013. The premises was re-inspected by the officer concerned of this department on 14-03-2017 in the presence of Mr. Deepak (Manager) and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "Assembly Building" (Restaurant) as above with effect from 28/03/12 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 29/03/17 at New Delhi by

424/3

Vipin Kental Chief Fire Officer

Copy to: -

Br onk

- 1. The Authorised Signatory, M/s Smoke House Deli Restaurant, Shop No-125, GF, DLF Place Mall, Plot No-3, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070
- 2. The joint C.P. (Lic.), First Floor, PS Defence Colony, New Delhi-110049
- 3. The DHO (South Zone), South MCD, Health Deptt. Green Park, New Delhi-16

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

| | - None | | | | |
|---------|---|---|-----------------------------------|--|--|
| 1 | | ION REPORT | | | |
| 1 | Name & Address of the Building | M/s Smoke House Deli Restaurant, Shop No. 125, GF, DLF Place, Plot No-3, Vasant Kunj, New Delhi-70 (A Unit of Dam Good Restaurants P Ltd) | | | |
| 2 | Type of Occupancy | | g "Group-D" Restaur | | |
| 3 | Building Comprised of | 2 tion Decement I | CE LICE 1st ELL D | ant | |
| 4 | Type of Case | Renewal | GF, UGF, 1 st Fl + Pro | ojection Room. | |
| 5 | Details of Previous NOC | | /T777/00 / T7 | | |
| 6 | | | 3/EH/384 Dated 28-05 | 5-013 | |
| | Fire Safety Directives Letter No | Nil | | | |
| 7 | Date of Inspection | 14-03-2017 | | | |
| 8 | Name of the Inspecting Officers | ADO R.N. Singh | | | |
| 9 | Name & Designation of Officers from the building side | Mr. Deepak (Manager) | | | |
| 10 | Year of construction | N/A Restt is running at Ground Floor only. | | | |
| 11 | Applicant letter No. | Nil dated Nil ODD No-1862 Dt. 17/02/2017 | | | |
| S. No | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Old NOC Dt. 28-05-2013 | Provided at Site | Remarks MR/NMR | |
| 1 | Access to Duilding IDLE Die Mall Est | requirement | | | |
| 1 | Access to Building. DLF Place Mall FS | Restaurant within | | 1 | |
| | Gate width Width of internal road | Mall Mall | As above | MR | |
| 2 | | D 11 10 151 | | | |
| | Number, width, type & arrangement of exits. | Provided & Main | ntained by DLF Place | Mall Mgmt. | |
| | a. Number of Staircase | B | | | |
| | Upper floors | Restaurant within M | 110 00010 | N/A | |
| | Basement floor | Restaurant within M | 110 00010 | N/A | |
| | b. Width of Staircase | Provided & Maintained by DLF Place Mall Mgmt. | | | |
| | Upper floors | Restaurant within M | all As above | N/A | |
| | Basement floor | Restaurant within M | all As above | N/A | |
| + | c. Protection of exits | Provided & Maintained by DLF Place Mall Mgmt. | | | |
| | Fire check door | Restaurant within Ma | all As above | N/A | |
| | Pressurization | Restaurant within Ma | | N/A | |
| | d. No. of continuous staircase to terrace | Restaurant within Ma | 115 400 10 | | |
| | e. Width of corridor | Restaurant within Ma | 110 00010 | N/A | |
| | f. Door size | 2m/1.5m | 14/11 | N/A | |
| | Door Size | 2111/1.5m | 2m, 1.5m & | MR | |
| 3 | Compartmentation. | Duovided 0 Mai | 0.99m | (old case) | |
| | • Fire check door. | Provided & Mair | ntained by DLF Place | | |
| | | Restaurant within Ma | 713 400 00 | N/A | |
| | Sealing of electrical shafts. Figure 1 and | | TESTOOTE | N/A | |
| | • Fire rating of shaft door. | Restaurant within Ma | 115 000 10 | N/A | |
| | Water curtain | Restaurant within Ma | 110 00010 | N/A | |
| 47 | • Fire dampers. | Restaurant within Ma | 115 00000 | N/A | |
| 4. | Smoke Management system. | Provided & Main | tained by DLF Place | Mall Mgmt. | |
| | Basement | 30 a/c per hour | As above | MR | |
| | Upper floors | 12 a/c per hour | As above | N/A | |
| 5. | Fire Extinguishers. | | | | |
| | Total numbers | 04 No's | 04 No's | MR | |
| | Types | | C-2, Co2-1, W.Co2-1 | MR | |
| | ISI Marking | | Provided | MR | |
| 6. | First Aid Hose Reels. | Provided & Main | tained by DLF Place | | |
| | Total numbers on each floor. | One (Near to Restt.) | Provided | MR | |
| | Length of hose-reel hose. | 30m | | | |
| | | | Provided | MR | |
| | Nozzle Diameter | 5mm | Provided | MR | |
| Renewal | . C. | noka Hausa Dali Da | W DIEDI II | ** | |

Renewal

Smoke House Deli Restt, DLF Place, Vasant Kunj, ND



| 7 | Automatic fire detection & alarming system. | Drovided & Main | tained by DLF Place | Mall Mon | |
|--------|---|---|-------------------------------|------------|--|
| | Type of detectors | N/A | As above | N/A | |
| | Location of Main Panel | N/A | As above | N/A | |
| | Location of Repeater Panel | N/A | As above | N/A | |
| | Alternate source of power | N/A | As above | N/A | |
| | Hooter's location | N/A | As above | N/A | |
| 8. | MOEFA | Required | Provided | MR | |
| 9. | Public Address System | N/A | As above | N/A | |
| 10. | Automatic Sprinkler System | | tained by DLF Place | | |
| | Basement | N/A | As above | N/A | |
| | Upper floors | N/A | As above | N/A | |
| | Sprinkler above false ceiling | N/A | As above | N/A | |
| 11. | Internal Hydrants. | Provided & Main | tained by DLF Place | Mall Mgmt. | |
| | Size of Riser/Down-comer | 100 mm | As above | MR | |
| | Number of Hydrant per floor | One (Near to Restt | | MR | |
| - | Hose box. | One (Near to Restt | | MR | |
| 12. | Yard Hydrants. | | tained by DLF Place | 1 | |
| | Total number of hydrants. | N/A | As above | N/A | |
| | Hose box. | N/A | As above | N/A | |
| 13. | Pumping arrangements. | | tained by DLF Place | | |
| 10. | • Ground Level | | | | |
| | Discharge of main pump. | N/A | As above | N/A | |
| | Head of main pump. | N/A | As above | N/A | |
| | > Number of main pumps. | N/A | As above | N/A | |
| | > Jockey Pump output. | N/A | As above | N/A | |
| | > Jockey Pump head. | N/A | As above | N/A | |
| | > Standby Pump output. | N/A | As above | N/A | |
| | > Standby Pump head. | N/A | As above | N/A | |
| | > Auto Starting / Manual Stopping. | N/A | As above | N/A | |
| ., | Access to pump house | N/A | As above | N/A | |
| | Terrace Level | Provided & Maintained by DLF Place Mall Mgmt. | | | |
| , | Discharge of pump. | 900 LPM | As above | MR | |
| - | > Head of pump. | 40 m | As above | MR | |
| - | Power supply. | Required | As above | MR | |
| | > Auto starting of pump. | Required | As above | MR | |
| 14. | Captive water storage for Fire Fighting. Provided & Maintained by DLF Place Mall Mgmt | | | | |
| | Underground tank capacity. | N/A | As above | N/A | |
| | > Draw-off connection. | N/A | As above | N/A | |
| | > Fire Service Inlet. | N/A | As above | N/A | |
| | Access to tank. | N/A | - As above | N/A | |
| | Overhead tank capacity. | 15,000 Ltr | As above | MR | |
| 15. | Exit Signage. | Required | Provided | MR | |
| 16. | Provision of Lifts. | | tained by DLF Place | | |
| | Pressurization of lift shaft. | N/A | As above | N/A | |
| | Pressurization of lift lobby. | N/A | As above | N/A | |
| | Communication in lift car. | IN/A | As above | N/A | |
| 3 | • Fireman's switch. | N/A | As above | N/A | |
| 1- | Lift signage. | N/A | As above | N/A | |
| 17 | Standby Power Supply | Required | Provided | MR | |
| 18. | Refuge Area | 27/4 | 27/4 | 37/4 | |
| | Total area | N/A | N/A | N/A | |
| enewal | • Location | N/A | N/A estt, DLF Place, Vasar | N/A . | |

Renewal

Smoke House Deli Restt, DLF Place, Vasant Kunj, ND



| 19. | Fire Control Room. | Provided & Maintained by DLF Place Mall Mgmt. | | |
|-----|---|---|----------|-----|
| | Detector System Panel. | N/A | As above | N/A |
| | Flow Switch Panel. PA system Panel. Battery backup Building floor plan | N/A | As above | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | N/A |
| 20. | | | | |

The Fire protection systems provided in the building were test checked and found functional at the time of inspection. Shortcomings issued vide letter no. F.6/DFS/MS/EH/2016/SZ/2932 dated 20/12/2016 has been complied.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/2013/EH/384 Dated 28-05-2013, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer
Name : R.N. Singh

July 13/17

Designation: ADO

Renewal

Smoke House Deli Restt, DLF Place, Vasant Kunj, ND

Div. Officer (SD)

fut repuils a copy of Mall FSC.

Quilarh 20/3/17

AD,