GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2017/ | 0 | 8

Dated: /3/7/17

FIRE SAFETY CERTIFICATE

Certified that M/s Vishesh Continental guest house located at 7A/12, WEA, Channa Market, Karol Bagh, New Delhi-110005, comprised of basement as Storage/ Hall, ground floor as reception & shops, first, second and third floor each having seven guest rooms and fourth floor having staff pantry in tin shed (Total 21 guest rooms), was issued FSC by this department vide letter no. F.6/DFS/MS/GH/2013/588 dated 12.02.2013. The guest house building was reinspected by the officer concerned of this department on 29-06-2017 in presence of Sh. B.S. Yadav, manager and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class residential (Guest house) w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 13/7/17 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

11/00/12/2012

Copy to: -

- 1. The Joint C.P..C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.
- 2. The Manager, M/s Vishesh Continental guest house, 7A/12, WEA, Channa Market, Karol Bagh, New Delhi-110005

INSPECTION REPORT

1. Name & address of the building : M/s Vishesh Continental, 7A/12, WEA, Channa Market,

Karol Bagh, New Delhi-05.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F.6/DFS/MS/GH/2013/588 dated 12.02.2013

5. Fire Safety directives letter No : N/A.

6. Date of inspection : 29-06-2017

7. Name of the Inspecting Officers: M.K. Chattopadhyay, Divisional Officer (South West), CDC

8. Name and designation of officers

Basements

Unner floors

from the building side : Mr. B.S. Yadav, manager

9. Year of Construction : Before 2010

10. Applicant's letter No. : nil dated 05.05.2017

S. No.	minimum Standards on fire prevention and fire safety U/R 33	Requirement as per letter No12.02.2013	Provided at site	Remarks MR/NMR				
1	Access to building							
T ELE	Road width	06 mts	Provided	MR				
	Gate width	05 mts	Directly accessible	MR				
	Width of internal road	N/A	N/A	N/A				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	-	-					
	Upper Floors	01	Provided	MR being old case				
	Basements	01	Provided	MR being old case				
	b. Width of staircases	-						
	Upper Floors	1.25 mts	1.26 mts.	MR				
	Basements	Old case	0.86 mt.	MR being old cas				
	c. Protection of exits	-	-	-				
		N/A	N/A	N/A				
	Fire check door	N/A	N/A	N/A				
	Pressurization No. of continuous staircases to terrace	01	01	MR				
	g. Width of Corridor	N/A	N/A	N/A				
	h. Door Size	Old case	0.90 mt.	MR being old cas				
3	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	Sealing of electrical shafts	N/A	N/A	N/A				
	Fire Rating of shaft door	N/A	N/A	N/A				
	Water Curtain	N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
4	Smoke Management System.							

30 a/c per hour

12 a/c per hour

MR

MR

Exhaust fan provided

Natural ventilation

5	Fire Extinguishers							
1	Total numbers	12	Provided	MR 🥓				
	• Types	CO ₂ , ABC type	Provided	MR				
	IS marking	ISI marked	Provided	MR				
6	First-Aid Hose Reels.							
	Total numbers on each floor	01	Provided	MR				
/	Length of hose reel hose	30 m	Provided	MR				
	Nozzle diameter	5 mm	Provided	MR				
7	Automatic fire detection and alarming		DT/A	27/4				
	Type of detectors	N/A	N/A	N/A				
	Location of Main Panel	N/A	N/A	N/A				
	Location of Repeater Panel	N/A	N/A	N/A				
	Alternate source of power	N/A	N/A	N/A				
	Hooters' Location	N/A	N/A	N/A				
8	MOEFA	Required	Provided	MR				
9	Public Address System.	Required	Provided	MR				
10	Automatic Sprinkler System.							
	Basement	Required	Provided	MR				
	Upper Floor	N/A	N/A	N/A				
	Sprinkler above false ceiling	N/A	N/A	N/A				
11	Internal Hydrants							
	Size of riser/down-comer	N/A	N/A	N/A				
	Number of hydrants per floor	N/A	N/A	N/A				
	Hose Box	N/A	N/A	N/A				
12	Yard Hydrants.							
	 Total number of hydrants 	N/A	N/A	N/A				
	Hose Box	N/A	N/A	N/A				
13	Pumping Arrangements.							
	Ground Level							
	Discharge of main Pump	N/A	N/A	N/A				
	➤ Head of Main pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	Jockey Pump out put	N/A	N/A	N/A				
	Jockey pump headStandby Pump out put	N/A	N/A	N/A				
	Standby Pump Head	N/A	N/A	N/A				
	> Auto Starting/ Manual	N/A	N/A	N/A				
	stopping	N/A	N/A	N/A				
	Pump House Access	N/A	N/A	N/A				

	Terrace level						
	> Discharge of pump	225 LPM	Provided	MR			
	> Head of the pump	30 mts	30 mts	MR			
	> Power Supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting	Ţ.	-				
	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	> Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	Old Case	Provided (2500 lts)	MR being old case			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	Required	Provided	MR			
	Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17	Standby power supply	Required	Provided (D.G. set 50 KVA)	MR			
18	Refuge Area.						
10	> Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. par	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/2014/SZ/496 dated 22.04.2014, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Land

DFA is put up for approval & signature please.

M.K. CHATTOPADHYAY
Divisional Officer (South West)