GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ /1269

Dated: 24/08/17

FIRE SAFETY CERTIFICATE

Certified that the **Swami Dayanand Adarsh Vidyalaya**, Village Mitraon, Najafgarh, New Delhi-110043, comprised of ground floor only having total 14 rooms (Including Class rooms & Office etc.) was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2014/SZ/1258 dated 07.10.2014 owned/occupied by Swami Dayanand Adarsh Vidyalaya was re- inspected by the officer concerned of this department on 31.07.2017 in the presence of Sh. Manjeet Kumar (Principal) and found that the Swami Dayanand Adarsh Vidyalaya have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Manager, Swami Dayanand Adarsh Vidyalaya, Village Mitraon, Najafgarh, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

Swami Dayanand Adarsh Vidyalaya, Village Mitraon, Najargarn, New Name & address of the building: Delhi-110043. Educational Type of Occupancy Renewal # Type of Case F.6/DFS/MS/School/2014/SZ/1258 dated 07.10.2014 3. 4. Details of Previous NOC Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 5. Fire Safety directives letter No Date of inspection A.D.O. Sandeep Duggal Name of Inspecting Officer Name and designation of officers Sh. Manjeet Kumar (Principal) From the building side 1989 Year of Construction S.D.A.V-17 dated 18.07.2017 10. Applicant's letter No. Remarks Provided at Requirement Minimum Standards on fire prevention and S. No. MR/NMR site as per FSC dt. fire safety U/R 33 07.10.2014 Access to building 1. MR Accessible 06 mtrs 12 mtrs Road width Directly accessible MR 4.5 mtrs from road Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. . a. Number of staircases Ground floor only N/A N/A Upper Floors N/A N/A N/A Basements b. Width of staircases Ground floor only Upper Floor N/A N/A N/A Basements N/A N/A c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A No. of continuous staircases to N/A N/A N/A N/A terrace 180 cms N/A Width of Corridor M/R, students are 100 cms 100 cms less than 45 in each Door Size f. classroom Compartmentation 3. N/A N/A N/A Fire check door N/A N/A Sealing of electrical shafts N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A S<mark>moke Management System</mark> 4. N/A N/A N/A Basements N/A N/A N/A Upper floors Fire Extinguishers 5. M/R Provided 06 no's Total numbers M/R ABC/CO₂ type Provided Types M/R ISI marked IS marking ISI marked First-Aid Hose Reels 6. N/A N/A N/A Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A N/A N/A Nozzle diameter ga Mitraon Najafoarh New Delhi-110043 Can

		Type of detectors	N/A	N/A	N/A
	30-3	Location of Main Panel	N/A	N/A	N/A
		Location of Repeater Panel	N/A	N/A	N/A
	·	Alternate source of power	N/A	N/A	N/A
		Hooters' Location	N/A	N/A	N/A
	8.	MOEFA	N/A	N/A	N/A
	9.	Public Address System	N/A	Provided	N/A
	10.	Automatic Sprinkler System			
		Basement	N/A	N/A	N/A
		Ground Floor	N/A	N/A	N/A
		Sprinkler above false ceiling	N/A	N/A	N/A
	11.	Internal Hydrants			
		Size of riser/down-comer	N/A	N/A	N/A
		Number of hydrants per floor	N/A	N/A.	N/A
	10	Hose Box	N/A	N/A	N/A
	1.2.	Yard Hydrants	NI/A	27/4	27/4
		Total number of hydrants	N/A	N/A	N/A
	13.	Hose Box Purpoing A ways governor	N/A	N/A	N/A
	13.	Pumping Arrangements • Ground Level			
		Ground LevelDischarge of main Pump	N/A	N/A	N/A
		Head of Main pump			
		Number of main pumps	N/A	N/A	N/A
		Jockey Pump out put	N/A	N/A	N/A
		Jockey pump head	N/A	N/A	N/A
		Standby Pump out put	N/A	N/A	N/A
		Standby Pump HeadAuto Starting/Manual Stopping	N/A	N/A	N/A
	•	Auto Starting/Manual Stopping	N/A	N/A	N/A
			N/A	N/A	N/A
		➤ Pump House Access	N/A	N/A	N/A
		Terrace level			
		Discharge of pump	N/A	N/A	N/A
		Head of the pump	N/A	N/A	N/A
		Power Supply	N/A	N/A	N/A
		Auto Starting of pump	N/A	N/A	N/A
	14.	Captive Water Storage for fire fighting			
		Underground tank capacity	N/A	N/A	N/A
		> Draw-off connection	N/A	N/A	N/A
		Fire service inlet		N/A	N/A
		Access to tank	N/A N/A	N/A N/A	N/A N/A
		. • Overhead Tank capacity			
	15.	Exit Signage.	N/A N/A	N/A N/A	N/A N/A
	13.	Exit Signage.	IN/A	IN/PA	N/A
l l	16.	Provision of Lifts.			(No Lift)
			**		
		 Pressurization of Lift Shaft 	N/A	N/A	N/A
		 Pressurization of Lift lobby 	N/A	N/A	N/A
	• 3' , "	Communication In lift Car	N/A	N/A	N/A
	2 - 1	• Fireman's Grounding Switch	N/A	N/A	N/A
		• Lift Signage	N/A	N/A	N/A
	N 2 2 2		N/A	N/A	N/A
	17.	Standby power supply			
	18.	Refuge Area.			
	10.	> Total Area	N/A	N/A	N/A
		> Location	N/A	N/A	N/A
B 27					

三五

19.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	 Flow Switch Panel PA System Panel Battery backup 	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A,	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2014/SZ/1258 dated 07.10.2014 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per letter submitted by the Principal (placed at C-19) there are less than 30 students in each class room.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

569 DO(SD)

Divisional Officer (South West)

10/08/2012

DOFO (52)

18/17

10/8 FTB

LFO(ST) W

W 1618

1157/cfost.

G-T. letter in but up for.

signatule please.

Go (SZ)

M SCELL VETE