GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2017/ 1638

FIRE SAFETY CERTIFICATE

Issued on _______at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Dated: 16/11/17

Copy to:-

1. The Manager, M/s Hotel Bill Palace, 7A/18, WEA, Karol Bagh, New Delhi- 110005.

2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. The means of escape shall be kept unlocked and readily available for easy escape of occupants in case of any emergency.
- 7. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : M/s. Hotel Bill Palace, 7A/18, WEA, Karol Bagh, New

Delhi- 110005.

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/GH/2014/NDZ/928 dated 24.07.2014

5. Fire Safety directives letter No : Nil

6. Date of inspection : 26-10-2017

7. Name of the Inspecting Officers : M.K. Chattopadhyay, DO(South West)

8. Name and designation of officers

from the building side : Mr. Hari Om, manager

9. Year of Construction : 2000- 01

10. Applicant's letter No. : nil dated 27.09.2017

The said guest house is comprised of ground floor (reception, office, 01 guest room), first floor (07 guest rooms), second floor (07 guest rooms), third floor (07 guest rooms) and terrace floor (01 pantry with staff room)

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Existing fire safety requirements as per letter dated 24.07.2014	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	06 mts	Provided	MR			
	Gate width	4.5 mts	Directly accessible	MR			
	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	-	-	-			
	Upper Floors	01	01	MR being old case			
	Basements	N/A	N/A	N/A			
	b. Width of staircases	-	-	-			
	• Upper Floors	1.25 mts	1.25 mts	MR being old case			
	Basements	N/A	N/A	N/A			
	c. Protection of exits	-					
	• Fire check door	N/A	N/A	N/A			
	• Pressurization	N/A	N/A	N/A			
	e. No. of continuous staircases to	01	01	MR			
	g. Width of Corridor	Old case	1.47 mts	MR			
	h. Door Size	Old case	0.78 mts	MR being old case			
3	Compartmentation.						
	• Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			

4	Smoke Management System.	1	N/A	N/A
	• Basements	12 a/c per hour		MR
	• Upper floors	12 a/c per hour	Natural Ventilation	IVIIX
5	Fire Extinguishers		Provided	MR
	Total numbers	24	Provided	MR
	Types	CO ₂ , ABC, WCO ₂	Provided	MR
	IS marking	ISI marked	Provided	
6	First-Aid Hose Reels.	MR		
	 Total numbers on each floor 	01	Provided Provided	MR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	
7	Automatic fire detection and alarmin	ng system.	N/A	N/A
	Type of detectors	N/A	IV/A	
	 Location of Main Panel 	N/A	N/A	N/A
		N/A	N/A	N/A
	Location of Repeater Panel All Andreas Source of power	N/A	N/A	N/A
	Alternate source of powerHooters' Location	N/A	N/A	N/A
		Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	reequi		
10	Automatic Sprinkler System.	N/A	N/A	N/A
	Basement		N/A	N/A
	• Upper Floor	N/A		N/A
	Sprinkler above false ceiling	N/A	N/A	IN/A
11	Internal Hydrants	N/A	N/A	N/A
	Size of riser/down-comer	. N/A		N/A
	 Number of hydrants per floor 		N/A	
	Hose Box	N/A	N/A	N/A
12	2 Yard Hydrants.		N/A	N/A
	Total number of hydrants	N/A		N/A
	Hose Box	N/A	N/A	
13	3 Pumping Arrangements.	V		
	Ground Level			N/A
	Discharge of main Pump		N/A	N/A N/A
	Head of Main pump	N/A		
	> Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	> T / A	N/A
		N/A	N/A	N/A

				The state of the s			
1	>	Standby Pump Head	N/A	N/A	N/A		
	>	Auto Starting/ Manual stopping	N/A	N/A	N/A		
	>	Pump House Access	N/A	N/A	N/A		
	•	Terrace level					
		Discharge of pump	450 LPM	Provided (220 LPM)	MR being old case		
		Head of the pump	30 mts	30 mts	MR		
		Power Supply	Required	Provided	MR		
		Auto Starting of pump	Required	Provided	MR		
4	Captive Water Storage for fire fighting.						
	•	Underground tank capacity	N/A	N/A	N/A		
	>	Draw-off connection	N/A	N/A	N/A		
	>	Fire service inlet	N/A	N/A	N/A		
	>	Access to tank	N/A	N/A	N/A		
	•	Overhead Tank capacity	5,000 lts	5000 lts	MR		
5	Exit S	ignage.	Required	Provided	MR		
6	Provision of Lifts.						
-41	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
	•	Pressurization of Lift lobby	N/A	N/A	N/A		
	•	Communication In lift Car	Required	Provided	MR		
	•	Fireman's Grounding Switch	Required	Provided	MR		
	•	Lift Signage	Required	Provided	MR		
17	Stand	by power supply	Required	Provided (125 KVA)	MR		
18	Refuge Area.						
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel	N/A	N/A	N/A		
		Battery backup	Required	Provided	MR		
		Building Floor Plans	N/A	N/A	N/A		
20		al Fire Protection Systems for ction of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect.	MR		

The fire protection systems provided in the building were checked and found functional

All the shortcomings issued by this department vide letter No. F.6/DFS/MS/GH/SZ/2017/1772 dated 14.07.2017 have been complied with by the guest house management.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/2014/NDZ/928 dated 24.07.2014, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

M.K.CHATTOPADHYAY
Div. Officer (South West)

DCFO (SZ)

Lanf 3 yrs

Cho Csas m-sleu

skell re

F.T. letter is fut up for Sign ple

CFo(SZ)

m-scell

MISTI

799/20/KW

