GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2017/SZ

Dated: 08 12 2017

FIRE SAFETY CERTIFICATE

Certified that the **Gyan Deep Public School**, Mundhela Khurd, New Delhi-110073 owned/occupied by Gyan Deep Public School was issued Fire Safety Certificate for ground floor only by this department vide letter No F.6/DFS/MS/School/2014/SZ/1074 dated 27.08.2014. The school building was re- inspected by the officer concerned of this department on 16.11.2017 in the presence of Sh. R.S Sehrawat (Manager) and found that three rooms have been added on first floor. The Gyan Deep Public School comprised of ground plus one upper floor have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 08 12 2017 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Manager,
 Gyan Deep Public School,
 Mundhela Khurd, New Delhi-110073
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

INSPECTION REPORT 1. Name & address of the building: Gyan Deep Public School, Mundhela Khurd, New Delhi-110073. Type of Occupancy 2. Educational Type of Case New/Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2014/SZ/1074 dated 27.08.2014 (For GF only) 5. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 16.11.2017 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. R.S Sehrawat (Manager) 9. Year of Construction 2004 (GF) & 2016-17 (FF) 10. Applicant's letter No. Nil dated 12.10.2017 S. No. Minimum Standards on fire prevention and Dir. Of Edu. Provided at site Remarks fire safety U/R 33 Circular dt. MR/NMR 01.03.2011 1. Access to building Accessible (06 mtrs) Road width M/R 06 mtrs 4.5 mtrs Directly accessible M/R Gate width N/A from road N/A Width of internal road N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors MR 01 no. 01 no. **Basements** N/A N/A N/A Width of staircases Upper Floor 150 cms 150 cms MR **Basements** N/A N/A N/A c. Protection of exits Fire check door Pressurization N/A N/A N/A N/A N/A N/A No. of continuous staircases to N/A N/A N/A terrace MR Width of Corridor 150 cms 260 cms M/R (Students are 100 cms 100 cms Door Size less than 45 in each classroom) 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door . N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. **Smoke Management System** N/A N/A N/A **Basements** Natural ventilation M/R Required Upper floors provided Fire Extinguishers 5. 05 no's Provided M/R Total numbers ABC type Provided M/R **Types** IS marking ISI marked M/R ISI marked First-Aid Hose Reels 6. N/A N/A N/A Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A Nozzle diameter N/A N/A

	Location of Main Panel	N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
8.	MOEFA	N/A	N/A	N/A	
9.	Public Address System	N/A	Provided	N/A	
10.	Automatic Sprinkler System	N/A	N/A	N/A	
	BasementGround Floor	N/A	N/A	N/A	
	SMC PS - 10 SMC PS - 100	N/A	N/A	N/A	
 11.	Sprinkler above false ceiling Internal Hydrants	N/A	IN/A	IN/A	
11.	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
12.	Yard Hydrants				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13.	Pumping Arrangements			8	
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put		N/A	N/A	
	> Jockey pump head	N/A	NAP AND		
	Standby Pump out putStandby Pump Head	N/A	N/A	N/A	
	> Auto Starting/Manual Stopping	N/A	N/A	N/A	
	Truto Starting Transact Stopping	N/A	N/A	N/A	
		N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
	Terrace level				
	> Discharge of pump	N/A	N/A	N/A	
	> Head of the pump	N/A	N/A	N/A	
	> Power Supply	N/A	N/A	N/A	
	> Auto Starting of pump	N/A	N/A	N/A	
14.	Captive Water Storage for fire fighting				
17.	0 0 0	N/A	N/A	N/A	
	 Underground tank capacity Draw-off connection 		N/A	N/A	
	Fire service inlet	N/A			
	Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	N/A	N/A	N/A	
	• • •	N/A	N/A	N/A	
15.	Exit Signage.	N/A	N/A	N/A	
16.	Provision of Lifts.			(No Lift)	
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	 Pressurization of Lift Shaft Pressurization of Lift lobby 		N/A	N/A	
	Communication In lift Car	N/A N/A	N/A N/A	N/A N/A	
	Fireman's Grounding Switch				
	Lift Signage	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
17.	Standby power supply				
18.	Refuge Area.				
	Refuge Area. > Total Area > Location	N/A	N/A	N/A	

19.	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backupBuilding Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per the undertaking given by the Manager (placed at C-13) there are less than forty five students in each class and three rooms have been added on first floor.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

Divisional Officer (South West)

F.T. letter is put up for signature please.

Sander

OUID

MSCEN 6/12