

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001.

No. F.6/DFS/MS/EH/2018/SZ /421

Dated: 15/03/2018

FIRE SAFETY CERTIFICATE

Certified that the M/s Haldiram Products Pvt. Ltd., 4B/16, Najafgarh Road, Tilak Nagar, New Delhi-110018 is in the building comprised of basement, ground floor plus two upper floors. But restaurant is running at ground floor plus two upper floors only was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/2014/SZ/1631 dated 23.12.2014 owned/ occupied by M/s Haldiram Products Pvt. Ltd. The restaurant was re-inspected by the officers concerned of this department on 26.02.2018 in the presence of Sh. Sudesh Kumar Sharma (Liaison Manager) and found that the M/s Haldiram Products Pvt. Ltd. have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (**Restaurant at ground plus two upper floors Only**) is fit for occupancy class Group "D" Assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on..... 15/03/2018at New Delhi.

13/3.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

8/3/18

Copy to:-

The Manager,
M/s Haldiram Products Pvt. Ltd.,
4B/16, Najafgarh Road, Tilak Nagar, New Delhi-110018.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. Basement shall be used as per the building bye laws.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

70/20
MS05

Building is comprised of Basement, ground floor plus two upper floors but restaurant is running at ground floor, First floor and second floor only.

INSPECTION REPORT

1. Name & address of the building: M/s Haldiram Products Pvt. Ltd., 4B/16, Najafgarh Road, Tilak Nagar, New Delhi-110018.
2. Type of Occupancy : Group D (Assembly Building)
3. Type of Case : Renewal
4. Details of Previous NOC : F.6/DFS/MS/EH/2014/SZ/1631 dated 23.12.2014
5. Fire Safety directives letter No : N/A
6. Date of inspection : 26.02.2018
7. Name of Inspecting Officers : D.O. M.K. Chattopadhyay & A.D.O. Sandeep Duggal
8. Name and designation of officers
From the building side : Sh. Sudesh Kumar Sharma (Liaison Manager)
9. Year of Construction : Before 2007
10. Applicant's letter No. : Nil dated 22.01.2018

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per FSC dt. 23.12.2014	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible (09 mtrs) 06 mtrs N/A	12 mtrs Directly accessible from road N/A	MR MR N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	02 No.'s N/A	02 No.'s N/A	MR N/A, restaurant running at GF, FF & SF
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	1.5 mtrs & 01 mtrs	153 & 104 cms	MR
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	N/A	N/A	N/A
		Required	Provided	MR
	d. No. of continuous staircases to terrace	N/A	N/A	N/A
	e. Width of Corridor	Required	One	MR
		1.5 mtrs	Opening in hall	MR
	f. Door Size	02 mtrs	Provided	MR
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4.	Smoke Management System			
	<ul style="list-style-type: none"> • Basements 	Required	Provided	MR
	<ul style="list-style-type: none"> • Upper floors 	Required	Natural Ventilation	MR
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	03 No.'s/floor ABC/ CO ₂ ISI marked	Provided Provided ISI marked	MR MR MR
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none"> • Total numbers on ground floor 	Two	Provided	MR

N/14

19.	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F.6/DFS/MS/EH/2014/SZ/1631 dated 23.12.2014 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:- As per the undertaking given by Authorized Signatory (placed at C-29) basement floor of Haldiram Restaurant located \$B/16, Najafgarh, Road, Tilak Nagar, New Delhi belongs to other's property and using restaurant for ground floor to second floor and the restaurant have no connection with basement floor.

[Signature]
27/2/18

Signature of Inspecting Officer
Name:- M.K. Chattopadhyay
Designation:- Divisional Officer

[Signature]
28/2/18

Signature of Inspecting Officer
Name:- Sandeep Duggal
Designation:- Asstt. Divisional Officer

974/DO(SO)
dt. 27/02/18

Dy. C.F.O. (South Zone)



[Signature]
29/2

cfos/sf
m.scell
we
5/3.

1654/cfsc
5/3.1/12/2

F.T. letter is put up for signature please.

[Signature]
08/3/18

[Signature]
m.scell
we
13/3.