## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110

No. F6/DFS/MS/School/2018/ 1402/449

dated: )8/3/8

## **FIRE SAFETY CERTIFICATE**

Issued on.....at New Delhi by

(Vipin Kental)
Chief Fire Officer

W\_

To,

The Vice Principal, Moti Ram & Mukherjee Memorial Sr. Sec. School, N-Pocket, Dilshad Garden, Delhi -110095.

Copy to:-

The Dy. Director of Education, North-East, B-Block, Yamuna Vihar, Delhi-110053.

## - Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building : Moti Ram & Mukherjee Mem. Sr. Sec. School,

N-pocket, Dilshad Garden, Delhi -110095.

2. Building is comprised of : Ground plus three upper floors ( two block bldg.)

3. Type of Occupancy : Educational

4. Type of Case : Renewal

5. Details of Previous NOC letter : F6/DFS/MS/School/2014/NDZ/569

dated 07/05/14

6. Fire Safety directive letter No. : F6/DFS/MS/BP/2001/2475 Dated- 08/11/2001

7. Date of Inspection : 05/03/2018

8. Name of the Inspecting officers : ADO Vijay Bahadur

9. Name and designation of Officer

from the building side : Mr. P. S. Jain (Vice Principal)

10. Year of Construction : 2001 & 2009

11. Applicant's letter No : MS/2017-18/141, Dated- 23/01/2018

S.NO.	Minimum Standards on fire prevention and fire safety U/R33	Directive Requirement	Provided at Site	Remarks MR/NMR
1	Access to building			
	Road width	06mtr.	15mtr.	MR
	Gate width	N/A	N/A	N/A
	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			¥
	a. Number of Staircases			
	Upper Floor	04Nos.(2 nos.in each block)	05 nos. (2 nos in 1 <sup>st</sup> block & 3 nos in 2 <sup>nd</sup> block)	MR
	Basement	N/A	N/A.	N/A
	B. Width of Staircases			
	Upper Floor	1.50mtr.	1.50mtr. each	MR
	Basement	N/A	N/A	N/A
	c. Protection of exits	N/A	N/A	N/A
	Fire check door	N/A •	N/A	N/A
	Pressurization     d. No. of continuous staircases to terrace     e. Width of Corridor	02 Nos.	04 Nos.	MR
		1.50mtr.	1.70mtr.	MR
	f. Door Size	01mtr.	1.12mtr.	MR
3	Compartmentation.			in late
	Fire check door	N/A	N/A	N/A
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A
	Fire rating of shaft door	N/A	N/A	N/A
	Water curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	Basement	N/A	N/A	N/A
	Upper floor	N/A	N/A	N/A
5.	Fire Extinguishers		The state of the s	
	Total numbers	27 nos.	27 nos.	MR
	• types	ABC /CO <sub>2</sub>	ABC /CO <sub>2</sub>	MR
	IS marking	ISI marked	ISI marked	MR

6	First-aid-Hose Reels.			
	Total numbers on each floor	02 nos.	00	
	The state of the design floor	02 1108.	02 nos.	MF
	<ul> <li>Length of hose reel hose</li> </ul>	30mtr.	30mtr.	MF
	Nozzle diameter	05mm	05mm	MF
7	Automatic fire detection and alarming s	ystem.	0011111	IVIF
	<ul> <li>Type of detectors</li> </ul>	N/A	N/A	N/A
	<ul> <li>Location of main panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Location of repeater panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Alternate source of power</li> </ul>	N/A	N/A	N/A
	<ul> <li>Hooter's location</li> </ul>	N/A	N/A	N/A
8	MOEFA	Required	Provided	MF
9	Public address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.		14//	14//-
	Basement	N/A	N/A	N/A
	upper floor	N/A	N/A	NI/A
	sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants	Required	Provided	N/A
	size of riser/down-comer	150 mm	150 mm	MR
	<ul> <li>Number of hydrants per floor</li> </ul>	02 No.	02 No.	MR
1				MR
12	Hose Box (Total)  Yard Hydrants.	08 No.	08 No.	MR
_	- Total Harrisel of Hydranits	N/A	N/A	N/A
3	TIOCO BOX (   B + Q	N/A	N/A	N/A
5	Pumping Arrangements.			
	Crodita Level	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
-	District ge of main i unip	1620 Lpm	1620 Lpm	MR
	Tieda of Mail Lalip	40 M	40 M	MR
	<ul><li>Number of main pumps</li><li>Jockey pump out put</li></ul>	01 no.	01 no.	MR
	> Jockey pump head	N/A	N/A	N/A
	> Standby pump out put	N/A	N/A	N/A
	> Standby pump Head	N/A	N/A	N/A
	> Auto Starting /Manual stopping	N/A	N/A	N/A
	> Pump House Access	Required	Provided	MR
	Terrace Level	Required	Provided	MR
4	➤ Discharge of pump	450 1		1111
	> Head of the Pump	450 Lpm. 40 M	450 Lpm.	MR
	> Power supply	Required	40 M	MR
	> Auto Starting of pump	Required	Provided	MR
1			Provided	MR
	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	50,000 Ltr.	1,00,000 Ltr.	MR
	> Fire service inlet	Required	Provided	MR
	> Access to tank	Required	Provided	MR
	Overhead Tank capacity	Required	Provided	MR
	Exit Signage.	10,000 Ltr.	10,000 Ltr.	MR
	Provision of Lifts.	Required	Provided	MR
	Pressurization of Lift Shaft	N/A	N/A	N/A
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication in lift car</li> </ul>	N/A	N/A	N/A
-		N/A	N/A	N/A
-	- Herrierre greatfallig Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A

17	Standby power supply	Alla		
18	Refuge Area.	N/A	N/A	N/A
	Total area	N		
	• Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
>	Detector system panel	NIG		
14-	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
		N/A	N/A	N/A
-	Battery backup	N/A	N/A	
1	Building Floor Plans	N/A		N/A
0	Special Fire Protection systems for	N/A	N/A	N/A
	protection of special Risks, if any:	IN/A	N/A	N/A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection. The shortcomings communicated earlier vide letter No. F6/DFS/MS/School/2017/2594 dated 10/10/17 have been rectified now...

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire

Signature of the Inspecting Officer

Name

:- Vijay Bahadur

Designation :- ADO (TP)