GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

No.F.6/DFS/MS/School/2018/SZ/ 579 4

Dated: 5/9/18

FIRE SAFETY CERTIFICATE

Certified that the Baby Modern School, B-25, Maharani Enclave, Hastsal Village, Uttam Nagar, New Delhi 110059 comprised of ground plus one upper floor having total 10 rooms (07 rooms on GF & 03 rooms on FF including classrooms, office & store etc.) owned/occupied by Baby Modern School was issued NOC by this department vide letter no. F.6/DFS/MS/2006/2078 dated 11.08.2006. The school was re-inspected by the officer concerned of this department on 10.03.2018 in the presence of Sh. Sunil Tyagi (Manager) and found that Baby Modern School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Manager, 1. Baby Modern School, B-25, Maharani Enclave, Hastsal Village, Uttam Nagar, New Delhi 110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

Orduna Flus One Opper Floor **INSPECTION REPORT** Baby Modern School, B-25, Maharani Enclave, Hastsal Village, Uttam 1. Name & address of the building: Nagar, New Delhi 110059. Educational 2. Type of Occupancy Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/2006/2078 dated 11.08.2006 5. Fire Safety directives letter No: Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. Sunil Tyagi (Manager) 9. Year of Construction Before 2006 10. Applicant's letter No. Form "J" dated 20.02.2018 Minimum Standards on fire prevention and Requirement Provided at site Remarks S. No. fire safety U/R 33 as per FSC dt. MR/NMR 11.08.2006 1. Access to building Road width Accessible 07 mtrs M/R Directly accessible MR 4.5 mtrs Gate width from road NA NA Width of internal road NA 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 02 No's M/R 01 No. **Basements** N/A N/A N/A b. Width of staircases 150 cms/additional 150 & 100 cms M/R Upper Floor staircase of 75 cms if less than 150 cms Basements N/A N/A N/A c. Protection of exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization d. No. of continuous staircases to N/A N/A N/A terrace M/R 150 cms 150 cms e. Width of Corridor Door Size 100 cms 100 cms M/R 3. Compartmentation N/A N/A N/A Fire check door • Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. **Smoke Management System** N/A N/A N/A **Basements** Natural MR Required Upper floors Ventilation 5. Fire Extinguishers 04 no's Provided M/R Total numbers ABC/CO₂ type Provided M/R **Types** ISI marked IS marking ISI marked M/R 6. First-Aid Hose Reels Total numbers on each floor N/A Provided N/A

7.	Automatic fire detection and alarming system		Company of the Compan	
-	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A N/A	N/A	N/A
	Alternate source of power	N/A N/A	N/A	N/A
	Hooters' Location	14/11	N/A	N/A
3.	MOEFA	N/A	N/A	N/A
).	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	77/4	77/4	DT/A
	Basement	N/A	N/A	N/A N/A
	0 171	N/A	N/A	
	Ground Floor Ground Floor Spring Spring	N/A	N/A	N/A
11.	Sprinkler above false ceiling Internal Hydrants			_
11.	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
3.	Pumping Arrangements	- L		
	Ground Level			c at
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	Jockey pump headStandby Pump out put	N/A	N/A	N/A
	> Standby Pump Head		N/A	N/A
	> Auto Starting/Manual Stopping	N/A		N/A
		N/A	N/A	
		N/A	N/A	N/A N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			-
	Discharge of pump	N/A	220 LPM	N/A
	> Head of the pump	N/A	30 m	N/A
	> Power Supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	2500 ltrs provided	N/A
		N/A	N/A	N/A
15.	Exit Signage.			
16.	Provision of Lifts.	~	No Lif	t
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	 Fireman's Grounding Switch 	N/A	N/A	N/A
	Lift Signage			N/A
	The state of the s	N/A N/A	N/A N/A	N/A N/A
17.	Standby power supply	IN/A	11//	14/11
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	NI-/ A	N/A	N/A

No.

Ground Plus One Upper Floor

	Ground 1 tub	one opper ricor		
19.	Fire Control Room			
	 Detector System Panel Flow Switch Panel PA System Panel 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Battery backupBuilding Floor Plans	N/A	N/A	N/A
	Building Floor Fland	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A
			P	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number F.6/DFS/MS/2006/2078 dated 11.08.2006 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note: As per the undertaking given by the Manager (placed at C-7) there are less than 45 students in each classroom.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

214/20/500

Divisional Officer (South West)

22/3/18

Party No.

Majorasa dy.

DOF (\$2)

22/3

The sty M.S

F710.

Verej3