GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Mixed/SZ/2018/ 8 79

Dated: 0//05

FIRE SAFETY CERTIFICATE

Centre, Jasola New Delhi-110044 comprises of three tiers Basement, Ground floor and 6 Upper floors was granted FSC by this department vide letter No. F6/DFS/MS/2014/SZ/1623 dated 22/12/2014. The premises was re- inspected by the officer concerned of this department on 20/04/2018 in the presence of Mr. Tilak Singh (Facility Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Mixed Occupancy (Mercantile & Business)" with effect from 2 for 2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

de &

Copy to:-

1. The Executive Engineer (Bldg.), SDMC, Jal Vihar, Lajpat Nagar, New Delhi-110024

2. The Authorized Signatory, Indian Coloniser Pvt. Ltd., Plaza M-6, Plot No. 06, Jasola Distt. Centre, Jasola New Delhi-110044

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration **every year** in **Form 'K'** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form** 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	INSPECTIO	N REPORT		
1	James & address of the building . Indian Colonise	r Pvt. Ltd., Plaza M-6,	located at Plot No. 06, J	asola Distt.
1. 1	Centre, Jasola 1	NEW Delli-110011		
2.	Type of Occupancy : Class- Mixed (I	- & F)	M tile & Dusiness)	1
3.	Type of Case : Renewal	[Mixed Occupancy (Mercantile & Business)	1
4. I	Details of Previous NOC : F6/DFS/MS/20	14/SZ/1623 dated 22/1 P/2007/886 dated 28/03	3/2007	
5. I	ne Salety discourse	7/2007/880 dated 28/0.	5/2001	
6. I	Date of inspection : 20/04/2018 Name of Inspecting Officer : A. K. Malik		9	
7.]	Name of Inspecting Officer : A. K. Malik Name and designation of officers		7.	
8.	The building side Mr Illak Single	h (Facility Manager)		
	· 2006-07 13 tier	· Basement + Ground	+ 6 upper floors]	
	Applicant's letter No. : outdoor diary n	o. 3462 dated 07/03/20	018	Remarks
S. No.	Minimum Standards on fire prevention and	NBC/BBL	Provided at site	MR/NMR
5.1.0.	fire safety U/R 33	Requirement		WIR/INIVIR
				2.7
1.	Access to building	9m	Provided	MR
	Road width	NA (No boundary on	Abut on Road	MR
	• Gate width	road side)	Provided	MR
	Width of internal road	6m	i i	
2.	Number, Width, Type & Arrangement of Ex	its		
	a. Number of staircases			MD
	Upper Floors	3 Nos	Provided	MR
	Basements	5 Nos	Provided	MR
	b. Width of staircases			
	T1	1.5m	2 x 1.5m & 1.8m	MR
	Upper FloorBasements	1.5m	2 x 1.5m & 3 x 1.8m	MR
	c. Protection of exits			
	Fire check door	Required	Provided	MR
			Provided	MR
	 Pressurization 	Required	3 Nos	MR
	to take manage	3 Nos		MR
	d. No. of continuous staircases to terrace	1.5m	Provided	MR
	e. Width of Corridor	1 m	1.5m (final exit)	IVIK
	f. Door Size		1	
2	Compartmentation			я я
3.	•	Required	Provided	MR
	• Fire check door	Required	Provided	MR
	 Sealing of electrical shafts 	-NA-	-NA-	-NA-
	Fire Rating of shaft door	-NA-	-NA-	-NA-
	Water Curtain		Provided	MR
	Fire Dampers	Required	TTOVICE	7.44
4.	Smoke Management System			
4.		30 a/c per hour	Provided	MR
	Basements	12 a/c per hour	Provided	MR
	Upper floors	12 are per flour		
5.	Fire Extinguishers		Provided	MR
	Total numbers	100 No's		MR
	• Types	ABC/W. CO ₂ /CO ₂	40/40/20 No's	
	IS marking	ISI	Yes	MR
6.	First-Aid Hose Reels			
0.	Total numbers on each floor	GF to terrace: 2 No:	s Provided	MR
	• Total numbers on each from	Basements: 4 Nos		
	 Length of hose reel hose 	30m	Provided	MR
	Nozzle diameter	5 <mark>mm</mark>	Provided	MR
			110,1000	
7.	Automatic fire detection and alarming syst	Smoke & Heat	Provided	MR
	Type of detectors		1 st basement	MR (old case
	 Location of Main Panel 	Ground Floor		
			-NA-	-NA-
	 Location of Repeater Panel 	-NA-	Provided	MR

	In		oloniser Pvt. Ltd., Ftd2d W-0, toedies at	Required	Provided	ЛR		
	•	Alt	ernate source of power	All Area				
	•	Но	oters' Location	Required	Flovided	MR		
8.	MO			Required	Provided	MR		
9.	Public Address System Required							
10.	Auto		Sprinkler System	Required	Provided	MR		
			sement	Required	Provided	MR		
		• Up	oper Floor	Required	Provided	MR		
		1	rinkler above false ceiling	Require				
11.	Inte	rnal I	lydrants	100mm	Provided	MR		
		• Si	ze of riser/down-comer	GF to terrace: 2 Nos	Provided	MR		
		• N	umber of hydrants per floor	Basements: 4 Nos		MR		
			ose Box	GF to terrace: 2 Nos	Provided	IVIIX		
		• H	ose box	Basements: 4 Nos				
12	Vo	rd Hy	drants		Provided	MR		
12.	1 a	Tu Hy	otal number of hydrants	06 Nos	Provided	MR		
			Jose Box	06 Nos	Provided			
13	D		Arrangements					
13.	Pu		Ground Level		Provided	MR		
		,	Discharge of main Pump	2280LPM		MR		
			Head of Main pump	60m	Provided	MR		
	5		Number of main pumps	One	Provided	MR		
			Jockey Pump out put	180 LPM	Provided	MR		
			Jockey pump head	60m	Provided	MR		
			Standby Pump out put	2280LPM	Provided	MR		
			Standby Pump Head	60m	Provided	MR		
			> Auto Starting/Manual Stopping	Required	Provided	MR		
			Pump House Access	Required	Provided	IVIIC		
					Provided	MR		
		•	Terrace level Discharge of pump	900 LPM	Provided	MR		
			Head of the pump	40m	Provided	MR		
			> Power Supply	Required	Provided	MR		
			> Auto Starting of pump	Required	Provided	177.7		
1.4		Cantix	e Water Storage for fire fighting					
14.		Captiv	Underground tank capacity		Provided	MR		
		3	> Draw-off connection	1,00,000 Lts	Provided	MR		
			Fire service inlet	Required	Provided	MR		
			> Access to tank	Required	Provided	MR		
			Overhead Tank capacity	20,000 Lts.	Provided	MR		
15		Evit S	ignage.	Required	Provided			
16			sion of Lifts.		Provided	MR		
10	•	11001	Pressurization of Lift Shaft	Required	Compensated with			
					excess lift shaft pressure	MR		
				Required	in conformity with			
	8	•	Pressurization of Lift lobby		provision of NBC-2016			
			a to the Let Cor	Required	Provided	MR		
		•	Communication In lift Car	Required	Provided	MR		
		•	Fireman's Grounding Switch	Required	Provided	MR		
			Lift Signage	Required	Provided	MR		
1	7.	Stan	dby power supply	Required				
1	8.	Refu	ige Area	Required	Provided	MR		
			> Total Area	5 th Floor	Provided	MR		
			> Location	3 11001				
	19.	Fire	Control Room	Required	Provided in basement	MR (old case		
			 Detector System Panel 	Required	Provided in basement	MR (old-case		
			Flow Switch Panel	Kedanea		ND /		

Indian Coloniser Pvt. Ltd., Plaza M-6, located at Plot No. 06, Jasola Distt. Centre, Jasola New Delhi-10044

	Battery backupBuilding Floor Plans	Required Provide		1 3 3 7 7	
		Required	Provided		MR MR
	Special Fire Protection System for	Manual CO ₂ flooding + 2 Nos of D.C.P. Extinguishers for HT/LT			17110
	Protection of special Risks, if any:		Provided	A	MR
		Panels			

The applicant in reply to the shortcomings communicated vide letter no. F6/DFS/MS/SZ/2017/3365 dated 11/12/2017 (C-123) submitted compliance/representation (C-124 & 125). All the Shortcomings except Sr. No.13 found complied during the inspection, however as represented/requested by applicant in r/o the shortcoming at Sr. No. 13 i.e. the requirement of lift lobby pressurization is compensated with excess pressure of lift shaft as stipulated in NBC-2016 may be accepted by competent authority and same has been marked as MR in inspection note at Sr. No. 16 above.

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA of Form "H" is put up for approval.

Signature of Inspecting Officer

Name: A. K. Malik
Designation: Divisional Officer

DY. CFO (SZ)

24/y

Crock

m'scell

FTDI.

Sinftis pulipfor sig

C6(52)

DOL 90

24-4-18 Chary No. 27