0GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/EH/2018/SZ/ / 63 9

Dated: 1.3/.7.1.18

FIRE SAFETY CERTIFICATE

Certified that M/s McDonald's Family Restaurant located at TDI West Side Mall, PVR 3'CS Cinema, Lajpat Nagar-III, New Delhi-110024, comprised of two tier basement, Ground plus two upper floors. The restaurant running at ground floor was issued FSC by this department vide letter No. F6/DFS/MS/EH/2015/SZ/614 dated 27-04-2015. The premises was re-inspected by officer concerned of this department on 29/05/2018 in the presence of Mr. Rahul Rawat (Manager) of the restaurant and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that building is fit for occupancy class "Assembly, Group-A" (Eating House) as above with effect from the date of issue of this certificate for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued 13/7/18 at New Delhi by

(Vipin Kental) Chief Fire Officer Tel. 011-23412225

Copy to: -

No.

- 1. Authorized Signatory, M/s McDonald's Family Restaurant at TDI West Side Mall, PVR 3'CS Cinema, Lajpat Nagar-III, New Delhi-110024
- 2. The Addl. Comm. of Police (Lic.), First Floor, P.S. Defense Colony, New Delhi-110049

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

		INSPECTIO	N REPORT	1			
	N 0 4 d d	INSPECTION REPORT McDonald's Family Restt at Ground Floor, TDI West McDonald's Family Restt at Ground Floor, TDI West					
1	Name & Add	aine & Address of the Burns		Side PVR 3'CS Cinema, Lajpat Nagar-III, ND-24			
	T CO was apply		Assembly, "Group-D" (Eating House)				
2	Type of Occupancy		02 Basements, Ground + 02 upper floors.				
3		Building Comprised of		Renewal			
5	Type of Case Details of Previous NOC		F.6/DFS/MS/EH/2015/SZ/614 Dated 27-04-2015				
6	Eire Sufety [Directives Letter No	N/A				
7	Fire Safety Directives Letter No Date of Inspection		29-05-2018				
8	Name of the	Inspecting Officers	Mehmood, ADO (SJ)				
9	Name & Des	signation of Officers	Mr. Rahul Rawat (Manager)				
7	from the building side		LG Cd L IIIino				
10	Year of cons	struction	2002 Restt running at ground floor of the building.				
11	Applicant letter No.		Outdoor Diary No	o. 5642 dated 09-04-201	8		
S. No.	Minimum standards on Fire Prevention		Old NOC	Provided at Site	Remarks MR/NMR		
S. 140.	and Fire Sa	fety U/R 33	requirements	15.04.0.1077.140.4 1 4			
1	Access to Building.			ema/2018/SZ/484 dated	MR		
		d width	Restt located in	As above	-NA-		
		e width	TDI West Side	As above	-NA-		
		Ith of internal road	Mall Building	As above	-IN/A-		
2		idth, type & arrangement of ex	xits.		le e e e e e e e e e e e e e e e e e e		
	a) Numbe	r of Staircase	Provided & M	aintained by Building M	-NA-		
		per floors.	-NA-	Restt. at GF			
	Basement floor.		-NA-	-NA-	-NA-		
		A.C.		Provided & Maintained by Building Management			
	b) Width of Staircase Upper floors		-NA-	-NA-	-NA-		
			-NA-	-NA-	-NA-		
	> Basement floor		Provided & Maintained by Building Management				
	c) Protection of exits Fire check door		-NA-	As above	-NA-		
			-NA-	As above	-NA-		
		essurization		As above	-NA-		
		continuous staircase to terrace	-NA-	As above	-NA-		
		of corridor	-NA- Required	1.40m & 1.24m	MR		
	f) Door size		Required & N	Maintained by Building N			
3	Compartmentation.		-NA-	As above	-NA-		
		re check door.	-NA-	As above	-NA-		
		aling of electrical shafts.	-NA-	As above	-NA-		
		re rating of shaft door.	-NA-	As above	-NA-		
		ater curtain	-NA-	As above	-NA-		
	Fire dampers.		Provided & Maintained by Building Management				
4.	The same of the sa	anagement system.	30 ACPH	As above	-NA-		
		asement		Provided in kitchen	MR		
	• U	pper floors	12 ACPH	Provided in kitchen	IVIIX		
5.	Fire Extin	nguishers.		06.21	MR		
	AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	otal numbers	Required	06 Nos			
	• Т	ypes	ABC / CO2	ABC & CO2	MR		
			ISI marked	Provided	MR		
	• ISI Marking First Aid Hose Reels.		Provided & Maintained by Building Managemen				
6.	First Aid	otal numbers on each floor.	One	Provided near Restt	MR		
			30 mtr	Provided	MR		
		ength of hose-reel hose.		Provided	MR		
	• \	lozzle Diameter s Family Restt at GF in TDI Wes	5 mm		The second secon		

M/s McDonald's Family Restt at GF in TDI West Side Mall, PVR 3' CS, Lajpat Nagar-III, New Delh

7 1	Automatic fire detection & alarming system.	Provided & Ma	nintained by Building Ma	anagement	
, ,	Type of detectors	Required	Heat & Smoke	MR	
	Location of Main Panel	Required	Ground floor	MR	
	Location of Repeater Panel	-NA-	-NA-	-NA-	
	Alternate source of power	Required	Provided	MR	
	Hooter's location	-NA-	-NA-	-NA-	
8. N	MOEFA	Required	Provided	MR	
	Public Address System	-NA-	-NA-	-NA-	
	Automatic Sprinkler System		aintained by Building M		
10.	Basement	-NA-	As above	-NA-	
	• Upper floors	-NA-	As above	-NA-	
		-NA-	As above	-NA-	
11 1			aintained by Building M		
11. I	Internal Hydrants. • Size of Riser/Down-comer	-NA-	As above	-NA-	
-		-NA-	As above	-NA-	
	Number of Hydrant per floor	-NA-	As above As above	-NA-	
	Hose box.				
12.	Yard Hy d rants.		aintained by Building M		
	Total number of hydrants.	-NA-	As above	-NA-	
	Hose box.	-NA-	As above	-NA-	
13.	Pumping arrangements.				
	Ground Level	THE RESIDENCE OF THE PARTY OF T	aintained by Building M		
	Discharge of main pump.	-NA-	2250 LPM	-NA-	
	Head of main pump.	-NA-	70m	-NA-	
	Number of main pumps.	-NA-	Two	-NA-	
	 Jockey Pump output. 	-NA-	480 LPM	-NA-	
	Jockey Pump head.	-NA-	70m	-NA-	
	Standby Pump output.	-NA-	2280 LPM	-NA-	
	> Standby Pump head.	-NA-	70m	-NA-	
	Auto Starting / Manual Stopping.	-NA-	Provided	-NA-	
	Pump house access.	-NA-	Provided	-NA-	
	 Terrace Level 		Provided & Maintained by Building Management		
	 Discharge of pump. 	225 LPM	1250 LPM	MR	
	Head of pump.	Required	50m	MR	
	Power supply.	Required	Provided	MR	
	 Auto starting of pump. 	Required	Provided	MR	
14.	Captive water storage for fire fighting.	Provided & M	laintained by Building N	1anagement	
	 Underground tank capacity. 	-NA-	1,00,000 Ltr.	-NA-	
	Draw-off connection.	-NA-	Provided	-NA-	
	Fire Service Inlet.	-NA-	Provided	-NA-	
	Access to tank.	-NA-	Provided	-NA-	
V 4	 Overhead tank capacity. 	2,500 Ltr	35,000 Ltr	MR	
	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.	Provided & Maintained by Building Management			
	 Pressurization of lift shaft. 	-NA-	As above	-NA-	
	 Pressurization of lift lobby. 	-NA-	As above	-NA-	
	 Communication in lift car. 	-NA-	As above	-NA-	
	• Fireman's switch.	-NA-	As above	-NA-	
	• Lift signage.	-NA-	As above	-NA-	
17.	Standby Power Supply	Required	Provided	MR	
	Refuge Area	1			
	Total area	-NA-	-NA-	-NA-	
	• Location	-NA-	-NA-	-NA-	
	AcDonald's Family Restt at GF in TDI West S			1	

M/s McDonald's Family Restt at GF in TDI West Side Mall, PVR 3' CS, Lajpat Nagar-III, New Delhi

19.	Fire C	ontrol Room.	Provided & Maintained by Building Management		
	•	Detector system panel.	-NA-	As above	-NA-
	•	Flow switch panel.	-NA-	As above	-NA-
		PA system panel.	-NA-	As above	-NA-
		Battery backup.	-NA-	As above	-NA-
	•	Building floor plan.	-NA-	As above	-NA-
20.		I Fire Protection System for the tion of special Risk, if any.	-NA-	As above	-NA-

The fire protection system provided in the building/ premises were checked/ operated at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/MS/DFS/EH/2015/SZ/614 dated 27/04/2015, renewal under rule 37 of the Delhi Fire Service Rules 2010, is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting

Name: Mehmood Design: ADO (SJ)

M/s McDonald's Family Restt at GF in TDI West Side Mall, PVR 3' CS, Lajpat Nagar-III, New Delhi

DO (8D)

hat up with FSC of hair premise.

P.S.C. of new frommo out e139, ag. De Spontes out e139,

