GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

NO. F6/DFS/MS/EH/NDZ/2018/ / 592

Dated: 9/7/18

FIRE SAFETY CERTIFICATE

Certified that the M/s Mirror Reloaded restaurant (Previously known as Mirror Restaurant) is running at F-32,34 & 37, First floor of the building which is comprised of basement, ground plus two upper floors at Star City Mall, Plot no. 1A, District Centre, Mayur Vihar-I, Delhi, owned/occupied by M/s Mirror Reloaded(A Unit of 3's Hospitality Service) was granted Fire Safety Certificate vide letter No. F6/DFS/MS/EH/2014/NDZ/897 dated 22/07/14. The restaurant was re-inspected by the officer concerned of this department 14/06/18 in the presence of Mr. Amit Kumar Mavi and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and found that the restaurant is fit for occupancy class "Eating House (Restaurant)" with effect from 9/7/18 for a period of three years subject to conditions printed overleaf.

Issued on

3/7/18 at New Delhi by

(Vipin Kental)
Chief Fire Cfficer

To,

M/s Mirror Reloaded, (A Unit of 3's Hospitality Service) F-32,34 & 37, Star City Mall, Plot no. 1A, District Centre, Mayur Vihar-I, Delhi.

Copy to:-

The Deputy Health Officer,
Shahdara (South) Zone, EDMC,
Health Department, Shahdara South Zone,
Karkardooma, Delhi

Conditions -

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 6 This NOC may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

Apoln

| 1 1 | | ON REPORT | | | | |
|--|---|---|--------------------|---------|--|--|
| 1. 1 | Name & address of the building : Mirror Reloaded restaurant, at F-32,34 & 37 FF,Sta | | | | | |
| 2 0 | Mall, Plo | ot no. 1A, District Centre, Mayur Vihar-I, Delhi. | | | | |
| 2. Building is comprised of : Restaurant is running at First Floor of the bu | | | | | | |
| 3 Т | | ed of B+G+2 upp | per floors | | | |
| | | • | | | | |
| | . Hericwa | MS/EH/2014/NDZ/897 dated 22/07/14 MS/BP/2004/1969 Dated 30/08/2004 for Mall 8 | | | | |
| | 110/013/1 | | | | | |
| | -tC1 | | | | | |
| | are of inspection : 14/06/18 ame of the Inspecting Officers: : R.K.Yada | | | | | |
| 9. N | ame of the designation of Officer | av (ADO) | | | | |
| | | 1/ 1/2 | | | | |
| | /ear of Construction : 2007 | Kumar Mavi (Manager) | | | | |
| | . 2007 | 1 (5) (2010 (100) | | | | |
| S.No | Minimum Standards on fire prevention | I.(S)/2018/1281 | | | | |
| | and fire safety U/R33 | BBL/NBC | Provided at | Remarks | | |
| 1 | Access to building | requirement | Site | MR/NMR | | |
| | Road width | 10 | | | | |
| | Gate width | 12 m 4.5 m | 13 m | MR | | |
| | Width of internal road | 06 m | 06 m | MR | | |
| 2 | Number, Width, Type and Arrangement o | 2 25 25 25 | 06 m | MR | | |
| | a. Number of Staircases | TEXITS | | | | |
| | Upper Floor | 2 no. | 2 | | | |
| | Basement | N/A | 2 no. | MR | | |
| | B. Width of Staircases | , , , | IV/A | N/A | | |
| | Upper Floor | 1.25 | | | | |
| | Basement | 1.25 m | 1.25 m | MR | | |
| | c. Protection of exits | N/A | N/A | N/A | | |
| | Fire check door | | 200 | | | |
| | Pressurization | Required | Provided | MR | | |
| | e. No. of continuous staircases to terrace | Required | Provided | MR | | |
| | g. Width of Corridor | N/A | N/A | N/A | | |
| | h. Door size | 2.5 m | 2.5 m | MR | | |
| | | 2.0 m | 2.0 m | MR | | |
| 3 | Compartmentation. | | | | | |
| | Fire check door | Required | Provided | MR | | |
| | Sealing of electrical shafts | Required | Provided | MR | | |
| | Fire rating of shaft door | 2 hrs | 2hrs | | | |
| | Water curtain | N/A | | MR | | |
| | Fire Dampers | | N/A | N/A | | |
| | Smoke Management System. | N/A | N/A | N/A | | |
| | Basement | N/A | NI/A | 1 | | |
| | Upper floor | N/A 12 a/c per | N/A | N/A | | |
| | - - - - - - - - - - - - - - | hour | 12 a/c per hour | MR | | |

| | Fire Extinguisher | |). | 06 no. | MR | | |
|-----------|--|------------|--------------------------|--------------------------|--------------|----------|--|
| | Total numbers | | & CO ₂ | ABC & CO ₂ MR | | | |
| | • Types | 000 007 00 | arked | ISI marked | MR | X | |
| | IS marking | 131 111 | a | | | <u>«</u> | |
| | First-aid-Hose Reels. | 01 no. | | 01 no. | MR | | |
| | Total numbers of each floor | | | 30 m | | | |
| | Length of hose reel hose | 30 m | | 5 mm | MR | | |
| | Nozzle diameter | | | and the second | | | |
| 7 | Automatic fire detection and alarming system | | & Smoke | Provided | MR | | |
| | Type of detectors | | Control room basement | | MR | | |
| | Location of main panel | | | Provided | Provided MI | | |
| | Location of repeater panel | | eption | Provided | M | MR | |
| | Alternate source of power | | uired | & 18.15. | | MR | |
| | Hooters's location | 1 | tegic | Provided | 101 | | |
| | | | tions | D ided | M | R | |
| 8 | MOEFA | | uired | 100 | TOVIGEG | | |
| 9 | Public address System. | N/A | ١ | N/A | IN | /A | |
| 10 | Automatic Sprinkler System. | | | 1 21/2 | N | /^ | |
| 10 | basement | N/ | | N/A | N/A MR | | |
| | upper floor | Re | equired | Provided | | | |
| | sprinkler above false ceiling | N | /A | N/A | l N | I/A | |
| | Internal Hydrants | | | | | 40 | |
| 11 | size of riser/down-comer | 1 | 00 mm | 100 mm | | MR | |
| | Number of hydrants per floor | 1 | no. | 1 no. | | MR | |
| | Hose Box | 1 | no. | 1 no. | | MR | |
| | | | | | | | |
| 12 | Yard Hydrants. Total number of hydrants | N/A | | N/A | | N/A | |
| | | 1 | N/A | N/A | | N/A | |
| | Hose Box | - | У | | | | |
| 13 | Pumping Arrangements. • Ground Level | | | For Mal | | | |
| | Dumn | | 4500 LPM | 4500 LF | M | MR | |
| | L CAdain Dump | | 50 M | 50 M | | MR | |
| | f main numns | | 2 Nos | 2 Nos | | MR | |
| | t and the state of | | 450 LPM | 450 LP | M | MR | |
| | , head | | 50 M | 50 M | | MR | |
| | - u out nut | | 4500 LPM 4500 | | LPM MR | | |
| | u llood | | 50 M | 50 M | | MR | |
| | /Manual stonning | | Required Au | | | | |
| 44 | > Auto Starting / Ivialidal stopping > Pump House Access • Terrace Level | | | Provid | vided MR | | |
| | | | | | p on terrace | | |
| f annum n | | | All above Pump N/A N/A | | N/A | | |
| | I Cal Damen | | N/A N/A | | N/A | | |
| | | | 14// | | A N/A | | |
| | Power supplyAuto Starting of pump | | | N/A N/A | | N/A | |

My

| 14 | Captive Water Storage for Fire Fighting. For Mall | | | | | | | |
|----|---|---------------|----------------|-------|--|--|--|--|
| | Underground tank capacity | 2,00,000 Ltrs | 2,00,000 Ltrs | N/A | | | | |
| | Draw-off connection | Required | Provided | MR | | | | |
| | Fire service inlet | Required | Provided | MR | | | | |
| | Access to tank | Required | Provided | MR | | | | |
| | Overhead Tank capacity | 2,50,000 Ltrs | 2,50,000 Ltrs | MR | | | | |
| 15 | Exit Signage. | Required | Provided | MR | | | | |
| 16 | Provision of Lifts. | f Lifts. | | | | | | |
| 7. | Pressurization of Lift Shaft | Required | Provided | MR | | | | |
| | Pressurization of Lift lobby | Required - | Provided for | MR | | | | |
| | | | basement | | | | | |
| | Communication in lift car | Required | Provided | MR | | | | |
| | Firemen's grounding switch | Required | Provided | MR | | | | |
| | Lift Signage | Required | Provided | MR | | | | |
| 17 | Standby power supply | N/A | N/A | N/A | | | | |
| 18 | Refuge Area. | | | | | | | |
| | Total area | N/A | N/A | N/A | | | | |
| | Location | N/A | N/A | N/A | | | | |
| 19 | Fire Control Room | | | | | | | |
| | Detector system panel | Required | Provided | MR | | | | |
| | Flow switch panel | Required | Provided | MR | | | | |
| | PA system panel | Required | Provided | MR | | | | |
| | Batter backup | Required | Provided | MR | | | | |
| | Building Floor Plans | N/A | N/A | N/A | | | | |
| 20 | Special Fire Protection systems for | N/A | Provided in LT | MR | | | | |
| | protection of special Risks, if any: | | & HT Panels | 14111 | | | | |

Previously the Mirror Restaurant running at the same address and now owner has changed the name of the restaurant i.e. Mirror Reloaded restaurant. The fire protection systems provided in the building were test checked and found functional at the time of inspection. Entire Mall FSC had already issued by DFS vide letter no. F6/DFS/MS/2018/NDZ/1298 dated 04/06/18.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F6/DFS/MS/EH/2014/NDZ/897 dated 22/07/14 renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name

R.K.Yadav

Designation

ADO (LN)

DO (EAST)

submitted plear.

318/ CFO AM2

DYLPOLYDY