GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

No.F.6/DFS/MS/School/2018/SZ/ 1585

Dated: 06/07/18

FIRE SAFETY CERTIFICATE

Certified that the Shanti Gyan International School, Goyla, Najafgarh, New Delhi-110071, comprised of two blocks namely School Block & Hostel Block. School Block is having ground floor plus three upper floors having total 07 rooms at GF, 07 rooms FF, 07 rooms at SF & 01 room on third floor & Hostel Block is having ground floor plus one upper floor, owned/occupied by Shanti Gyan International School was issued NOC by this department vide letter no. F6/DFS/MS/2008/2144 dated 28.07.2008. The School building was re-inspected by the officer concerned of this department on 11.05.2018 in the presence of Mr. Ajay Singh (Vice-Principal) and found that now six additional rooms have been constructed on third floor. Shanti Gyan International School have complied/deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the school building/ premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 06 107/18 at New Delhi.

Note:- The Hostel building comprised of ground plus one upper floor issued FSC earlier by this department is not covered under DFS Act 2007 and Rules 2010 & require any FSC separately from this department.

> (VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Principal, Shanti Gyan International School, Goyla, Najafgarh, New Delhi-110071.
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if
- The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Comprised of Two blocks namely School Block (Ground floor plus three upper floors) & Hostel Block (Ground plus one upper floor)

INSPECTION REPORT

1. Name & address of the building: Shanti Gyan International School, Goyla, Najafgarh, New Delhi-71

2. Type of Occupancy : Educational3. Type of Case : Renewal/Addition

4. Details of Previous NOC : F6/DFS/MS/2008/2144 dated 28.07.2008

5. Fire Safety directives letter No : N/A
6. Date of inspection : 11.05. 2018

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Mr. Ajay Singh (Vice-Principal)

9. Year of Construction : Before 2008 & Addition of Rooms on third floor before 2010

10. Applicant's letter No. : SGIS/18-19/04/10 dated 15.04.2018

S. No.	8:	um Standards on fire prevention and ety U/R 33	Requirement as per NOC dt. 28.07,2008 9 DOC		Remark MR/NN		
1.	Access	to building	Ciculary 1-3.11				
	•	Road width	Accessible 06 mtrs	Provided	1	IR	
	•	Gate width	4.5 mtrs	05 mtrs		IR	
	•	Width of internal road	N/A	N/A	N.	/A	
2.		r, Width, Type & Arrangement of Exit	S		1		
	a. Num	ber of staircases					
	•	Upper Floors	02 no.'s in SB &	02 no.'s in each	I M	IR .	
	•	Basements	02 no.'s in HB	block	NI	/A	
	b Wide	th of staircases	N/A	N/A	IN.	/A	
	b. Widi			1220100	111 1	MR	
	Upper FloorBasements		150 cms/additional staircase of 75 cms	The second secon	& 100 cms in school block 70 cms (02 no.'s) split into		
		Basements	if less than 150 cms	two (120 cms each) i			
	in the state of th		N/A	block N/A	I N	/A	
	c. Prote	ection of exits	14/11	10/21	1	70 N	
	•	Fire check door	N/A	N/A	N	/A	
		Pressurization					
	d. No.	of continuous staircases to	N/A	N/A	IN	N/A	
	terr					(D)	
	e. Wic	dth of Corridor	Required	Two		MR	
	f. Do	or Size	150 cms	200 cms in SB & 180 cms in HB	N	1R	
			100 cms	107 cms in SB & 120 cms in HB	N	1R	
3.	Compa	artmentation		1			
7	•	Fire check door	N/A	N/A	N	I/A	
	•	Sealing of electrical shafts	N/A	N/A	N	I/A	
	•	Fire Rating of shaft door	N/A	N/A	N	I/A	
	•	Water Curtain	N/A	N/A	N	I/A	
	•	Fire Dampers	N/A	N/A		I/A	
4.	Smoke	Management System				3	
	• •	Basements	N/A	N/A	N/	'A	
	•	Upper floors	Required	Natural ventilation	M	R	
5.	Fire E	xtinguishers					
		Total numbers	12 no.'s	Provided	MI	R	
		Types	ABC/CO ₂ type	Provided	MI	R	
		IS marking	ISI marked	ISI marked	MI		
6.	First-A	Aid Hose Reels	151 markou				
						0	
	•	Total numbers on each floor in SB	01	Provided	MI		
	•	Length of hose reel hose	30 mtrs	Provided	M		
	4	Mozzlo diameter	5 mm	Provided	MI	R	

	• Type of detectors	IN/A	N/A	IV/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
3.	MOEFA	N/A	N/A	N/A			
).	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System						
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
10	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
10	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	➤ Head of Main pump	N/A	N/A	N/A			
	Number of main pumps						
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
Y 1.33	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
4.00	Auto Starting/Manual Stopping	N/A	N/A	N/A			
		N/A	N/A	N/A			
	N. D. T. T.	N/A	N/A	N/A			
	Pump House Access			A 11 A A			
	Terrace levelDischarge of pump	450 LPM	Provided	MR			
7	> Head of the pump	40 mtrs	Provided	MR			
	> Power Supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
	8 - F F	Required	Tiovided	IVIIX			
14.	Captive Water Storage for fire fighting						
		NI/A	NI/A	N/A			
	 Underground tank capacity Draw-off connection 	N/A	N/A				
	> Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	N/A	N/A	N/A			
		10,000 ltrs	Provided	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.			No Lift			
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	 Pressurization of Lift lobby 	N/A	N/A	N/A			
	 Communication In lift Car 	N/A	N/A	N/A			
	 Fireman's Grounding Switch 	N/A	N/A	N/A			
	Lift Signage						
		N/A	N/A	N/A			
17.	Standby power supply	N/A	N/A	N/A			
18.	Refuge Area.						
	D Total Area	NT/A	NT/A	NT/A			
	Total AreaLocation	N/A	N/A	N/A			
		· · · · · · · · · · · · · · · · · · ·		the state of the s			

19.	Fire C	Fire Control Room				
		Detector System Panel	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A	
		PA System Panel	N/A	N/A	N/A	
		Battery backup	N/A	N/A	N/A	
		Building Floor Plans	N/A	N/A	N/A	
•••	Consider	l Fire Protection System for Protection	N/A	N/A	N/A	
20.	of special Risks, if any:					

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/2008/2144 dated 28.07.2008 renewal/grant in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note: Earlier NOC was issued for 07 rooms on GF, 07 rooms on FF, 07 rooms on SF & 01 room on third floor & hostel block and Six rooms added on third floor.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

D.O. (South/West)

The 1. of 1001. region FSC earlier as not