GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/FH/SZ/2018/ 157 8

Dated: 28/6/18

FIRE SAFETY CERTIFICATE

Certified that the Kundan Farm House located at Khasra No. 16/11/2, 16/30, 17/14 & 17/29, Village Kapashera, Mehrauli, New Delhi comprised of sunken basement, ground floor & open farm house was granted FSC by this department vide letter no. F6/DFS/MS/FH/2015/SZ/951 dated 09/06/2015. The premises was re-inspected by the officer concerned of this department on 06/06/2018 in the presence of Mr. Dhruv Sharma & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010and that the building is fit for occupancy Group D "Assembly Building Farm House" with effect > 2-1-2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on....? ? / () at New Delhi by.

(Vipin Kental) **Chief Fire Officer** Ph:-011-23412235

Copy to:-

1. The Executive Engineer (Bldg), SDMC, Nazafgarh Zone, Main Zonal Building, Dasna Road, Nazafgarh, New Delhi-110043.

2. Sh. Dhruv Sharma, Kundan Farm House, Khasra No. 16/11/2, 16/30, 17/14 & 17/29,

Village Kapashera, Mehrauli, New Delhi

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. The use of basement shall be made as per the plans approved by the building department.

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first Service Rules 2010. http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms form is available

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to

-		NSPEC	TION REPORT				
1. 1		INSPECTION REPORT: Kundan Farm House located at Khasra No. 16/11/2, 16/30, 17/14 & 17/29, Village Kapashera, Mehrauli, New Delhi.					
2. 7	Гуре of Occupancy :	: Assembly Building Group "D" (Farm House)					
		: Assembly Building Group "D" (Farm House) : Renewal : F6/DFS/MS/FH/2015/SZ/951 dated 09/06/2015					
		: F6/DFS/MS/FH/2012/2134 dated 13/06/2012 : 06/06/2018					
6. I	or mopeonom						
	Name of Inspecting Officer : A.K. Malik Name and designation of officers From the building side : Sh. Dhruv Sharma						
				asement & ground floor			
			or diary no. 7532		1		
S.	Minimum Standards on fire preve		NBC/BBL	Provided at site	Remarks		
No.	and fire safety U/R 33	******	Requirement	- A	MR/NMR		
1.	Access to building		•		1 12 13		
	Road width		12 m	Provided	MR		
	 Gate width 		4.5 m	Provided	MR		
	 Width of internal road 		-NA-	-NA-	-NA-		
2.	Number, Width, Type & Arranger	ment of	Exits		_		
	a. Number of staircases						
	 Upper Floors 		-NA-	-NA-	-NA-		
	Basements		One	One -	MR (SunkenBasement)		
	b. Width of staircases			No. C. Control of the			
	Upper Floor		-NA-	-NA-	-NA-		
	Basements		Required	1.52m	MR (Basement floor is directly accessible being sunken)		
	c. Protection of exits				being sumeri)		
	 Fire check door Pressurization d. No. of continuous staircases to terrace e. Width of Corridor 		Required	Not provided	MR (old case)		
			-NA-	-NA-	-NA-		
			One	Not provided	MR (old case)		
			-NA-	-NA-	-NA-		
				GF: 2m & 2 of 1.07m	MR		
	f. Door Size		2m & 1 m (2Nos on each level)	Basement: 2m & 3 of 1.02m	IVIIC		
3.	Compartmentation		1				
-	Fire check door		-NA-	-NA-	-NA-		
	 Sealing of electrical shafts 				-NA-		
	• Fire Rating of shaft door		-NA-	-NA-			
	Water Curtain		-NA-	-NA-	-NA-		
	• Fire Dampers		-NA-	-NA-	-NA-		
			-NA-	-NA-	-NA-		
4.	Smoke Management System						
	Basements		30 ACPH	Natural Ventilation	-NA-		
	Upper floors		12 ACPH	Natural Ventilation	-NA-		
5.	Fire Extinguishers						
	Total numbers		6 No's	Provided	MR		
	• Types	and the second s	ABC/W.CO ₂ /CO ₂	3/3/-	MR		
	IS marking		ISI	Yes	MR .		
6.	First-Aid Hose Reels		.1	1.00			
0,	Total numbers on each floor	r	One	Provided	MR		
	• Length of hose reel hose		30 m	Provided	MR		
	Nozzle diameter		5 mm	Provided	MR		
7.	Automatic fire detection and alarming system						
	Type of detectors		-NA-	-NA-	-NA-		
	 Location of Main Panel 		-NA-	-NA-	-NA-		
	• Location of Repeater Panel	1			-NA-		
	Alternate source of power		-NA-	-NA-	and the same of th		
			-NA-	-NA-	-NA-		

Kundan Farm House located at Khasra No. 16/11/2. 16/30. 17/14 & 17/29 Village Kanashara Mahasuli N. D.

	Kundan Farm House located at Khasra No. 16 • Hooters' Location	/11/2, 16/30, 17/14 & 17	7/29, Village Kapashera, Me	ehrauli, New Delhi			
8.		-INA-	-NA-	-NA-			
9.	Public Address System	Required -NA-	Provided	MR			
10	O. Automatic Sprinkler System	-INA-	-NA-	-NA-			
	 Basement 	-NA-	-NA-	N/A			
	Ground Floor	-NA-	-NA-	-NA-			
11	Sprinkler above false ceiling	-NA-	-NA-				
11	and the state of t			-NA-			
	• Size of riser/down-comer	100 mm	Provided	MR			
	Number of hydrants per floorHose Box	01	01	MR			
12		01	01	MR			
	Junuinus			The second of th			
	Total number of hydrantsHose Box	-NA-	10 No's provided				
13.		-NA-	10 No's provided	-NA-			
	Ground Level						
	Discharge of main Pump	27.		-			
	Head of Main pump	-NA-	-NA-	-NA-			
	Number of main pumps	-NA-	-NA-	-NA-			
	> Jockey Pump out put	-NA-	-NA-	-NA-			
	Jockey pump head	-NA-	-NA-	-NA-			
	Standby Pump out put	-NA-	-NA-	-NA-			
	Standby Pump Head	-NA-	-NA-	-NA-			
	Auto Starting/Manual	-NA-	-NA-	-ΝΛ-			
	Stopping	-NA-	-NA-	-NA-			
	Pump House Access	-NA-	-NA-	-NA-			
	Terrace level			-11/1-			
	Discharge of pump	900 LPM	Provided at Ground Leve	MR (old case)			
	Head of the pumpPower Supply	40m	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
		Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	-NA-	50,000 1				
	Draw-off connection	-NA-	50,000 Liters	-NA-			
	Fire service inlet		-NA-	-NA-			
	Access to tank	-NA-	-NA-	-NA-			
	 Overhead Tank capacity 	10000 Lts	-NA-	-NA-			
15.	Exit Signage.	Required	Provided Provided	MR			
16.	Provision of Lifts. Required Provided MR						
	 Pressurization of Lift Shaft 	-ΝΛ-	X1.4				
	 Pressurization of Lift lobby 		-NA-	-NA-			
40	 Communication In lift Car 	-NA-	-NA-	-NA-			
	• Fireman's Grounding Switch		-NA-	-NA-			
	• Lift Signage	-NA-	-NA-	-NA-			
17.	Standby nower	-NA-	-NA	-NA-			
	Standby power supply Refuge Area.	Required	Provided	MR			
10.	Total Area			1			
	Location	-NA-	-NA-	-NA-			
19.	Fire Control Room	-NA-	-NA-	-NA-			
	Detector System Panel						
	Flow Switch Panel	-NA-	-NA-	-NA-			
- Marian	and the state of t	-NA-	-NA-	-NA-			
	Tri System Lanel	-NA-	-NA-	-NA-			
	rattery backup	-NA-	-NA-	-NA-			
	Building Floor Plans	-NA-	-NA-				
20.	Special Fire Protection System for	-NA-	,	-NA-			
-	Joseph IVI	-1 V/1-	- N/A	314			

-019-

Kundan Farm House located at Khasra No. 16/11/2, 16/30, 17/14 & 17/29, Village Kapashera, Mehrauli, New Delhi The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35(3) of the Delhi Fire Service Rules 2010.

Accordingly Form "H" in shape of DFA is put up for approval under Rule 35(4).

Signature of Inspecting Officer

Name: A. K. Malik Designation: DO (SD)

- I The FSC Was resucced for Gif only. of the sunken basement is added later on by licence of not in use
- rest is use of this summen part base-ment now of meets Exit regurement

1533/c/20152

May please see the appeared Sanction blan at Cl2+ Cl8. The Sasement is appeared Structe. The parameters were not mentioned by inspecting officer in previous note.