GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/GH/2018/SZ/ 1052

Dated: 1.7.1.5.7.18

FIRE SAFETY CERTIFICATE

Certified that M/s **Hotel Lords Inn** located at A–10, C.R. Park, New Delhi, comprised of Basement, Ground & 03 upper floors (20 Guest Rooms) was issued FSC by this department vide letter No. F.6/DFS/MS/GH/2015/SZ/489 dated 07/04/2015. The premises was re-inspected by officer concerned of this department on 20/04/2018 in presence of Mr. Harmeet Madan (Prop.) and found that guest house premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class 'Residential' Group–A, (Lodging & Rooming House) as above with effect from the date of issue of this certificate for a period of **Three years** subject to compliance of the conditions mentioned below

Issued on 1418 at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to: -

0

- 1. The Addl. Comm. of Police (Lic.), Ist Floor, P.S. Defence Colony, New Delhi-110049
- 2. The Proprietor, M/s Hotel Lords Inn at A-10, Chitranjan Park, New Delhi-110019

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	INSPECTIO	ON REPORT	I LINE LANGE			
1	Name & Address of the Building	M/s Hotel Lords Inn at A–10, Chitranjan Pa				
		Near Savitri Cinema Complex, New Delhi-19				
2	Type of Occupancy	Residential, Group-A (Guest House)				
3	Building Comprised of	Basement, Ground + 03 upper floors				
4	Type of Case	Renewal				
5	Details of Previous NOC	F.6/MS/DFS/	GH/2015/SZ/489 dated (07-04-2015		
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	20-04-2018		T		
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	Name & Designation of Officers	Mr. Harmeet Madan (Prop.)				
	from the building side					
10	Year of construction	Basement (Office, Hall), Gd floor (Rec. & 04 rooms 1st and 2nd floor (08 rooms each), 3rd floor (owner residence) Total 20 Guest Rooms.				
11	Applicant letter No.		P/Lic. (H) dated 20-03-2	018		
S. No		Old NOC	Provided at Site	Remarks		
	and Fire Safety U/R 33	requirements		MR/NMI		
1	Access to Building.	- 1,10				
	Road width.	Required	10 mts.	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, width, type & arrangement of exits.					
	a. Number of Staircase					
	Upper floors	One	Provided	MR		
	Basement floor	Two	Provided	MR		
	b. Width of Staircase					
1	Upper floors.	1.25m	1.26m	MR		
	Basement floor.	1.25m	1.26m & 1.20m	MR (old case)		
	c. Protection of exits	×				
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircase to terrace	One	Provided	MR		
	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	1m	1.25m (final exit)	MR		
3 -	Compartmentation.	1111	1.25m (mai cxit)	IVIIC		
	Fire check door.	N/A	N/A	N/A		
	Sealing of electrical shafts.	Required	Provided	MR		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain.	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4.						
4.	Smoke Management system.					
4.	Smoke Management system. Basement	30 ACPH	Exhaust fan provided	MR		
4.		30 ACPH 12 ACPH	Exhaust fan provided N/A			
4. 5.	Basement			MR N/A		
	Basement Upper floors					
	Basement Upper floors Fire Extinguishers.	12 ACPH	N/A	N/A MR		
	Basement Upper floors Fire Extinguishers. Total numbers	12 ACPH Required	N/A 12 Nos	N/A MR		
	Basement Upper floors Fire Extinguishers. Total numbers Types	12 ACPH Required ABC / CO2	12 Nos W.CO2, ABC & CO2	MR MR		
5.	Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking	12 ACPH Required ABC / CO2	12 Nos W.CO2, ABC & CO2	MR MR		
5.	Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels.	Required ABC / CO2 ISI Marked	N/A 12 Nos W.CO2, ABC & CO2 Provided	MR MR MR		

M/s Hotel Lords Inn at A-10, Chitranjan Park, New Delhi

7 A	utomatic fire detection & alarming system.			
A	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
*	Hooter's location	Required	Provided	MR
8. M	IOEFA	Required	Provided	MR
	ublic Address System	Required	Provided	MR
	utomatic Sprinkler System	Required	4	
IV. A	Basement	Required	Provided	MR
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11. In	nternal Hydrants.	1112		
11.	Size of Riser / Down-comer	N/A	N/A	N/A
	Number of Hydrant per floor	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
12. Y	ard Hydrants.	14/11	17/11	14/11
140	Total number of hydrants.	N/A	N/A	N/A
		N/A	N/A	N/A
	Hose box.	IV/A	IN/A	IV/A
13. Pt	umping arrangements.			
	Ground Level	37/1	77/4	27/4
Tr.	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	450 LPM	Provided	MR
	> Head of pump.	40 mtr	Provided	MR
	> Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
14. C	aptive water storage for Fire Fighting.	NIA	T N/A	DT/A
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A N/A
	Fire Service Inlet.	N/A	N/A N/A	N/A N/A
	Access to tank.	N/A 5 000 Ltr	N/A Provided	MR
E E	Overhead tank capacity.	5,000 Ltr. Required	Provided Provided	MR
	xit Signage. rovision of Lifts.	Required	Flovided	IVIK
16. P		N/A	N/A	N/A
	Pressurization of lift shaft.	N/A N/A	N/A N/A	N/A
	Pressurization of lift lobby.	N/A N/A	N/A N/A	N/A N/A
	Communication in lift car.	N/A N/A	N/A N/A	N/A N/A
	• Fireman's switch.			
	• Lift signage.	N/A	N/A	N/A
	tandby Power Supply	Required	Provided (DG Set)	MR
18. R	efuge Area	27/4	37/4	BT/A
	Total area	N/A	N/A	N/A
-	• Location	N/A	N/A	N/A

M/s Hotel Lords Inn at A-10, Chitranjan Park, New Delhi

19.	Fire Control Room.			<u> </u>
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any.			

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/MS/DFS/GH/2015/SZ/489 dated 07-04-2015, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: R.N. Singh Designation: ADO (BCP)

M/s Hotel Lords Inn at A-10, Chitranjan Park, New Delhi

260/cfo.22 dy 33450 18-114/1-18-114/1-18-114/1-24-418

miscell FTM,

A Dob Letter Part of for

COO(\$2)

miscell Mys

Signordore Mean

05/10/185) TIMS/18