GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/GH/2018/SZ/ 1058

FIRE SAFETY CERTIFICATE

Certified that Hotel Tryfena, located at B-14, East of Kailash, New Delhi-110065 comprised of basement, stilt, ground & 03 upper floors (30 guest rooms) was issued FSC by this department vide letter No. F.6/DFS/MS/GH/2015/SZ/155 dated 03-02-2015. The guest house premises was re-inspected by officer concerned of this department on 23/04/2018 in the presence of Mr. Subash and observed that said guest house premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class 'Residential' Group—A, (Lodging & Rooming House) as above with effect from [41,5] 2018 for a period of Three years subject to compliance of the conditions mentioned below

Issued on 44518 at New Delhi by

(Vipin Kental)
Chief Fire Officer

Copy to: -

- 1. The Addl. Comm. of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049
- 2. The Manager, Hotel Tryfena, B-14, East of Kailash, New Delhi-110065

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

		NI DED COM			
		N REPORT		B # 1	
1	Name & Address of the Building	Hotel Tryfena,B-14, East of Kailash, New Delhi- 110065			
2	Type of Occupancy	Residential, Group-A (Guest House)			
3	Building Comprised of	Basement, Stilt, Ground + 03 upper floors			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/GH/2015/SZ/155 dated 03-02-2015			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	23-04-2018		7	
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)			
9	Name & Designation of Officers	Sh. Subash			
	from the building side		7		
10	Year of construction	2010 (30 guest rooms)			
11	Applicant letter No.	Nil dated 02-04-2018 (Old Case)			
S. No	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remark	
	and Fire Safety U/R 33	requirements		MR/NMI	
1	Access to Building.			,	
	Road width.	9 mts.	Provided	MR	
	Gate width	Required	Direct Approachable	MR	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of exits.				
	a. Number of Staircase				
	Upper floors	One	Provided	MR	
	Basement floor	Two	Provided	MR	
	b. Width of Staircase				
	Upper floors.	1.25m	1.28m	MR	
	Basement floor.	1.25m	1.20m,1.05m	MR	
	c. Protection of exits				
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
		One	Provided 01 nos	MR	
		N/A	N/A		
	e. Width of corridor f. Door size	N/A N/A	N/A N/A	N/A N/A	
3	Compartmentation.	IN/A	IN/A	IN/A	
3	Fire check door.	N/A	N/A	N/A	
	 Sealing of electrical shafts. 	N/A	N/A	N/A	
	 Fire rating of shaft door. 	N/A	N/A	N/A	
	Water curtain.	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
4.	Smoke Management system.	14/71	IV/A	IVA	
4.	Basement	30 ACPH	Exhaust fan provided	MR	
	Upper floors	12 ACPH	N/A	N/A	
5.	Fire Extinguishers.	12 ACFII	11/71	14/74	
J.	Total numbers	Required	14 Nos	MR	
	Types	ABC / CO2	ABC & CO2	MR	
	ISI Marking	ISI Marked	Provided Provided	MR	
6.	First Aid Hose Reels.	131 Walkeu	Flovided	IVIK	
0.	Total numbers on each floor.	One	Provided	MR	
		30m	Provided		
	Length of hose-reel hose.			MR	
	 Nozzle Diameter 	5mm	Provided	MR	

7	Automatic fire detection & alarming system.			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			
	Size of Riser / Down-comer	N/A	1 no provided	N/A
	Number of Hydrant per floor	N/A	1 no provided	N/A
	Hose box.	N/A	1 no procvided	N/A
12.	Yard Hydrants.		1	- 1
R. And to	Total number of hydrants.	N/A	provided	N/A
		N/A	provided	N/A
4.0		14/17	provided	
13.	Pumping arrangements.			
	Ground Level	N/A	N/A	N/A
	Discharge of main pump.	N/A	N/A	N/A
	> Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A N/A	N/A	N/A
	Jockey Pump head.Standby Pump output.	N/A	N/A	N/A
		N/A	N/A	N/A
	Standby Pump head.Auto Starting/Manual Stopping.	N/A N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	A	14/71	17/13	14/18
	Terrace Level Discharge of nump	900 LPM	Provided 450X 2no	MR
	Discharge of pump.	40 mtr	Provided each	MR
	Head of pump.Power supply.	Required	Provided	MR
	Power supply.Auto starting of pump.	Required	Provided	MR
1.4	Captive water storage for Fire Fighting.	Required	11011000	
14.	Underground tank capacity.	· N/A	N/A	N/A
	 Onderground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	10,000 Ltr.	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	1		
10.	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	m: 1 1 1	Required	Provided	MR
4.00		Required	Provided	MR
	Lift signage. Standard Sandard Standard Standard	Required	Provided	MR
17	Standby Power Supply	Required	110/1000	
18.	Refuge Area	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	 Location 	IN/A	IN/A	14/14

19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	Required	01 co2 type fire	MR
	Protection of special Risk, if any.		extinguisher provided	
			near elect panel	

The Fire protection systems provided in the premises/building were test checked at random and found functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter F.6/DFS/MS/GH/2015/SZ/155 dated 03-02-2015, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

R.N. Singh Name: Designation: ADO (BCP)

) CS2/ miscell