GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2018/ 828

Dated: .6.8.1.8

FIRE SAFETY CERTIFICATE

Certified that M/s **The Fatty Bao Restaurant** (A Division of Olive Café South Pvt. Ltd) at Sangam Courtyard, Plot No-9, Sector-9, R.K. Puram, New Delhi-110022, located at 2nd Floor of the building comprised of three basements, ground plus two upper floors was issued Fire Safety Certificate by this department vide letter No. F.6/MS/DFS/EH/2015/SZ/1177 dated 06/07/2015. The premises was re-inspected by the officer concerned of this department on 25/07/2018 in the presence of Mr. Sumer Singh (Manager) of the restaurant and found that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly, **Group-D**" (Restaurant) with effect from the date of issue of this certificate for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 6/8/8 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph: 011-23412225

Copy to: -

- 1. Auth. signatory, M/s The Fatty Bao Restaurant (A Division of Olive Café South Pvt. Ltd), 2nd Floor, Sangam Courtyard, Plot No-9, Sector-9, R.K. Puram, New Delhi-110022
- 2. DHO, South MCD, Public Health Department, South Zone, Green Park, New Delhi-110016

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept unlocked & free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

	INSPECTIO	ON REPORT			
1	Name & Address of the Building	M/s The Fatty Bao	Restt. (A Division of	Olive Café	
1	Traine & Fragress of the 2 shames	South Pyt. Ltd.) at 2 nd Floor, Sangam Courtyard Mall,			
	· · · · · · · · · · · · · · · · · · ·	Plot No-9, Sector-9, R.K. Puram, New Delhi-110022			
2	Type of Occupancy	Assembly "Group-D" (Eating House)			
3	Building Comprised of	Three tier basements, ground + 02 upper floors.			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/MS/DFS/EH/2015/SZ/1177 dated 06/07/2015			
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/2010/1304 dated 04.05.2010			
7	Date of Inspection	25-07-2018			
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)			
9	Name & Designation of Officers	Mr. Sumer Singh (Manager)			
,	from the building side				
10	Year of construction	Restt located at 2 nd floor of the building.			
11	Applicant letter No.	Outdoor Diary No	. 9643 dated 05.07.20	18	
S. No.	Minimum standards on Fire Prevention			Remarks	
	and Fire Safety U/R 33	requirements		MR/NMF	
1	Access to Building.	F6/DFS/MS/SZ/C	Cinema/2017/1725 Dt	. 01/12/2017	
	Road width	Restt. within	As above	MR	
	• Gate width	Commercial	As above	-NA-	
	Width of internal road	Complex Bldg	As above	-NA-	
2	Number, width, type & arrangement of	exits.			
	a) Number of Staircase	Provided	& Maintained by Bldg	g Mgmt	
	> Upper floors.	02 Nos	As above	MR	
	Basement floor.	-NA-	As above	-NA-	
	O Shot Manual Ma		& Maintained by Bldg	g Mgmt	
	b) Width of Staircase	2 mtr	As above	MR	
	> Upper floors	-NA-	As above	-NA-	
	> Basement floor	Provided & Maintained by Bldg Mgmt			
	c) Protection of exits		As above	MR	
	➤ Fire check door	Required	As above	MR	
	Pressurization	Required	As above	MR	
	d) No. of continuous staircase to terrac	e Required	As above As above	MR	
	e) Width of corridor	2 mtr		MR	
	f) Door size	2 exit (2m/1m) 2m x 1 & 1m x 2 Provided & Maintained by Bldg Mgn			
3	Compartmentation.			MR	
	Fire check door.	Required	As above	MR	
	 Sealing of electrical shafts. 	Required	As above	MR	
	 Fire rating of shaft door. 	Required	As above As above	-NA-	
	Water curtain	-NA-	As above As above	-NA-	
	Fire dampers.	-NA-			
4.	Smoke Management system.	Provided & Maintained by Bldg Mg		MR	
	Basement	30 ACPH	As above	MR	
	Upper floors	12 ACPH	Provided	IVIIV	
5.	Fire Extinguishers.		0631	MR	
	Total numbers	Required	06 Nos	MR	
	• Types	ABC / CO2	ABC type		
	ISI Marking	ISI marked	Provided	MR	
6.	First Aid Hose Reels.	Provided & Maintained by Bldg Mgmt			
	Total numbers on each floor.	Required	02 Nos near Restt		
	 Length of hose-reel hose. 	30 mtr	Provided	MR	
		5 mm	Provided	MR	
	Nozzle Diameter The Fatty Bao Restt at 2 nd Floor, Sangam Cou			Now Delhi	

The Fatty Bao Restt at 2nd Floor, Sangam Courtyard Mall, Plot No-9, Sec-9, RK Puram, New Delh

-	Automatic fire detection & alarming system.	Provided &	Maintained by Bldg Mg	mt	
7		Required	Smoke & Heat	MR	
	Type of detectorsLocation of Main Panel	Required	Ground floor	MR	
		Required	FCR	MR	
	Location of Repeater Panel	Required	Provided	MR	
	Alternate source of power	Required	Provided	MR	
	Hooter's location	Required	Provided	MR	
8.	MOEFA	-NA-	As above	-NA-	
9.	Public Address System	Provided & Maintained by Bldg Mgmt			
10.	Automatic Sprinkler System	-NA-	As above	-NA-	
	Basement	Required	As above	MR	
	Upper floors. / Restt. Area	-NA-	As above	-NA-	
	Sprinkler above false ceiling	Provided &	Maintained by Bldg M	emt	
11.	Internal Hydrants.		As above	MR	
	Size of Riser/Down-comer	Required	As above	MR	
	 Number of Hydrant per floor 	Required	As above	MR	
	Hose box.	Required	AS above	17111	
12.	Yard Hydrants.	D 1 1	As above	MR	
	Total number of hydrants.	Required		MR	
	Hose box.	Required	As above	IVIIV	
13.	Pumping arrangements. Fire fighting system is common for entire complex				
	Ground Level		tem is common for entir	MR	
	Discharge of main pump.	2850 LPM	2850 LPM	MR	
	Head of main pump.	70m	70m	MR	
	Number of main pumps.	02 Nos	02 Nos		
	Jockey Pump output.	180 LPM	180 LPM	MR	
	Jockey Pump head.	70m	70m	MR	
	Standby Pump output.	2850 LPM	2850 LPM	MR	
	Standby Pump head.	70m	70m	MR	
	Auto Starting/Manual Stopping.	Required	Provided	MR	
	Pump house access.	Required	Provided	MR	
	Terrace Level				
	Discharge of pump.	-NA-	-NA-	-NA-	
	Head of pump.	-NA-	-NA-	-NA-	
	Power supply.	-NA-	-NA-	-NA-	
	Auto starting of pump.	-NA-	-NA-	-NA-	
14.	Captive water storage for fire fighting.		stem is common for ent	ire comple	
1-7-	Underground tank capacity.	Required	2,00,000 Ltr	MR	
	> Draw-off connection.	Required	Provided	MR	
	Fire Service Inlet.	Required	Provided	MR	
	Access to tank.	Required	Provided	MR	
	 Overhead tank capacity. 	5,000 Ltr	20,000 Ltr	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.	Provided & Maintained by Bldg Mgmt		Mgmt	
10.	Pressurization of lift shaft.	Required	As above	MR	
	Pressurization of lift lobby.	Required	As above	MR	
	• Communication in lift car.	Required	As above	MR	
	• Fireman's switch.	Required	As above	MR	
	• Lift signage.	Required	As above	MR	
17		Required	Provided (DG Set)	MR	
17.					
18.	• Total area	-NA-	-NA-	-NA	
	,40 (34 AtS).	-NA-	-NA-	-NA	
	Location The Fatty Bao Restt at 2 nd Floor, Sangam Cour			lovy Dolhi	

The Fatty Bao Restt at 2nd Floor, Sangam Courtyard Mall, Plot No-9, Sec-9, RK Puram, New Delhi

19.	Fire Control Room.	Provided & Maintained by Bldg Mgmt		
	 Detector system panel. 	-NA-	As above	-NA-
	• Flow switch panel.	-NA-	As above	-NA-
	PA system panel.	-NA-	As above	-NA-
	Battery backup.	-NA-	As above	-NA-
	Building floor plan.	-NA-	As above	-NA-
20.	Special Fire Protection System for the	-NA-	-NA-	-NA-
	Protection of special Risk, if any.			

The fire protection system provided in the building/ premises were checked/ operated at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/MS/DFS/EH/2015/SZ/1177 dated 06/07/2015, renewal under rule 37 of the Delhi Fire Service Rules 2010, is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

The Fatty Bao Restt at 2nd Floor, Sangam Courtyard Mall, Plot No-9, Sec-9, RK Puram, New Delhi

21/2/18
21/2/18
21/2/18
21/2/18

DO (SD)

rapple 18

Cho spr m-scell

A. D. H. COR Sust ins for

C80 (82)

M. SCEU WE 6/8/18

Signotore Mean

618/18/AMDISS,