

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/DFS/MS/EH/SZ/2018/ 18118

Dated: 8/8/18

FIRE SAFETY CERTIFICATE

Certified that the M/s. Mughal Mahal Restaurant located at lower ground floor of Sethi Bhawan, 7, Rajendra Place, New Delhi- 110008 comprised of lower ground, upper ground plus six upper floors but restaurant is running at lower ground floor only, was granted FSC by this department vide letter No. F6/DFS/MS/EH/2015/1384 dated 31.07.2015. The premises was re-inspected by the officer concerned of this department on 30/07/2018 in presence of Sh. Rajesh Kalra (manager) and found owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class assembly (restaurant) with effect from 8/8/18 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 8/8/18 at New Delhi by.


(VIPEN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

1. Sh. Rajesh Kalra (Manager),
M/s. Mughal Mahal Restaurant,
Sethi Bhawan, 7, Rajendra Place, New Delhi- 110008.

Following Fire Safety Directives must be adhered to: -

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
3. The trained firefighting staffs should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of BBL.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : M/s. Mughal Mahal Restaurant, Sethi Bhawan, 7, Rajendra Place, New Delhi- 110008.
2. Type of Occupancy : Assembly (Restaurant)
3. Type of Case : Renewal
4. Details of previous NOC : F.6/DFS/MS/EH/2015/1384 dated 31.07.2015
5. Fire Safety directives letter No : N/A.
6. Date of inspection : 30.07.2018
7. Name of the Inspecting Officers : M.K. Chattopadhyay, Divisional Officer (South West)
8. Name and designation of officers from the building side : Sh. Rajesh Kalra, Manager
9. Year of Construction : Before 1980
10. Applicant's letter No. : Form 'J' dated 18.07.2018

The said restaurant is running at lower ground floor of Sethi Bhawan comprised of lower ground, upper ground plus six upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per FSC dt.- 31.07.2015	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	09 mts	Provided	MR
	• Gate width	4.5 mts	Provided	MR
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	-	-	-
	• Upper Floors	-	Running at ground lower ground floor	--
	• Basements	N/A	N/A	N/A
	b. Width of staircases	-	-	-
	• Upper Floors	-	Running at ground lower ground floor	--
	• Basements	N/A	N/A	N/A
	c. Protection of exits	N/A	N/A	N/A
	• Fire check door	-	-	-
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
		N/A	N/A	N/A
	g. Width of Corridor	N/A	N/A	N/A
	h. Door Size	02 exit door	1.03 mts, 0.98 mt	MR being old case
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	Sealed	----
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
			N/A	N/A

	<ul style="list-style-type: none"> Types IS marking 	CO ₂ , ABC type ISL marked	Provided Provided	MR MR
6	First-Aid Hose Reels.			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	01 30 m 5 mm	Provided & connected with sethi Bhawan Provided Provided	MR MR MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A N/A N/A Required N/A	N/A N/A N/A D.G. set (62.5 KVA) N/A	N/A N/A N/A MR N/A
8	MOEFA	Required	Provided & connected with sethi Bhawan	MR
9	Public Address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Entire Restaurant Sprinkler above false ceiling 	N/A Required N/A	N/A Provided & connected with sethi Bhawan N/A	N/A MR N/A
11	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	100 mm 01 01	Provided & connected with sethi Bhawan Provided Provided	MR MR MR
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A N/A	N/A N/A	N/A N/A
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply 	--- N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A ----- 900, 220 LPM 30 mts Required	--- N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A ----- Provided & connected with sethi Bhawan Provided Provided	--- N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A ----- MR MR MR

N/17


	<ul style="list-style-type: none"> Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank Overhead Tank capacity 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	Provided & connected with Sethi Bhawan	----
		N/A	N/A	N/A
		5000 lts	Provided (50,000 lts) & connected with Sethi Bhawan	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby power supply	Required	Provided & connected with Sethi Bhawan	MR
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/EH/2015/1384 dated 31.07.2015, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

31/08/18
2/8/2018


28/8/18

M.K. CHATTOPADHYAY
Divisional Officer (South West)

DCFO (SZ)





M. S. Chauhan

FTD

W
6/8

Chattopadhyay