GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001

No.F.6/DFS/MS/School/2018/SZ/

Dated:

20/8/18

FIRE SAFETY CERTIFICATE

Certified that the **New Holy Faith Public School,** Kh. No. 41//9/1(2-8), Village-Haibatpura, Najafgarh, New Delhi-110043 comprised of ground floor plus one upper floor, owned/occupied by New Holy Faith Public School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2014/SZ/1028 dated 13.08.14. The School building was re-inspected by the officer concerned of this department on 31.07.2018 in the presence of Sh. Manish Tehlan (Principal) and found that now second floor has been constructed and having total 30 rooms (Including, Class rooms, Sports room, Office, Library, Store room etc.). New Holy Faith Public School have complied/deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on. 2018/19 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Chairman, New Holy Faith Public School, Kh. No. 41//9/1(2-8), Village-Haibatpura, Najafgarh, New Delhi-110043
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. There shall not be more than 45 children in the classrooms at second floor as width of second exit is less than 01 meter.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

School building is comprised of ground plus two upper floors. INSPECTION REPORT 1. Name & address of the building: New Holy Faith Public School, Kh. No. 41//9/1(2-8), Vill.-Haibatpura, New Delhi-110043. Type of Occupancy Educational Type of Case New/Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2014/SZ/1028 dated 13.08.14 (For GF & FF Only) 5. Fire Safety directives letter No : N/A 6. Date of inspection 31.07.2018 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. Manish Tehlan (Principal) 9. Year of Construction 2006 (GF & FF) & 2016-17 (SF) 10. Applicant's letter No. Nil dated 21.06.2018 S. No. Minimum Standards on fire prevention and Provided at Remarks fire safety U/R 33 requirements site MR/NMR 1. Access to building Road width Accessible M/R, being old case 4.7 mtrs 4.5 mtrs Gate width Directly accessible MR N/A from road Width of internal road N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 02 No.'s Provided M/R Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms 154, 150 & 110 M/R Basements (02 no.'s) c. Protection of exits cms N/A N/A N/A Fire check door Pressurization N/A N/A N/A d. No. of continuous staircases to N/A N/A N/A terrace e. Width of Corridor N/A N/A N/A f. Class room door Size 150 cms. 220 cms M/R 90 & 90 cms (GF & FF) 100 cms M/R 90 & 100 cms (Double. doors) on SF 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. Smoke Management System Basements N/A N/A N/A Upper floors Required Natural ventilation M/R provided 5. Fire Extinguishers Total numbers 12 no's Provided MR ABC/CO2 type **Types** Provided MR IS marking Provided MR ISI marked First-Aid Hose Reels 6. Total numbers on each floor 02 no.'s per floor Provided MR 30 mtrs Length of hose reel hose Provided MR 5 mm Dearidad Mazzla diamatan

| 7. | Automatic fire detection and alarming system | | | |
|-----|--|-------------------|-------------------|------------|
| | Type of detectors | N/A | N/A | N/A |
| | Location of Main Panel | N/A | N/A | N/A |
| | • Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of powerHooters' Location | N/A | N/A | N/A |
| | Hooters' Location | N/A | N/A | N/A |
| 8. | MOEFA | N/A | N/A | N/A |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | 27/4 | 27// | 27/1 |
| | Basement | N/A | N/A | N/A |
| | Ground Floor Springly a share Colonia 11. | N/A | N/A | N/A |
| 11. | Sprinkler above false ceiling Internal Headers 4. | N/A | N/A | N/A |
| 11. | Internal Hydrants • Size of riser/down-comer | N/A | N/A | N/A |
| | Number of hydrants per floor | N/A | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 12. | Yard Hydrants | IN/A | IN/A | IN/A |
| 12. | Total number of hydrants | N/A | N/A | N/A |
| | Hose Box | N/A N/A | N/A N/A | N/A N/A |
| 13. | Pumping Arrangements | IN/A | 11/71 | IN/A |
| 10. | z amping zarangements | | | |
| | Ground Level | | | |
| | Discharge of main Pump | N/A | N/A | N/A |
| | > Head of Main pump | N/A | N/A | N/A |
| | Number of main pumpsJockey Pump out put | N/A | N/A | N/A |
| | > Jockey pump head | N/A | N/A | N/A |
| | Standby Pump out put | N/A | N/A | N/A |
| | Standby Pump Head | N/A | N/A | N/A |
| | Auto Starting/Manual Stopping | | | |
| | | N/A | N/A | N/A |
| | , | N/A N/A | N/A | N/A |
| | Pump House Access | IN/A | N/A | N/A |
| | • Terrace level | 450 1 03 5 | D | 100 |
| | Discharge of pump | 450 LPM | Provided | MR |
| | Head of the pumpPower Supply | 30 mtrs | Provided Provided | MR MR |
| | > Auto Starting of pump | Required Required | Provided | MR MR |
| | and a summy or pump | Required | riovided | IVIN |
| 14. | Captive Water Storage for fire fighting | | | |
| | Underground tank capacity | N/A | N/A | N/A |
| | Draw-off connection | N/A | N/A | N/A |
| | Fire service inlet | N/A | N/A | N/A |
| | Access to tank | N/A | N/A | N/A |
| | Overhead Tank capacity | 10000 ltrs | Provided | MR |
| 15. | Exit Signage. | Required | Provided | MR |
| 17 | | * 15 | | |
| 16. | Provision of Lifts. | DT/A | No Lif | |
| | Pressurization of Lift Shaft Pressurization of Lift Shahy | N/A | N/A | N/A |
| | Pressurization of Lift lobbyCommunication In lift Car | N/A | N/A | N/A |
| | Fireman's Grounding Switch | N/A | N/A | N/A |
| | Lift Signage | N/A | N/A | N/A |
| | ~ ~. g.m.g~ | N/A | N/A | N/A |
| 17. | Standby power supply | N/A | N/A | N/A |
| 18. | Refuge Area. | | | |
| 10. | > Total Area | N/A | N/A | N/A |
| | > Location | | | |
| | | N/A | N/A | N/A |

2/18

| 19. | Fire Control Room | | | |
|-----|---|-----|-----|-----|
| £ , | Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 20. | Special Fire Protection System for Protection of special Risks, if any: | N/A | N/A | N/A |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings communicated by this department vide letter no. F.6/DFS/MS/School/2017/SZ/1714 dated 07.07.17 has been complied.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Note:- As per the sizra certificate (placed at C-30,31 & 26) issued by Tehsildar, SDM Office Complex, Tura Mandi, Najafgarh, New Delhi-110043 address of the above mentioned school is Kh. No. 41//9/1, Village Haibatpura, New Delhi and road is 06 meter wide in front of the school.

As per the undertaking given by the Principal (placed at C-33,34) the school is comprises of ground plus two upper floors and total 30 rooms. In each class room no. of students are less than 45.

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

703/00/500

Divisional Officer (South West)

D6/8/18

Chief Fire Original Property Chief Fire Origi

198

F7101

miscell

U W