

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001 No. F.6/DFS/MS/EH/SZ/2018/ 2011

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of Tum Tum Asia (A Unit of Corporate Services Pvt. Ltd.), 2, Ground Floor, Eros Corporate Tower, Nehru Place, New Delhi-110019. The Building comprised of Basement, Ground floor + 15 Upper floors but the Restaurant is running on Ground floor only was inspected by the officer concerned of this department on 27/08/2018 in the presence of Mr. Akshay and found that the said restaurant have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group- D Assembly Building with effect from ------2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on......at New Delhi by.

(Vipim Kental) Chief Fire Officer 9 c Phi 011-23412225

Copy to:-

1. The Addl. C. P. (Lic.), 1st Floor, Defence Colony, New Delhi-110024 {Ref: 2792/Addl.CP/Lic./EH/(DA-II)/New Delhi dated 19/07/2018}

2. Sh. Kiran Kalra S/o Sh. Vinod Kalra, R/o H. No. 9, Block-A, Priyadarshini Vihar, Laxmi Nagar, New Delhi-110092

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety \* measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first 18 The Rules of Delhi Fire Service schedule http://dclhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

7. This FSC will become null & void, if the FSC of main occupancy is not renewed under Rule 37 OR cancelled under Rule 40 of DFS Rules-2010.

1.	Name & address of the building: Eating House	e in the name & style of	of Tum Tum Asia (A	Unit of SKE							
	Corporate Se	rvices Pvt. Ltd.), 2, Gr	ound Floor, Eros Co	rporate Tower.							
	Corporate Services Pvt. Ltd.), 2, Ground Floor, Eros Corporate Tower, Nehru Place, New Delhi-110019.										
	ype of Occupancy :Group D Assembly Building [Building is B+G+ 15 upper floors]										
	ype of Case : New [Restaurant is running at Ground floor only]										
	in the vious NOC : NA										
6. I	Parte of inspection 27/09/2010										
	Date of inspection : 27/08/2018										
8. N	Name of Inspecting Officer : A.K. Malik Name and designation of officers										
I	From the building side : Mr. Akshay										
9. 3	Year of Construction : 2005										
	applicant's letter No. : Outdoor diary No. 10772 dated 26/07/2018										
S.	Minimum Standards on fire prevention	Remarks									
No.	and fire safety U/R 33	NBC/BBL Requirement	Provided at site	MP/NMD							
1.	Access to building [Eros Corporate Tower FSC No. of F6/DFS/MS/Mixed/SZ/2018/698 dated 13/04/2018										
	<ul> <li>Road width</li> </ul>	Restaurant within	As Above	MR							
	<ul> <li>Gate width</li> </ul>	Tower									
	<ul> <li>Width of internal road</li> </ul>										
2.	Je with angument of Parts IF (0) (000 N. Walling and no lower management)										
	a. Number of staircases										
	• Upper Floors	Restaurant within Tower	As Above	MR							
	Basements	Restaurant within Tower	As Above	NA							
	b. Width of staircases										
	• Upper Floor	Restaurant within Tower	As Above	MR							
	<ul><li>Basement</li><li>c. Protection of exits</li></ul>	Restaurant within Tower	As Above	NA							
3	201 1401 1000000000000000000000000000000	D - d : ili : T		,							
	<ul><li>Fire check door</li><li>Pressurization</li></ul>	Restaurant within Tower	As Above	NA							
	d. No. of continuous staircases to terrace	Restaurant within Tower	As Above	NA							
	e. Width of Corridor	Restaurant within Tower	As Above	NA							
	f. Door Size	Restaurant within Tower	As Above	NA							
		Restaurant within Tower	As Above	NA MR							
3.	Compartmentation 2m & 1.3m										
	Principal I										
	<ul> <li>Sealing of electrical shafts</li> </ul>		As Above	NA							
	• Fire Rating of shaft door	Restaurant within Tower	As Above	NA							
	Water Curtain	Restaurant within Tower	As Above	NA							
	• Fire Dampers	Restaurant within Tower	As Above	NA							
	A	Restaurant within Tower	As Above	NA							
4.	Smoke Management System [Provided & N	laintained by Tower man	nagement]								
	<ul> <li>Basements</li> </ul>	30 ACPH	As Above	NA							
	• Upper floors	12 ACPH	As Above	MR							
5.	Fire Extinguishers										
y	• Total numbers	2 No's	4 Nos	MR							
	• Types	ABC/W.CO <sub>2</sub> /CO <sub>2</sub>	2/2/-	MR							
-	IS marking	ISI marked	Yes	MR							
6.	First-Aid Hose Reels[Provided & Maintained										
	Total numbers on each floor	One (Near to Restaurant)	As Above	MR							
	• Length of hose reel hose	30 m	As Above	MR							
7.	Nozzle diameter  Automotic final later	5 mm	As Above	MR							
/ •	Automatic fire detection and alarming sys	tem[Provided & Mainta		gement]							
	• Type of detectors	NA	As Above	NA							
	Location of Main Panel     Location of Main Panel	NA	As Above	NA							
	Location of Repeater Panel     Alternation	NA	As Above	NA ·							
	Alternate source of power	NA NA	As Above	NA							
0	Hooters' Location	•	As Above	NA							
8.	MOEFA	Required	Provided	MR							

			Ground Floor			-	
	11	•	Sprinkler above false ceiling	NA	As Above	NA	
	11.	THICH III	in nyarants Provided & Maintain	NA NA	As Above	NA	
		•	Size of riser/down-comer	d by Tower manageme	ent]	11/1	
		•	Number of hydrants per floor	100mm	As Above	MR	
	12		JUSE BOY	One (near to Restaurant)	As Above	MR	
	12.	Yard H	ydrants[Provided & Maintained by otal number of hydrants	One (near to Restaurant)	As Above	MR	
				Y Tower management]			
	10	•	10se Roy	NA	NA	NA	
	13.	Pumping	g Arrangements [Provided & Mair	NA NA	NA	NA	
		• G	g Arrangements[Provided & Mair round Level	agement]	. 17.1		
		À	Discharge of main Pump				
			nead of Main nump	NA	NA	NA	
			Number of main number	NA	NA	NA	
			Jockey Pump out put	NA	NA	NA	
		A A	Jockey pump head	NA	NA	NA	
			Standby Pump out put	NA	NA	NA	
			Standby Pump Head	NA	NA	NA	
		<u> </u>	Auto Starting/Manual Stopping	NA	NA	NA	
			Pump House Access	NA	NA	NA	
				NA ID	NA		
		~	Discharge of pump Head of the pump	Provided & Main	I Tovided & Maintained by Toylor		
			Power Supply		As Above	MR-	
		_	Auto Starting of pump	40 M	As Above	MR	
1	4. C	- 1' YY	- carting of pump	Required	As Above		
1	7.	aptive W	ater Storage for firefighting[Prov	vided & Maint:	As Above	MR	
		<ul> <li>Und</li> </ul>	ater Storage for firefighting[Proverground tank capacity	raca & Maintained by	Tower management		
		<b>&gt;</b> 1	Draw-off connection	NA	As Above	NA	
		> 1	ire service inlet	NA	As Above	NA	
		> F	ccess to tank	NA	As Above	NA	
		• Over	head Tank capacity	NA	As Above	NA	
15		it Signag	e.	10,000 Lts	As Above		
16	. Pr	ovision of	Lifts [Provided & M.	Required	Provided	MR	
	Trialitatined by Mollman						
			Caramon of Litt Shaff	NA	NA		
		• Comr	urization of Lift lobby	NA	NA	NA	
		• Firem	nunication In lift Car	NA	NA NA	NA	
	1	• Lift S	an's Grounding Switch	NA	NA	NA	
17.	Sta	ndby now	ver supply	NA	NA	NA	
18.	Ref	uge Area	Provided & M.:	Required	Provided	NA	
		> Total	[Provided & Maintained by Tower	management	Trovided	MR	
		Locati	on	NA	NA		
19.	Fire	Control	Room[Provided 8 No :	NA	NA	NA	
		Detect	Room[Provided & Maintained by or System Panel	Tower management]	11/1	NA	
			witch Panel	NA	NA		
	•	PA Sve	stem Panel	NA	NA NA	NA	
	•	Batter	Dackup	NA	NA	NA	
	•	Buildin	g Floor Plans	NA	NA	NA	
20.	Spec	ial Fire P	rotection System for	NA	NA	NA	
	Prote	ection of	special Risks, if any:	NA	NA	NA	
		Not	e-1		TALL	NA	
		On th					

On the file of M/s Kiara (TFB Food Ventures), M-30, First Floor, M-Block Market, GK-II, New Delhi a note was moved by undersigned based on the discussion held with CFO (SZ) on 31/07/2018. In this regard the initial cases of Restaurants cleared in South Division, namely Laid Back Café & W D House of M-Block, GK-II, New Delhi were also discussed in r/o past practices approved on them. It was directed by CFO (SZ) that all past practices in r/o building parameters, fire protection arrangement & change of occupancy shall cease with immediate effect. The scope of guiding circular issued by Director vide office and

Fire Protection Measures: Onwards the required measures under Rule 33 of DFS Rules-2010 shall 1 determined in accordance with Year of construction of building, however if the occupancy of the premise is changed than the requirement shall be determined in accordance with the date of conversion.

- On 10/08/2018 the matter was discussed again in the chamber of CFO (SZ) in the presence of Dy. CFO (SZ). CFO (SZ) directed that office order no. F2/DFS/HQRS/14752 dated 09/08/2011 shall be enforced strictly in r/o Building Parameters as well as Fire Protection Measures. The provisions of BBL/NBC/UBBL pertaining to alteration of occupancy (Clause 2.3/BBL-1983 & Clause 1.4.118/UBBL-2016) will not be applicable in assumption that the upcoming occupancy was the initial occupancy of the subjected premise/building at the time of construction.
- All previous orders/direction issued in the name of past practice shall stand repealed for future cases.

In the absence of any written orders/directions/approval of verbal orders mentioned above this case is prepared on the basis of last verbal direction of competent authority (i.e. dated Note:-2

It is also to inform that this proposed Eating house is situated at the place earmarked for a Business occupancy i.e. office -3 in the building plan approved by this department on 08/02/2002 (C-7 of

The fire protection systems provided of the Eating House were randomly tested, checked and found functional at the time of inspection and it is recommended under Rule 35(3) to grant fire safety certificate and Form "H" is put up in shape of DFA for approval.

Accordingly competent authority may take decision under Rule 35(4).

Signature of Inspecting Officer Name: - A.K. Malik

Designation: - DO (SZ)

Dy. CFO (SZ)

CFO XX

It was decided that the building parameters shall be cheeked as per the relavent BBL as these cannit be changed but the exit wildth of restaurants Coming up later on will have exit reguirement of 2 mt as done in past cases. The matter has already been discussed with Go FDW.

A may kindly be endroad as bu discussion for uniformily m

CRIMINAL May hindly see